

Nicodemus National Historic Site

Nicodemus, Kansas

Historic Structures Report Update

May 2010



Prepared for:
National Park Service
Midwest Regional Office
Omaha, Nebraska

Prepared by:
Bahr Vermeer Haecker Architects
Wiss, Janney, Elstner Associates, Inc.

1 TABLE OF CONTENTS

2 Acknowledgementsiv

3 Executive Summaryv

4

5 **Project Scope and Methodology** 1

6

7 **Supplemental History and Work Performed** 4

8 A.M.E. Church 4

9 Old First Baptist Church 8

10 St. Francis Hotel/Fletcher-Switzer Residence 12

11 Nicodemus School District No. 1 Building 14

12 Township Hall 17

13

14 **Updated Condition Assessment** 20

15 A.M.E. Church 20

16 Old First Baptist Church 23

17 St. Francis Hotel/Fletcher-Switzer Residence 27

18 Nicodemus School District No. 1 Building 31

19 Township Hall 34

20

21 **Treatment and Use** 40

22 Preservation Objectives 40

23 Requirements for Treatment 41

24 Recommendations for Future Research 42

25 Updated Recommendations 44

26 A.M.E. Church 44

27 Old First Baptist Church 46

28 St. Francis Hotel/Fletcher-Switzer Residence 47

29 Nicodemus School District No. 1 Building 48

30 Township Hall 50

31 Opinion of Probable Costs 52

32

33 Bibliography 53

34

35 Appendix

36 Appendix B: As-built Drawings, Old First Baptist Church, 2004

1 ACKNOWLEDGEMENTS

2

3 National Park Service – Midwest Regional Office

4 Bill Harlow, Historical Architect, COTR

5 George Sievers, Contracting Officer

6 National Park Service – Nicodemus National Historic Site

7 Mark Weaver, Superintendent

8 Annette White

9 Bahr Vermeer Haecker Architects

10 Dan Worth, AIA, Historical Architect, Project Manager

11 Mike Gengler, AAIA, LEED AP, Graduate Architect

12

13 Wiss, Janney, Elstner Associates, Inc.

14 Deborah Slaton, Architectural Historian

15 Kenneth Itle, AIA, Project Architect

16

17

1 EXECUTIVE SUMMARY

2 At the request of the National Park Service
3 (NPS), Bahr Vermeer Haecker Architects
4 (BVH) and Wiss, Janney, Elstner Associates,
5 Inc. (WJE) have prepared this Addendum to the
6 October 25, 2002, *Historic Structures Report*
7 (HSR) for the Nicodemus National Historic Site.
8 This Addendum updates various sections of the
9 October 2002 HSR and addresses the five
10 structures within the National Historic Site: the
11 African Methodist Episcopal (A.M.E.) Church,
12 the Old First Baptist Church, the St. Francis
13 Hotel/Fletcher-Switzer House, the Nicodemus
14 District No. 1 School Building, and the
15 Nicodemus Township Hall.

16
17 The national significance of Nicodemus was
18 recognized by its designation as a National
19 Historic Landmark (NHL) on January 7, 1976.
20 In 1996, the five buildings that are the focus of
21 this HSR Addendum and the 2002 HSR were
22 established as a National Historic Site to be
23 administered by the National Park Service. In
24 2002 a *Cultural Landscape Report for*
25 *Nicodemus National Historic Site* (CLR) was
26 prepared that described the developmental
27 history of Nicodemus and also provided
28 essential information on the appropriate periods
29 of significance. The 2004 *General Management*
30 *Plan for Nicodemus National Historic Site*
31 (GMP) articulates a vision for the site that will
32 guide future management teams for the next ten
33 to fifteen years and suggests potential
34 partnerships, uses, and treatment strategies for
35 the five historic properties. Additionally, the
36 September 2009 *Long-Range Interpretive Plan*
37 *for Nicodemus National Historic Site* (LRIP)
38 was recently completed to provide a vision for
39 future interpretation of the historic resources of
40 the site.

41
42 The CLR identified an appropriate period of
43 national significance for the community to be
44 1877–1888, the “boom” years of Nicodemus.
45 Two of the five National Historic Site
46 structures—the A.M.E. Church and the St.
47 Francis Hotel/Fletcher-Switzer residence—
48 survive from this period. The Schoolhouse, First
49 Baptist Church, and Township Hall, which
50 postdate the period of national significance, are

51 significant for their association with important
52 themes in the history and development of
53 Nicodemus as well as of other African-
54 American communities during the nineteenth
55 and twentieth centuries: home, church, school,
56 business, traditions of mutual assistance, and
57 local government. The five buildings in this
58 study are also of interest as examples of
59 vernacular architecture using local building
60 materials. Although all of the buildings have
61 changed over time, and some of their materials
62 and features have deteriorated, each building
63 retains sufficient integrity to illustrate its historic
64 character. In addition to the period of national
65 significance discussed above, the CLR suggests
66 that the property be assessed for significance as
67 a Traditional Cultural Property, with a period of
68 significance extending from 1877 through the
69 present.

70
71 Since the 2002 HSR was prepared, the
72 conditions of the five building have changed—
73 some buildings are in dramatically better
74 condition due to the recent implementation of
75 repair work, while other buildings are in worse
76 condition due to ongoing unaddressed
77 deterioration. The A.M.E. Church is still in a
78 somewhat deteriorated condition but has
79 received recent structural and exterior
80 stabilization including masonry repairs by the
81 National Park Service. The Fletcher-Switzer
82 House and Old First Baptist Church have
83 received much-needed repairs and stabilization.
84 The Schoolhouse has received some
85 stabilization work and miscellaneous repairs by
86 the National Park Service but now requires
87 extensive exterior maintenance. The Township
88 Hall, which is the only one of the five buildings
89 still in use, has received both interior and
90 exterior repairs and is in fair condition.

91
92 This Historic Structures Report Update
93 identifies a recommended scope of repairs to
94 address existing deterioration and future
95 maintenance needs of the buildings based on
96 conditions observed during the current
97 (November 2009) survey. All of the updated
98 recommendations have been developed in
99 accordance with the Secretary of the Interior’s

1 Standards and in accordance with the general
2 treatment preservation, restoration, or
3 rehabilitation. **Preservation** is the act or process
4 of applying measures necessary to sustain the
5 existing form, integrity, and materials of an
6 historic property. **Rehabilitation** is the act or
7 process of making possible a compatible use for
8 a property through repair, alterations and
9 additions while preserving those portions or
10 features which convey its historical, cultural or
11 architectural values. **Restoration** is the act or
12 process of accurately depicting the form,
13 features and character of a property as it
14 appeared at a particular period of time by means
15 of the removal of features from other periods in
16 history and reconstruction of missing features
17 from the restoration period. Because some of
18 the reuse options are in the early stages of
19 planning and have not been fully defined, the

20 recommendations included in this report are
21 focused on the preliminary measures needed to
22 protect and stabilize the buildings through
23 ongoing maintenance and repair of historic
24 materials and features, rather than extensive
25 restoration and new construction. Specific
26 treatment recommendations have been updated
27 and are provided for structural stabilization,
28 weatherproofing, safety and protection of
29 building fabric, interior repairs, cyclical
30 inspection, and maintenance. As appropriate,
31 general recommendations for future
32 program/reuse alternatives are also provided,
33 including further research and investigation,
34 structural analysis, Americans with Disabilities
35 Act (ADA) compliance, code compliance,
36 termite inspection, and archaeological
37 investigation.

38

39

PROJECT SCOPE AND METHODOLOGY

1 PROJECT BACKGROUND

2 On November 12, 1996, Congress established
3 Nicodemus National Historic Site,
4 encompassing a portion of the town of
5 Nicodemus, Kansas, to be administered by the
6 National Park Service with the following
7 express purpose:

- 8 1. to preserve, protect, and interpret for the
9 benefit and enjoyment of present and future
10 generations, the remaining structures and
11 locations that represent the history
12 (including settlement and growth) of the
13 town of Nicodemus, Kansas; and
- 14 2. to interpret the historical role of the town of
15 Nicodemus in the Reconstruction period in
16 the context of the experience of westward
17 expansion in the United States.¹

18 The establishment of this new unit of the
19 National Park system built upon previous efforts
20 to recognize the national significance of the
21 town, including its designation as a National
22 Historic Landmark (NHL) on January 7, 1976,
23 an Historic American Buildings Survey
24 documentation project conducted in 1983 by
25 students and staff of the College of Architecture
26 and Design at Kansas State University, and a
27 special resources study prepared in 1993 by the
28 National Park Service. In 1996, the five
29 buildings discussed in this Historic Structures
30 Report Update were established as a National
31 Historic Site to be administered by the National
32 Park Service.

33 This Historic Structures Report Update has been
34 developed with consideration of the recent
35 General Management Plan as well as the 2002
36 HSR. The recommendations presented in this
37 report are based on the analysis of existing
38 conditions and integrity as well as the treatment
39 recommendations implemented to date. The
40 technical treatment recommendations in this
41 report are based on the treatment *preservation*,

¹ U.S. Congress Public Law 104-333, November
12, 1996, section 512.

42 as this treatment focuses on stabilizing and
43 protecting the properties as they currently exist.
44 However, this approach will need to be modified
45 to include aspects of the treatments *restoration*
46 and *rehabilitation* as GMP initiatives are
47 implemented, especially if recommendations for
48 ownership of the various properties are realized.
49 With these factors in mind, the following
50 treatment recommendations have been made.

51 STUDY BOUNDARIES AND 52 DESCRIPTION OF PROPERTIES 53 INVOLVED

54 Nicodemus National Historic Site is located in
55 Nicodemus Township, Graham County, Kansas.
56 The site is in the northwestern portion of the
57 state, approximately 40 miles north of Interstate
58 70 and the city of Hays. The National Historic
59 Site consists of five noncontiguous parcels of
60 land within the Nicodemus Township.

61 This Historic Structures Report Update
62 addresses the five properties that comprise the
63 Nicodemus National Historic Site:

- 64 ■ the former African Methodist
65 Episcopal (A.M.E.) Church – a 0.17
66 acre lot located at the northwest corner
67 of Third Street and Adams Avenue
- 68 ■ the Old First Baptist Church – a 0.18
69 acre property located at the northeast
70 corner of Fourth Street and
71 Washington Avenue
- 72 ■ the former St. Francis Hotel (also
73 known as the Fletcher-Switzer
74 Residence) – a 0.55 acre property
75 located at the southeast corner of Third
76 Street and Washington Avenue
- 77 ■ the former Nicodemus School District
78 No. 1 Building – a 2.33 acre site
79 located at the northwest corner of
80 Fourth Street and Madison Avenue
- 81 ■ Township Hall – an approximately
82 0.73 acre site at the northwest corner of

1 Second Street and Washington
2 Avenue.

3 PROJECT SCOPE AND METHODOLOGY

4 The purpose of the Historic Structures Report
5 Update is to provide a companion document to
6 the 2002 Nicodemus HSR, including any
7 updates to the findings of research,
8 investigation, analysis, and evaluation of the
9 historic structures. In addition, the preservation
10 objectives for the historic properties are updated
11 and as are treatment measures recommended for
12 implementing and accomplishing these
13 objectives. The Historic Structures Report
14 Update will provide the NPS with a basis for
15 decision-making for preservation of the
16 buildings. Together with the HSR, the report
17 update will also serve as a record document of
18 existing conditions and as a basis for planning
19 future preservation and maintenance.

20 Each HSR is tailored to the requirements of the
21 specific project. For this Historic Structures
22 Report Update a complete revision of the
23 original HSR was not necessary; however, many
24 key issues were addressed including updating the
25 condition assessment of the existing materials
26 and structural systems of the buildings, as well as
27 associated repair and preservation treatments.
28 This Historic Structures Report Update included
29 the following tasks:

- 30 1. Limited archival research
- 31 2. Documentation of the buildings with
32 digital photography
- 33 3. Visual inspection and condition
34 assessment of architectural features and
35 building materials
- 36 4. Visual inspection and condition
37 assessment of structural systems
- 38 5. Limited visual inspection and condition
39 assessment of mechanical, electrical, and
40 plumbing systems
- 41 6. Verification of previously noted
42 significant character-defining elements
43 and systems

44 7. Selection of a preferred treatment
45 approach and development of specific
46 treatment recommendations along with
47 detailed cost estimates

48 8. Preparation of the Historic Structures
49 Report Update.

50 No samples or building materials studies were
51 performed during this study, with the exception
52 of limited wood species identification as
53 discussed below. Also no destructive testing or
54 investigation was performed. Further
55 investigation that requires extensive removals,
56 dismantlement, excavation, or more extensive
57 testing is addressed in the recommendations
58 provided in this report.

59 The following tasks were performed as part of
60 this study:

61 **Research and Document Review.**

62 Limited research was performed to search
63 out additional documentation of the history
64 and construction of the buildings,
65 particularly as related to work performed
66 since completion of the 2002 HSR study.
67 Documents were assembled on recent
68 stabilization efforts on several of the
69 buildings as well as PMIS statements for
70 planned stabilization and preservation
71 efforts. This research builds upon the
72 significant historical and archival research
73 performed for the 2002 HSR and the
74 Cultural Landscape Report.

1 **Measured Drawings.** For purposes of this
2 update, measured drawings prepared to document
3 the existing properties in the 2002 HSR, and
4 2004 stabilization contract documents prepared
5 for the stabilization of the First Baptist Church,
6 were used as baseline documents to record
7 existing conditions. Drawings were also found
8 for the north wall stabilization of the Nicodemus
9 School District No. 1 Building, prepared by the
10 NPS Historic Preservation Training Center.
11 These drawings can be used in the future as
12 baselines to prepare construction drawings for the
13 recommended treatments. For this report,
14 reduced size copies of the First Baptist Church
15 and School stabilization documents are provided
16 in Appendix B.

17 **Condition Assessment and**
18 **Documentation.** Members of the project
19 team performed a two day site visit to
20 update building documentation and
21 perform a visual condition assessment.
22 The site visit for condition assessment was
23 performed November 9–10, 2009, by
24 project team members from BVH and
25 WJE. During this site visit, visual
26 observation was made of all five buildings
27 and existing conditions were documented
28 with field notes and photographs. The
29 visual inspection addressed the exterior
30 envelope of each building as well as
31 interior spaces and features.

32 **Development of History and Evaluation of**
33 **Significance.** No additional research was
34 performed on the developmental history nor was
35 any additional evaluation performed of the
36 historical significance. The 2002 HSR
37 evaluation provided the basis for the updated
38 recommended treatment alternatives.

39 **Development of Preservation Objectives,**
40 **Requirements for Treatment, and Treatment**
41 **Recommendations.** In cooperation with the
42 National Park Service, and in coordination with
43 the GMP, 2002 HSR, and CLR, the preservation
44 objectives and requirements for treatment of the
45 five subject buildings were updated. Based on
46 the requirements for treatment, the
47 recommendations for treatment were revised for
48 each building.

49 These treatment approaches relate to the long
50 term use of the buildings as described under the
51 GMP. Before the long term uses can be
52 determined, however, issues of building
53 ownership and management must be resolved.
54 In the interim, the treatment *preservation* as
55 described in the 2002 HSR remains appropriate
56 to protect the historic resources in the short
57 term. Therefore, the technical treatment
58 recommendations presented herein are focused
59 on immediate maintenance and stabilization
60 measures to protect the buildings. Additional
61 investigation and review of existing conditions
62 of the subject buildings will be needed once the
63 decision is made to implement long term uses
64 consistent with the GMP. Once the long term
65 uses of the individual buildings are identified,
66 treatment efforts may change from basic
67 maintenance and stabilization to restoration or
68 rehabilitation treatment approaches appropriate
69 to the end use.

70 **Preparation of Historic Structures Report**
71 **Update.** The information gathered through
72 research, condition survey, and review and
73 discussion was compiled into this Historic
74 Structures Report Update. This report has been
75 prepared following the organizational guidelines
76 of the National Park Service, and addresses all
77 five buildings included in the study.

78

SUPPLEMENTAL HISTORY AND WORK PERFORMED

1 A.M.E. CHURCH

2 As discussed in 2002 *Historic Structures*
3 *Report*, significant stabilization work was
4 implemented at the A.M.E. Church beginning in
5 1996, and continuing in 2000 and 2001. After
6 completion of the HSR, additional stabilization
7 work was performed beginning in 2003–2004.
8 Work has continued in subsequent years.

9 In late 2003, the front doors at the east elevation
10 were removed and shipped to the NPS Historic
11 Preservation Training Center in Frederick,
12 Maryland, for restoration. The work included
13 wood repairs and installation of new glazing at
14 the upper panels. The doors were recoated with
15 white paint. The existing hinges were retained
16 and a new doorknob/lockset was installed. New
17 threshold sweep weatherstripping was added at
18 the sill of each door, and the operation of the
19 doors was adjusted for a secure fit. The wood
20 door frame was also repainted as part of this
21 work. The doors were reinstalled in spring 2004
22 (Figure 1).²

23 New limestone for use in repairing the A.M.E.
24 church was purchased in 2003 and delivered to
25 the site on September 26, 2003.³ Subsequently,
26 several stone units near grade on the south
27 elevation were replaced (Figure 5). Some stone
28 units were installed in 2009, however the extent
29 of that work is not documented. The original
30 stone units were observed to be severely
31 deteriorated when inspected during the 2001
32 HSR field work. Additional new limestone
33 material is stored on wooden pallets to the north
34 of the building. The new stone material is not
35 covered or secured.

36 In 2004, the exterior stucco was removed from
37 all exterior walls of the main sanctuary; the

38 stucco remains in place on the exterior walls of
39 the vestibule (Figure 3).

40 Following the stucco removal, the masonry
41 joints of the west elevation were repointed.
42 Based on visual observations, a relatively hard
43 portland cement based mortar was apparently
44 used. The mortar was installed deeply into the
45 joints and was raked back up to 1/2 inch from
46 the stone surface. The masonry joints of the east
47 and south elevations were also repointed after
48 the stucco was removed. A different mortar mix
49 was used than on the west elevation, with the
50 mortar joints filled to the masonry surface and
51 struck concave (Figure 4).⁴ The repointing work
52 was implemented by NPS staff.

53 In September to December 2005, four new
54 wood-framed double hung windows were
55 fabricated and installed by a contractor engaged
56 by NPS to replace the existing ventilated board-
57 ups and windows at the south elevation
58 (Figure 2). The original windows were
59 considered to be deteriorated to be repaired. It is
60 not known if the original window sash were
61 salvaged for storage. The new window units are
62 wood, one-over-one double hung, single glazed
63 units, primed with two coats of Porter Paints
64 #513 (an oil-modified acrylic bonding primer)
65 and painted with one coat of Porter Paints #631
66 (100 percent acrylic gloss paint), color Brilliant
67 White. The design of the new units matched the
68 profiles and construction of the original
69 windows, based on surviving fragments of the
70 original windows.⁵

71 Exterior wood elements of the building were
72 painted in summer 2007.⁶ Although not
73 documented, this work may also have included
74 painting the exterior stucco at the vestibule. NPS
75 supplied the materials, and the Colorado Range
76 Riders Youth Corps performed the work.

2. PMIS 85774A, Completion Report dated December 22, 2003.

3. Ibid. The new stone was supplied by Bayer Stone, Inc., St. Mary's, Kansas, and is identified as Manhattan White (Cottonwood), Machine-Split Veneer Stone, from quarries in Chase or Pottawatomie Counties, Kansas.

4. PMIS 85774B, Completion Report dated March 10, 2005.

5. PMIS 85774C, Completion Report dated January 13, 2006.

6. PMIS 85774D, Completion Report dated November 20, 2007.

1 At the interior of the A.M.E. Church few
2 changes have occurred since the *2002 Historic*
3 *Structures Report*. At the east anteroom, little if
4 any of the interior finishes have been modified
5 since 2002. The floor of the anteroom is
6 finished with 3-1/4 inch wide tongue and groove
7 flooring with a blue-gray painted finish. The
8 ceiling is wood tongue and groove boards,
9 painted white. The boards are approximately
10 3/4 inch thick by 5-1/2 inches wide. The
11 exterior entry doors are wood stile and rail doors
12 with three inset panels, unpainted. The glass
13 view panel in the upper part of the door is
14 covered with Masonite. The doors into the
15 sanctuary are white painted wood stile and rail
16 with inset panels and spring hinges. Additional
17 equipment and tools stored in the anteroom are
18 presumably being used for the exterior repairs
19 and modifications (Figures 6 and 7).

20
21 The sanctuary is also much as it was in 2002.
22 Most of the 1 x 6 flooring boards and tongue
23 and groove ceiling bead boards that were
24 removed for the north wall stabilization still lie
25 within the space in piles. These piles, once
26 neatly stacked and organized, have been moved
27 and pieces strewn about, most likely the result
28 of workers needing to have access to portions of
29 the exterior walls for recent work. The north
30 wall is still a temporary plywood and stud wall
31 constructed as part of the previous stabilization
32 work. The south, east, and west walls are
33 plaster applied directly to stone and are painted
34 pink (Figures 8, 9 and 10). The chancel area is
35 defined by a raised wood platform with three
36 tiers at the west end of the sanctuary. This
37 platform includes wood railings, balusters, a
38 communion rail, and several sets of steps.
39 Portions of the pulpit rail remain in place while
40 other fragments are scattered around the space.
41 No other improvements or alterations were
42 observed.

43



1
2 *Figure 1. The restored doors at the east elevation of the*
3 *A.M.E. Church. Compare to Photo A-19 in the 2002*
4 *HSR. Photo by BVH, 2009.*



5
6 *Figure 2. New windows at the south elevation. Photo by*
7 *WJE, 2009.*



8
9 *Figure 3. Overview from the southeast showing the*
10 *removal of stucco from the main sanctuary and the*
11 *recoating of the stucco at the vestibule. Photo by WJE,*
12 *2009.*



13
14 *Figure 4. Detail at the southwest corner of the church,*
15 *showing two types of repointing mortar, with joints*
16 *struck back on the west elevation (left) or tooled to a*
17 *concave profile on the south elevation (right). Photo by*
18 *WJE, 2009.*



19
20 *Figure 5. New stone units were installed near grade on*
21 *the south elevation. Compare to Photo A-20 in the 2002*
22 *HSR. Photo by WJE, 2009.*



1
2 *Figure 6. View of south east corner of Anteroom. Note*
3 *tools and equipment stored. Photo by BVH, 2009.*



4
5 *Figure 7. View from Anteroom into Sanctuary. Photo*
6 *by BVH, 2009.*



7
8 *Figure 8. View looking towards north east corner of*
9 *Sanctuary. Note that all ceiling boards have been*
10 *removed since 2002 HSR. Photo by BVH, 2009.*



11
12 *Figure 9. View looking towards Chancel in Sanctuary.*
13 *Photo by BVH, 2009.*



14
15 *Figure 10. Detail of items removed and piled near*
16 *Chancel. Note that materials include door, frame, wall*
17 *and floor boards. Photo by BVH, 2009.*

18

1 OLD FIRST BAPTIST CHURCH

2 After completion of the HSR in 2002, a major
3 structural and building envelope stabilization
4 project was implemented at the Old First Baptist
5 Church. The project included installation of
6 exterior structural shoring at the east wall;
7 interior shoring to support the roof framing near
8 the east wall; reinforcing of the roof structure;
9 re-roofing of the building with new wood
10 shingles; reconstruction of the vestibule
11 mansard roof; reconstruction of the northwest
12 addition roof; dismantling of the brick chimney;
13 removal of finishes at interior partition walls
14 and localized portions of the ceiling; localized
15 stucco and masonry repairs; and installation of
16 window board-ups with ventilation. This work
17 was implemented from December 2005 to
18 September 2006.⁷ The stabilization project was
19 designed by the HSR project team and is
20 documented in the as-built drawings included in
21 Appendix B.

22 While much of the interior fabric observed and
23 documented in the 2002 HSR remains, the
24 stabilization project caused several changes and
25 modifications to some of the interior finishes
26 and systems. Prior to the stabilization, a clean-
27 up of the interior was performed, including
28 mitigation of vermin and mold growth.⁸ As part
29 of the stabilization, carpet and vinyl sheet floor
30 coverings were removed and a protective layer
31 of 4 foot by 8 foot sheets of oriented strand
32 board (OSB) was laid over the majority of the
33 floor area. Since much of the stabilization work
34 was focused on the east wall, tower, and west
35 interior/chimney bearing walls, these areas of
36 the interior were the most affected by the work.
37 At the east wall ceiling, a narrow section of the
38 stamped tin ceiling running north to south over
39 the entire length of the wall was been removed
40 (Figures 22 and 23). Correspondingly, a narrow
41 section of flooring along the east wall was
42 removed to allow the insertion of a wood
43 structural shoring and bracing and small
44 concrete foundation piers. All of the flooring
45 boards and ceiling panels were carefully
46 disassembled, stacked, and stored within the

47 interior of the sanctuary (Figures 18 and 19). At
48 the west wall dividing the kitchen from the
49 sanctuary, most of the existing wall over the
50 kitchen pass-through window was dismantled,
51 including the brick chimney and plaster finishes.
52 Additional structural wood framing and shoring
53 was installed, leaving the pass-through window
54 and door opening intact (Figure 14). The
55 structural improvements and the need to insert
56 additional beams and framing also necessitated
57 the removal of the tin ceiling panels at the
58 kitchen. The appliances in the kitchen have been
59 cleaned, disconnected, and are stored within the
60 room. The propane gas space heater originally
61 located in the sanctuary has also been
62 disconnected and is stored within the interior of
63 the church (Figure 21 and 24). The study and the
64 two toilets remain in much the same condition
65 and configuration as observed in 2002. The
66 remainder of the interior finishes including
67 plaster walls, wood wainscoting, doors and
68 frames are unchanged since 2002.

69

7. PMIS 91926.

8. PMIS 118896, Completion Report dated December 1, 2006.



1
2 *Figure 11. Overview from the southeast showing east*
3 *wall shoring. Photo by BVH, 2009.*



10
11 *Figure 14. Interior shoring and removal of finishes at*
12 *the interior partition wall between the sanctuary and*
13 *kitchen. Photo by BVH, 2009.*



4
5 *Figure 12. Wood shoring at the east wall. Photo by*
6 *WJE, 2009.*



14
15 *Figure 15. Reconstructed vestibule mansard roof.*
16 *Photo by WJE, 2009.*



7
8 *Figure 13.. Interior shoring to support the roof*
9 *structure near the east wall. Photo by BVH, 2009.*



17
18 *Figure 16. Typical window board-up. Photo by BVH,*
19 *2009.*



1
2 *Figure 17.. Reconstructed northwest addition roof.*
3 *Photo by WJE, 2009.*



13
15 *Figure 20. Detail view of stored furniture at center of*
16 *sanctuary. Photo by BVH, 2009.*



4
5 *Figure 18.. View of chancel. Note new shoring at east*
6 *wall beyond. Photo by BVH, 2009.*



20
21 *Figure 21. Detail view in kitchen. Note that appliances*
22 *have been disconnected from power/propane, cleaned,*
23 *and stored. Photo by BVH, 2009.*



7
8 *Figure 19. Detail view of stored flooring boards in the*
9 *chancel. Also note protective layer of OSB applied*
10 *over historic flooring remaining in place. Photo by*
11 *BVH, 2009.*



24
25 *Figure 22. Detail view of ceiling/wall junction at east*
26 *wall showing strip of ornate tin ceiling material*
27 *removed for shoring installation. Photo by BVH, 2009.*



1
 2 *Figure 23. Detail at southeast corner of sanctuary*
 3 *showing portion of flooring removed to allow*
 4 *repointing and repairs to stone wall/foundation. Photo*
 5 *by BVH, 2009.*



6
 7 *Figure 24. Detail at study noting stored gas space*
 8 *heater and materials removed from kitchen area. Photo*
 9 *by BVH, 2009.*



10
 11 *Figure 25. Interior view of typical window that has had*
 12 *a protective plywood cover installed. Photo by BVH,*
 13 *2009.*

14

1 ST. FRANCIS HOTEL/FLETCHER-
2 SWITZER RESIDENCE

3 Exterior stabilization work was performed in
4 November 2007 to March 2008 to secure the
5 exterior envelope of the building and address
6 some of the more significant and large-scale
7 deficiencies identified in the 2002 HSR.

8 Localized stucco repairs were implemented to
9 address large holes and damage, and the exterior
10 stucco and siding were repainted. Damaged
11 areas of wood trim were replaced or repaired by
12 adding new wood pieces over gaps or holes.
13 Window openings on the west, south, and east
14 elevations were boarded up with painted
15 plywood. New membrane flashing was installed
16 to cover the gap between upper level walls and
17 the shed roofs along the north and south sides of
18 the building.⁹

19 Little if any interior stabilization work or
20 changes has taken place since the 2002 HSR.
21 The interior finishes and systems remain much
22 as they were observed and documented in 2002.
23 At the first floor, the residence is filled with a
24 tremendous amount of furnishings, appliances,
25 and miscellaneous household items. Some
26 flammable and dangerous items are stored
27 within the building, including a gas-filled
28 motorcycle at the rear south porch. It appears
29 that many of the items at the first floor living
30 room and bedroom may have been moved from
31 the second floor east and south bedrooms, as
32 they are almost mostly empty. The north
33 bedroom remains completely filled with
34 household items and furniture (Figures 26
35 through 30).

36



37
38 *Figure 26. View of the north elevation of the St. Francis*
39 *Hotel/Fletcher-Switzer Residence. Photo by WJE, 2009.*



40
41 *Figure 27. View of the east elevation showing stucco*
42 *repairs and repainting of exterior stucco and wood*
43 *trim. Photo by WJE, 2009.*



44
45 *Figure 28. View of the southwest corner of the building,*
46 *showing flashing repair between the second floor wall*
47 *and shed roof. Compare to Photo F-18 in the 2002*
48 *HSR. Photo by WJE, 2009.*

9. PMIS 103880, Completion Report dated April 11, 2008.



1
2 *Figure 29. View stored materials at rear south porch.*
3 *Photo by BVH, 2009.*



4
5 *Figure 30. The second floor bedroom has been cleaned*
6 *out since 2002 and contains few items. The south*
7 *window has been covered but large gaps around the*
8 *frame allow moisture to penetrate into the building and*
9 *wall system. Photo by BVH, 2009.*

10
11

1 NICODEMUS SCHOOL DISTRICT NO. 1
2 BUILDING

3 Relatively little work has been performed at the
4 school building since the major repair work of
5 summer 1998, as documented in the HSR.

6 Between August and October 2005, repairs were
7 performed at the north wall to address
8 displacement that had occurred due to previous
9 water leakage (Figure 31). Interior wood shoring
10 was constructed to support the roof structure.
11 Although the drawings for this work indicated
12 that concrete piers were to be built in the crawl
13 space to support the shoring wall, as
14 implemented the shoring wall bears on the floor
15 framing of the schoolhouse. Cellulose insulation
16 was removed from the wall cavity. A new 2x4
17 sill plate, new 2x4 wall framing, new plywood
18 sheathing, and new painted wood exterior siding
19 was installed at the north wall below the
20 window sill. The original siding was found to be
21 too deteriorated for reuse.¹⁰


22 It appears that some of the intended work was
23 not completed. The interior wood-framed
24 shoring wall remains in place (Figure 32). Some
25 components of the original exterior wood
26 window trim had been removed and not
27 replaced (Figure 33). Matching pieces of wood
28 trim were observed, in a partially repaired
29 condition, stored in the interior of the building.

30 Other than the north wall stabilization, the
31 interior finishes and fabric remain much as they
32 were observed during the inspection conducted
33 for the 2002 HSR. Some furnishings and
34 miscellaneous items have been removed, most
35 likely to accommodate the stabilization work.
36 Some furnishings do still remain, however, in
37 the main classroom space and include school
38 desks and some church pews. All other rooms
39 including the coat room, kitchen, and entry hall
40 are empty (Figures 34 through 38).

41



42
43 *Figure 31. Detail of new stud framing and exterior*
44 *sheathing below the windows of the north wall. Photo*
45 *by WJE, 2009.*



46
47 *Figure 32. Interior shoring remains in place at the*
48 *north wall. Photo by WJE, 2009.*

10. Project Completion Report, Nicodemus NHS,
School House North Wall Stabiliation, FY05, 6345-
C205-CCS, for Project No. NICO-05-04; PMIS
92568.



1
2 *Figure 33. Some exterior wood window trim was*
3 *removed and not replaced. Note temporary plastic*
4 *sheeting at left window jamb. Photo by WJE, 2009.*



5
6 *Figure 34. View looking southeast in classroom.*
7 *Photo by BVH, 2009.*



8
9 *Figure 35. View looking southwest in classroom.*
10 *Photo by BVH, 2009.*



11
12 *Figure 36. View of entry hall. Photo by BVH, 2009.*



1
2 *Figure 37. View of coat room. Photo by BVH, 2009.*



3
4 *Figure 38. View of kitchen. Photo by BVH, 2009.*

5

1 TOWNSHIP HALL

2 The Township Hall remains in use as the
3 temporary NPS visitor center for the site. At the
4 time of this inspection, several modular office
5 units had been set up in the main auditorium
6 space to accommodate park staff. Renovations
7 are reportedly also underway at a nearby
8 apartment complex for space to serve as park
9 offices. Once these renovations are completed,
10 several of the offices currently housed at the
11 Township Hall will reportedly be moved to the
12 apartment complex, opening up the auditorium
13 for public and interpretive usage.

14
15 A variety of maintenance-type work has been
16 initiated by NPS at the Township Hall since the
17 2002 HSR with the work performed by
18 contractors engaged by NPS.

19 A new asphalt shingle roof was installed. As
20 part of the roofing project, the wood exterior
21 false rafters and eaves were painted, and the
22 brick chimney was repointed (Figure 38).

23 The exterior steel window sash and adjacent
24 steel lintels were repainted. The concrete
25 window sills were also painted (Figure 39).

26 One of the two air conditioning condensers
27 serving the building has been replaced
28 (Figure 40). Also, the 8-foot diameter cesspool
29 installed in 1939 located 30 feet north of the
30 north wall of the Township Hall was replaced
31 with a new septic tank and leach field in August
32 2005.¹¹

33 At the interior much of the fabric and finishes
34 remain as observed in 2002, but recent
35 maintenance work has included a variety of
36 improvements. At the men's and women's
37 restrooms, new toilet fixtures have been
38 installed and plumbing lines improved/replaced.
39 The wall and floors in the restrooms have been
40 painted and new light fixtures installed.
41 Instantaneous hot water heaters have also been
42 installed in the basement and hot water piped to
43 the lavatories in the restrooms. The walls and

44 floors of the side rooms and stairs outside the
45 restrooms have been painted.



46
47 *Figure 38. View from the southeast of the Township*
48 *Hall, showing new asphalt shingle roofing, painted*
49 *wood trim, and repointed brick masonry chimney.*
50 *Photo by BVH, 2009.*



51
52 *Figure 39. Newly repainted steel window and concrete*
53 *sill. Photo by WJE, 2009.*

11. PMIS 117969, Completion Report dated September 30, 2005.



1
2 *Figure 40. The new York air conditioning condenser is*
3 *at right. Photo by WJE, 2009.*



4
5 *Figure 41. View looking south west towards NPS*
6 *sales/bookstore area. Photo by BVH, 2009.*



7
8 *Figure 42. View looking along the northwest wall where*
9 *NSP staff offices were installed. Photo by BVH, 2009.*



10
11 *Figure 43. Detail view in basement. Note installation of*
12 *instantaneous water heater and new plumbing lines.*
13 *Photo by BVH, 2009.*



14
15 *Figure 44. Detail view in men's restroom. Note new*
16 *toilet fixtures, plumbing and new paint finishes. Photo*
17 *by BVH, 2009.*



1

- 2 *Figure 45. Detail view in west side room/stair. Note*
- 3 *new exit door, panic hardware, exit lighting, handrail*
- 4 *improvements, and paint finishes. Photo by BVH, 2009.*

1 UPDATED CONDITION ASSESSMENT

A.M.E. CHURCH

Exterior

The following conditions were observed during site work performed for the HSR Update:

- The recently restored front doors are in good condition, and the new windows in the south elevation are in good condition.
- The main roof structure appears to be stable. The asphalt shingle roofing is watertight. The interior roof shoring is in good condition and appears to provide appropriate support.
- Exterior wood trim has an intact, recently applied paint coating.
- The corrugated sheet metal roof of the vestibule is generally intact and unchanged since the 2002 HSR.
- The temporary north wall appears to be generally intact. There are some gaps and openings that can allow vermin to enter the building.
- As noted in the 2002 HSR, there is an open joint at the north and south sides of the vestibule where the stuccoed vestibule walls meet the stone walls of the sanctuary (Figure 46).
- Due to removal of stucco from the main portion of the church, a much greater extent of stone masonry is now exposed. Individual cracked or spalled stone units are present throughout the facades. It is not known if this distress was pre-existing and concealed by the prior stucco cladding, or if the observed conditions are newly-developed distress caused by the stucco removal or weathering since the stucco removal. Most stone units have distinctive chisel marks, created to provide a key for the previous adhered stucco coating.
- Some of the recently installed pointing mortar at the west elevation has cracked and separated from the stone, and there is some cracking of stone that apparently post-dates the repointing work (Figure 47). At the east and south elevations where a different mortar mix was used, the joints are intact and in good condition. It appears that an inappropriately hard mortar was used at the west elevation, while at the south and east elevations the mortar mix appears to be compatible with the stone substrate.
- The new replacement stone units on the south elevation near grade are intact, although these units are not a good aesthetic match to the adjacent original stone (refer to Figure 5 above). The new stone units may better blend visually once they have weathered.
- The building roof does not have gutters. On the south side, grade slopes away from the building and the soil appears to drain well. Sunlight also helps to dry this side of the building. On the north side, grade slopes toward the building. The turf grass near the building wall was observed to be saturated with water (Figure 48).
- On the south side, the window openings are defined by masonry arches infilled with semicircular stone lunettes above the rectangular window opening. One of the lunette stones has cracked and requires repair (Figure 49). It is possible that this stone was cracked previously, but that the cracking was concealed by the prior stucco cladding.
- Cracking of the stucco on the east elevation of the vestibule is unchanged since the 2002 HSR. The stucco appears to have been recoated since the 2002 HSR.

Interior

Entry Vestibule

- The flooring exhibits some cupping, warping, and water damage at the southwest corner, and is in fair condition overall.
- The vestibule walls have a plaster finish over limestone masonry. The plaster finish is in poor condition and has fallen off the limestone substrate in many places, leaving the limestone exposed. A large crack has developed in the plaster near the entry doors to the sanctuary indicative of structural movement (refer to Figure 7).
- The ceiling is composed of bead board tongue and groove planks attached directly to the underside of the bottom chord of the roof truss, and is in fair condition. An access hatch has been cut into the bead board ceiling and covered with a piece of plywood (Figure 50). The paint finish on the bead board ceiling is not excessively built up and the beading detail is still evident. The paint, however, is in poor condition with localized failure and general chalking.
- The doors to the sanctuary are painted double swinging wood stile doors, each with a single panel. The doors and double action hardware are in fair condition.

Sanctuary

- The vinyl floor covering has been mostly removed with small portions of the covering still in place.
- The subfloor was partially disassembled at the side walls for the previous stabilization project. Where the subfloor planking remains in place it is in fair condition, with cupped, warped, checked, and loose boards.
- The plaster on the walls exhibits severe cracking and delamination of plaster due to water damage. The plaster in the sanctuary is generally in poor condition. The north wall is in the same condition as in 2002,

with exposed stud framing and plywood sheathing installed during the NPS structural stabilization efforts in 2000.

- The bead board tongue and groove ceiling has been removed in its entirety and has been stacked haphazardly in the middle of the sanctuary.

Chancel

- The floor of the chancel is warped and cupped, and is in fair condition overall.
- Towards the rear of the chancel, the wood flooring of the raised chancel has been partially removed to expose the floor joists below.
- Several pieces of wood trim are missing from the chancel railing, including caps at the posts and stiles of the communion rail. The rail is in fair condition.
- Debris and detritus litter the chancel and sanctuary.



Figure 46. View inside the vestibule. There is a continuous open joint (note visible daylight) between the main sanctuary wall and the vestibule walls at the north and south sides of the vestibule. Photo by WJE, 2009.



Figure 49. Cracked lunette stone over one window on the south elevation. Photo by WJE, 2009.



Figure 47. Cracking of recently repointed mortar joints and stone at the west elevation. Photo by WJE, 2009.



Figure 50. Access to attic space above cut into bead board ceiling of vestibule. Photo by BVH, 2009.



Figure 48. Saturated turf grass along the north elevation. Photo by WJE, 2009.

OLD FIRST BAPTIST CHURCH

Exterior

The following conditions were observed during site work performed for the HSR Update:

- The interior and exterior of the building remain in stable condition following stabilization work implemented in 2005–2006. The new roofing systems are intact and appear watertight. The window and door board-ups are intact.
- Galvanized metal roof flashings have begun to develop surface corrosion, and some cedar shingles are cupped or split (Figure 51). This weathering of the roof materials does not appear to have affected the water tightness of the roof system.
- Newly applied stucco is intact, although other areas not included in the recent work have localized cracking and delamination. The areas of new stucco installed in 2006, as well as older pre-2001 stucco repair areas, are not coated (Figure 52).
- Although treated lumber was used for the exterior east wall shoring, the wood elements are starting to weather (Figure 53).
- The paint coating on the wood trim enclosures has begun to weather (Figure 54).
- The concrete masonry walls of the northwest addition have weathered noticeably since the 2002 HSR. Few stucco remnants now remain on this structure, except directly below the roof overhang. Many mortar joints are heavily eroded or completely open (Figure 55). Efflorescence is present at some areas, indicating water penetration of the masonry construction.

Interior

Foyer

- The wood flooring of the foyer is warped and cupped, and is in fair condition overall.

- The plaster walls have water damage and are cracked. The plaster is in fair condition. The wood wainscot is deteriorated with severe water damage and is in poor condition.
- Some plaster has been removed to allow for the new tower framing, exposing the lath beneath (Figure 56).
- The ceiling of the foyer has been removed to accommodate new joist framing for the tower above (Figure 56).
- The exterior doors and frames have been removed and replaced with a temporary plywood door and side panel, painted on the exterior only. The transom has also been in-filled with plywood (Figure 57).

Sanctuary

- Portions of the wood flooring have been removed to accommodate stabilization efforts and a protective layer of oriented strand board (OSB) panels has been laid over much of the floor.
- The wood plank flooring is cupped, warped, and split due to water infiltration at the southwest corner but generally is in good condition overall.
- The carpet at the stage/chancel floor has been removed and OSB panels laid down over the floor planking.
- The plaster walls are severely cracked and plaster has been removed or fallen off in many locations, exposing the wood lath beneath. The plaster is generally in poor condition. The painted bead panel wainscot below the plaster is in good condition.
- The east wall has been stabilized and stud framing with bracing has been installed to support the roof framing above.
- The plaster and lath of the west wall separating the sanctuary from the kitchen have been removed and the header over the server window temporarily stabilized with crib framing (Figure 58).

- The pressed metal ceiling is generally in fair to good condition. Portions of the metal ceiling have been removed to accommodate stabilization efforts.
- The kitchen doors and frame, as well as the serving counter door, have been removed. The doors are stored in the kitchen space
- The railing of the chancery is missing.

Kitchen

- The carpet in the kitchen has been removed with wood floors remaining. The wood floors of the kitchen are in good condition.
- The plaster walls of the kitchen are cracked in localized areas but generally are in good condition. The painted bead panel wainscot and chair rail trim below the plaster are in good condition.
- The pressed metal ceiling in the kitchen is relatively intact and in good condition. The chimney flue has been removed and the opening in-filled (Figure 58).

Study

- The floor of the study is exposed plywood sheathing and exhibits water damage in areas.
- The walls of the study are exposed painted concrete masonry units. The walls show indications of moisture infiltration with efflorescence of the CMU and deterioration of the paint surface. The masonry walls are generally in good condition, while the paint finish is in poor condition.
- The ceiling of the study is composed of gypsum wall board panels affixed to the underside of the bottom chord of the roof joist. Much of the ceiling plane has been removed and remaining portions are severely water damaged (Figure 59). Portions of the ceiling that remain are severely deteriorated, with indications of mold growth (Figure 60).

Toilet Room A

- The floor exhibits severe water damage. The plaster walls are sound and uncracked. The wood paneled walls are severely water damaged. The ceiling has severe water damage and mildew.

Toilet Room B

- There is a hole in the floor caused by water damage and rotted wood. There are cracks in the plaster of the east wall.



Figure 51. Minor cupping of the cedar shingles and corrosion of the sheet metal flashing have occurred as the new roof system has weathered. Photo by WJE, 2009.



Figure 52. The newly installed stucco at the north elevation and elsewhere is uncoated. Photo by BVH, 2009.



Figure 53. The treated wood shoring at the east wall has begun to weather. Photo by WJE, 2009.



Figure 56. Wall plaster and ceiling plaster removed in foyer for tower stabilization effort. Photo by BVH, 2009.



Figure 54. The painted wood trim board-ups have begun to weather. Photo by WJE, 2009.



Figure 55. The concrete masonry walls of the northwest addition are significantly deteriorated, with eroded and open mortar joints and efflorescence. Photo by WJE, 2009.



Figure 57. Entry doors removed and replaced with temporary plywood door and side panel. Photo by WJE, 2009.



Figure 58. Chimney flue removed. Note metal strap that suspended flue masonry. Photo by BVH, 2009.



Figure 60. Ceiling in study exhibiting severe deterioration and apparent biological growth. Photo by BVH, 2009.



Figure 59. Ceiling in study that has either fallen down or been removed since 2002. Photo by BVH, 2009.

ST. FRANCIS HOTEL/FLETCHER-SWITZER RESIDENCE

Exterior

The following conditions were observed during site work performed for the HSR Update:

- Although recent stucco repairs have addressed the large holes in the walls noted in the 2002 HSR, many smaller gaps in the exterior walls remain, some of which may permit water leakage. Recent painting work has stabilized the exterior wood trim, although split, displaced, and broken pieces remain at all elevations. Many areas of wood exterior trim or exposed wood structure (such as the exposed rafter ends) are unpainted (Figures 61 and 62).
- The board-ups of the side and rear elevation windows and doors are effective at securing the building. The north elevation doors and windows are essentially unchanged since the 2002 HSR and remain unboarded to provide access to the interior.
- For the most part, the building roof is unchanged since the 2002 HSR. The many roof/wall intersections and changes in roof plane still likely allow some water leakage to the interior, although the large gaps between the north and south second floor gable walls and the adjacent shed roofs have been covered with new membrane flashing.
- Access to the interior to assess the current condition of the building structure and the water tightness of the building envelope is limited by the material stored in the building (Figure 63). The volume of stored furniture and other items in the interior seems to have increased since the 2002 HSR. Some of these items are flammable and potentially hazardous, including a motorcycle with gasoline in its fuel tank, paint cans, roofing asphalt cans, and a kerosene lamp. Many interior materials have damage and biological growth as a result of previous or ongoing water infiltration (Figures 64 and 65).

Interior – First Floor

Front Porch

- The concrete floor is cracked and spalled, and is generally in poor to fair condition.

Entry

- The paneling on the north, west, and east walls is mismatched, water damaged, and warped, and is in fair condition overall.
- The indoor/outdoor carpeting is worn and loose, and is in poor condition overall.
- The gypsum board ceiling has extensive water damage and is in poor condition, with some pieces of board missing.
- The door into the storage room is rotted with delaminated veneer and is in poor condition.

Living Room/Dining Room

- The linoleum floor is worn and curled, with large pieces missing, and is in poor condition overall.
- The gypsum board ceiling is in fair condition with cracking of panel edge seams. Holes broken through the ceiling reveal old newspapers used as insulation (Figure 66).
- The door into the storage space under the stairs is water damaged and in fair condition. The door to the second floor stairway does not close properly. The lower portion of this door is rotted, with delaminated veneer, and is in poor condition.

North Bedroom

- There are cracks at the north and west walls and some minor paint loss. The door into the south bedroom is missing and the finish on the wood door frame is deteriorated.

South Bedroom

- The carpeting is worn. The west and south walls exhibit severe cracking. There is

severe cracking at joints in the ceiling. The door leading to the bathroom has some water damage at the bottom. The stone lintel above the door into southwest bedroom has cracked, and the wood door is off its hinges.

Bathroom

- The flooring is cracked and warped with severe water damage, and is in poor condition.
- The north wall has severe water damage and is in poor condition.
- The wood ceiling has some cracking at the edges and is in fair condition.

Kitchen

- The sheet vinyl flooring is cracked, torn, and delaminated, and is in poor condition overall.
- The wallpaper on the east wall is peeling. The painted plaster on the south wall is deteriorating.
- The kitchen cabinets are warped and water damaged, and are in fair condition overall.
- The door to the back porch is discolored.

Pantry

- The vinyl flooring is warped, deteriorated, and rotted to the point that the crawlspace below can be seen through openings in the floor, and is in poor condition overall.
- The gypsum board is cracked and water damaged at the west wall.
- The ceiling is heavily water damaged at the center of the room. The door frame at the opening to the kitchen is water damaged.

Back Porch

- The carpet is loose and torn, and the vinyl is cracked and in poor condition overall.

- Some of the wood wall paneling is missing, warped, and water damaged.
- The exposed plywood sheathing that comprises the ceiling of the back porch is severely deteriorated and water damaged, and is in poor condition overall. The exposed shed roof framing also exhibits water damage and is in fair condition.

Southwest Bedroom

- The carpeting is worn and torn in places. The plaster of the north wall is cracked and deteriorated. The wood paneling on the other walls is warped and water damaged. The ceiling finishes are warped, peeling, and water damaged.

Interior – Second Floor

East Bedroom

- The carpet is worn and loose.
- The wallpaper on the walls and ceiling is severely cracked and delaminated.

North Bedroom

- The floor is vinyl over wood sheathing. The east, west, and south walls are painted plaster over masonry. The plaster exhibits severe cracking and spalling. The north wall is gypsum board over wood framing. The gypsum board is covered with wallpaper. The wall finishes are severely deteriorated. The sloped ceiling is gypsum board covered with wallpaper. The ceiling materials are severely water damaged.

South Bedroom

- All finishes in the south bedroom are severely deteriorated.
- The carpet is worn and water stained, and is in poor condition.
- The plaster on the walls is cracked in many locations and is deteriorating due to moisture infiltration. Various localized

repairs have been performed since 2002 (refer to Figure 30).

- The gypsum board ceiling, where still in place, is sagging and is deteriorated. Other areas of the ceiling material have been removed or have fallen down, revealing the roof framing above (Figure 67). Newspaper used as wallpaper has been painted over. The newspaper is shredded and torn, and generally falling off the gypsum board substrate. The ceilings are generally in poor condition.



Figure 61. Deterioration of the wood roof overhang, south elevation. Photo by WJE, 2009.



Figure 62. Unpainted wood eave trim and unsealed gaps between stucco and wood trim. Photo by WJE, 2009.



Figure 63. A large quantity of furniture and other items is stored in the building. Photo by BVH, 2009.



Figure 64. Previous or active water leakage has damaged the plywood roof deck and wood rafters at the southeast corner of the first floor. Photo by BVH, 2009.



Figure 65. Previous or active water leakage has resulted in the collapse of gypsum wallboard and ceiling finishes at the second floor. Photo by BVH, 2009.



Figure 67. Gypsum board ceiling deterioration. Photo by BVH, 2009.



Figure 66. Access/inspection holes broken into the living room ceiling by unknown party at unknown date. Photo by BVH, 2009.

NICODEMUS SCHOOL DISTRICT NO. 1 BUILDING

Exterior

The following conditions were observed during site work performed for the HSR Update:

- The existing roof shingles date to the 1990s and are generally intact. Localized roof leakage is occurring around the chimney, most likely related to deficiencies in the roof flashing.
- Significant additional deterioration of the building foundation has occurred since the 2002 HSR. In particular, the cracking at the northeast corner of the building has worsened (Figure 68). Based upon the cross-section of the wall exposed at the crack and spall locations, it appears that the cast-in-place concrete foundation is only intermittently reinforced with salvaged iron fragments such as straps, fencing, and grilles.
- Significant additional weathering of the exterior siding has occurred since the 2002 HSR. The paint coating has subsequently weathered, leaving much of the wood siding exposed. Large portions of the siding have cracked, split, or detached from the building (Figures 69 and 70). The newly installed siding at the bottom half of the north elevation is intact (Figure 71).
- To assist with future repair design, a fragment of wood siding, assumed to be original, was collected for laboratory analysis. The wood material was identified as Western Yellow Pine group (*Pinus ponderosa*).
- The structural stability of the building roof requires further study. The east wall of the building has bulged outward (Figure 72), likely due to irregular forces imparted by the configuration of the hip roof and the presence of vertical ties from the ceiling joists to one rafter at the centerline of the building. These conditions are unchanged since the 2002 HSR.

▪ *Interior*

Entry Hall

- The flooring is cupped and warped, and the finish is worn. The floor of the entry hall is generally in fair condition.
- There is severe cracking of the plaster at the corners of the walls and the paint is deteriorated due to moisture infiltration. The plaster is in fair condition overall.
- The finish of the wood trim is chipped and worn, and has a build-up of multiple coats of paint. The trim is generally in fair condition.
- The ceiling is severely water damaged over the south entry door area and the plaster is delaminating from the wood lath. The ceiling plaster is in fair condition.
- The wood of the door to the exterior is cracked and damaged.

Coat Room

- The floor is in good condition except for accumulation of dirt and debris.
- Minor cracking of the plaster of the east wall is evident; however, the plaster is generally in good condition. The paint finish is peeling, crazed, and in poor condition.
- The ceiling is painted plaster, which is in fair condition.
- The painted wood base trim has worn and chipped paint and is in fair condition.
- The painted finish of the door into the classroom is severely cracked, crazed, and worn. There is also damage at the edges and top of the door.

Storage Room

- There is severe cracking and large areas of plaster delamination at the south, east, and north walls due to water infiltration.

Classroom

- The wood flooring exhibits some warping and cupping but is generally in fair condition overall.
- Past water leakage near the chimney and clean-out on the east wall has damaged the floor, wall, and ceiling.
- Various localized failure of the plaster has left the wood lath exposed. The plaster is in fair condition overall.
- At various locations the plaster is severely cracked. The plaster is in fair to poor condition overall.

Kitchen

- The flooring has severe cracking and curling at the edges.
- Severe cracking has occurred at the east wall, and stepped cracks have occurred on the north and east walls, related to the structural displacement of the east building wall.

Other conditions are essentially unchanged since the 2002 HSR.



Figure 68. Crack at the northeast corner of the foundation. Photo by WJE, 2009.



Figure 69. Deterioration of the existing wood siding at the west elevation. Photo by BVH, 2009.



Figure 70. Deterioration of the existing wood siding at the west elevation. Photo by BVH, 2009.



Figure 71. View of the north elevation showing newly installed wood siding. Photo by WJE, 2009.



Figure 72. The east wall of the building has bulged outward; note the curve of the roof eave line. Photo by WJE, 2009.



Figure 73. Plaster and gypsum wall board removed for stabilization effort. Photo by BVH, 2009.

TOWNSHIP HALL

Exterior

The following conditions were observed during site work performed for the HSR Update:

- Water leakage is occurring at the top of the walls. A possible source for the observed leakage is the unsealed gap between the masonry and wood roof eave trim (Figure 74).
- Water leakage is occurring around the brick chimney on the east face of the roof near the north end. Access to inspect the chimney close-up was not possible during the field work for this study, but the water leakage may be related to the flashing at the base of the chimney. This flashing appears to be older than the recently installed asphalt shingle roofing.
- During the recent roof replacement, new flashing was installed into a new reglet at the joint between the vestibule roof and the main building south wall (Figure 75). The reglet joint and the lap joints within the flashing are unsealed.
- Perimeter drainage at the base of the building is problematic. There are no gutters at the roof. On the east side of the building, there is a concrete walk installed in 1971 along the entire length of the building (Figure 76). On the west side of the building, there is a concrete terrace along the north half (Figure 77). These concrete paved areas slope toward the building, exacerbating stone spalling and staining at the base of the wall. At the north side area well, the exterior basement steps have an area drain that does not seem to be connected to piping (Figure 78). This area reportedly ponds water during rain.
- Other than exterior repainting, the window conditions are unchanged since the 2002 HSR. Deterioration of interior glazing putty is continuing, and many lights have been reglazed from the interior using sealant (Figure 79). There are some cracked panes of glass.
- The existing exterior doors are not original. The south main entrance doors were replaced prior to 1977. The east side entrance door has been replaced since the 2002 HSR and consists of an aluminum door in a vinyl-clad frame. The north basement door is a painted steel door in a wood frame. The west side entrance door is a painted plywood panel door and has been repainted since the 2002 HSR. The west side door has paint loss and wood decay along the bottom edge (Figure 80).
- At the north elevation, the pipe railing around the area well and steps leading to the basement door has surface corrosion and paint loss.
- The basement level window opening at the east side of the north elevation is infilled with glass block, one unit of which is damaged.
- For most of the building, the condition of the exterior masonry has worsened slightly since the 2002 HSR. Distress conditions include step cracking at the south elevation (Figure 81); cracking and spalling at window lintels (Figures 82 and 83); cracking deterioration of mortar joints (Figure 84); localized spalling, especially near grade (Figure 85); and organic growth and staining, which is heaviest near grade on the east and west elevations and across the north elevation.
- The north elevation was affected by a recent hail storm. Many small chips of stone spalled from the stone surface as a result of hail impact (Figure 86). Since the spalled areas are free of organic growth and staining, the elevation has a somewhat speckled appearance (Figure 87). The spalling damage does not require repair, but it does demonstrate the fragility of this stone to impact damage.

Interior

Vestibule

- The textured plaster ceiling has minor cracking and is in good condition overall.
- The painted concrete floor has minor shrinkage cracks and is in good condition overall.
- The exterior entry doors are in good condition. An accessible threshold has been added since 2002.

Ticket Booth

- The paint on the wood ticket counter is chipped. The counter is in fair condition overall.

Closet in Vestibule

- There is minor cracking in the plaster walls and a large crack at the window lintel. The plaster walls are generally in good condition.
- The ceiling plaster has minor hairline cracks and is generally in good condition.
- The paint on the closet door is chipped and scratched, but otherwise the door is in good condition.

Assembly Hall

- The finish on the wood floor is worn and scratched in traffic areas, with some stains near the stage area. The flooring is generally in good condition.
- There is considerable cracking in the plaster walls, especially at the window lintels. Localized water staining is evident; however, the plaster walls are in good condition overall.
- The visible ceiling plane is composed of acoustic ceiling tiles affixed to the bottom chord of the roof trusses, and is in good condition with no visible signs of water leakage.

East Side Room and East Stairs

- The concrete floor has been painted since 2002. Reflective caution tape has been applied to the concrete stair treads (Figure 88). The floors are in good condition.
- There is a suspended acoustic ceiling tile system in the east side room. A tile is missing and the grid exhibits surface corrosion (Figure 89). The ceiling is generally in good condition.
- The plaster walls have minor cracking and water damage, and are generally in good condition.
- The exit door has been replaced since 2002 with a hollow metal door with panic hardware, and is in good condition (figure 88).

Women's Restroom

- The concrete floor in the restroom has been painted since 2002 and is in good condition.
- There is minor cracking in the plaster at the east and west walls. The walls are in good condition.
- The suspended acoustical tile ceiling exhibits water damage, with some warped and deformed tiles. The ceiling is in fair condition.

Stage

- The painted concrete floor is worn at traffic areas.
- There is some warping in the wood wall paneling.
- Some water damage has occurred to the suspended ceiling panels, which are warped and deformed. The ceilings are in fair condition.

West Side Room and West Stairs

- The floor has been painted since 2002. Reflective caution tape has been applied to

the stair treads. The floors are in good condition.

- There is cracking in the plaster wall at the intersection of the stage floor and the basement wall. There is minor cracking and water damage at the southwest corner of the ceiling.

Men's Restroom

- The floor has been painted since 2002. The floor is in good condition.
- Hairline cracking has occurred in the plaster walls and in the original plaster ceiling where visible above the suspended acoustical tile.

Basement

- The basement has been cleaned and painted since 2002. The walls, floors, and concrete ceiling structure have been repainted.



Figure 74. Open joint where the stone masonry meets the wood roof trim at the eave and gable. Photo by WJE, 2009.



Figure 75. New flashing and reglet where the vestibule roof meets the south gable wall. Photo by WJE, 2009.



Figure 76. Staining and stone distress near grade and the concrete paving along the east elevation. Photo by WJE, 2009.



Figure 77. Concrete terrace at the north half of the west elevation. Note the concentration of staining and masonry distress at the areas adjacent to the concrete paving. Photo by WJE, 2009.



Figure 78. Exterior stairs at the north side of the building. Photo by WJE, 2009.



Figure 81. Step cracking at the south gable wall. Photo by WJE, 2009.



Figure 79. Reglazing of individual lights with sealant is visible as a light-colored perimeter (for example, center bottom light). Photo by WJE, 2009.



Figure 82. Spalling of stone at the bearing point of a window lintel. Photo by WJE, 2009.



Figure 80. The west side entrance door has paint loss and wood deterioration. Photo by NPS, 2009.



Figure 83. Cracking of stone at the bearing point of a window lintel. Photo by WJE, 2009.



Figure 84. Cracking of mortar joints. Photo by WJE, 2009.



Figure 87. Intermittent impact damaged stone without organic growth gives the north elevation a speckled appearance. Photo by WJE, 2009.



Figure 85. Heavy staining and spalling of stone, concentrated at grade near the concrete paving. Photo by WJE, 2009.



Figure 88. Painted concrete floor with reflective caution tape at stairs. Photo by BVH, 2009.



Figure 86. Spalled stone units at the north elevation due to impact damage. Photo by WJE, 2009.



Figure 89. Location of missing ceiling tile, revealing removed plaster with lath remaining. Note corrosion on metal frame for ceiling tile. Photo by BVH, 2009.

1 TREATMENT AND USE

2 PRESERVATION OBJECTIVES

3 In the 2002 HSR, the overall treatment
4 *preservation* was recommended for the five
5 buildings of the Nicodemus National Historic
6 Site. The treatment options and details of the
7 *Secretary of the Interior's Standards* are
8 described in the HSR. The *Secretary of the*
9 *Interior's Standards* identifies *preservation* as
10 an appropriate treatment:

- 11 ■ when the property's distinctive materials,
12 features, and spaces are essentially intact
13 and thus convey the historic significance
14 without extensive repair or replacement.

15
16 The 2002 HSR noted that the five subject
17 buildings were essentially intact, although in
18 varying states of disrepair.

- 19 ■ when depiction at a particular period of time
20 is not appropriate.

21
22 The 2002 HSR noted that the significance of
23 Nicodemus was in part related to the
24 ongoing life of the community and that
25 depiction of a particular historic moment
26 had not been determined.

- 27 ■ and when a continuing or new use does not
28 require additions or extensive alterations.

29
30 The 2002 HSR noted that no General
31 Management Plan (GMP) existed and no
32 new use had been identified for the four
33 disused buildings, and that the Township
34 Hall did not require major alterations to
35 continue to function as an interim visitor
36 center.

37 Subsequent to the completion of the 2002 HSR,
38 the National Park Service completed a GMP for
39 Nicodemus National Historic Site.¹² The GMP
40 defined the following long-term uses for the five
41 buildings of the study:

- 42 ■ The St. Francis Hotel/Fletcher-Switzer
43 Residence and the Nicodemus School
44 District No. 1 Building were designated as
45 part of the "story area," to be used for the
46 interpretation of Nicodemus for visitors. A
47 long-term goal would be acquisition of these
48 properties by NPS from willing
49 sellers/donors.

- 50 ■ The A.M.E. Church was designated as the
51 "spiritual area," to be used for
52 contemplation and personal reflection by
53 visitors.

- 54 ■ The Old First Baptist Church and the
55 Township Hall were designated as the
56 "traditional use area," to continue to evolve
57 over time to suit community needs and
58 goals. Visitors may be allowed to visit the
59 buildings as determined by local
60 stakeholders, but NPS involvement would
61 be limited.

62 Because the various long-term uses for the five
63 buildings have been defined by the GMP, it is
64 appropriate to reconsider the overall
65 recommended treatment approach for the
66 buildings. Based on current programmatic
67 requirements for the individual structures, and
68 on current NPS goals for the historic site,
69 different treatment approaches have been
70 identified for the different structures. The
71 specific treatments must be compatible within
72 the overarching preservation guidelines for the
73 historic site. It is important to make sure that the
74 treatment of each individual structure is
75 consistent with the interpretation of the town
76 site as a whole and to avoid the creation of an
77 appearance that never existed historically.

78 For the A.M.E. Church, the treatment
79 *restoration* is appropriate for the long term use
80 identified in the GMP. Due to the previous
81 deterioration of the building, significant repair
82 work is required before the building can serve
83 its intended function as the "spiritual area." The
84 proposed contemplation/reflection use does not
85 require alteration of the original form of the

12. National Park Service, *Nicodemus National Historic Site: General Management Plan*, April 2004.

1 building; any needed contemporary facilities for
2 visitors can be provided at other structures of the
3 site.¹³ The restoration of the building should be
4 guided by physical evidence and photographic
5 documentation of the building as it existed circa
6 1950, during its most recent period of active use.

7 For St. Francis Hotel/Fletcher-Switzer
8 Residence and the Nicodemus School District
9 No. 1 Building, the treatment *rehabilitation* is
10 appropriate for the long term use identified
11 under the GMP. Under this treatment, the
12 buildings can be adapted to meet the
13 interpretative, educational, or other needs of
14 contemporary visitation, physical deterioration
15 of materials can be repaired, and the historic
16 character of the buildings can be protected.

17 For the Old First Baptist Church and the
18 Township Hall, the treatments *rehabilitation* or
19 *preservation* can be considered for the possible
20 long term uses identified under the GMP. If
21 desired by the local community, the existing
22 physical condition of the buildings can be
23 sustained (with appropriate maintenance to
24 address deterioration or weathering). The
25 *preservation* option assumes that contemporary
26 visitation to these buildings would be limited; in
27 the case of the Old First Baptist Church, visitors
28 would be able to view the building exterior only.
29 Alternately, if the local community identifies
30 new uses that are compatible with the historic
31 character of the structures, the *rehabilitation*
32 option would be appropriate. This option would
33 permit changes to allow new uses of both
34 buildings by the local community and/or visitors
35 to the site.

36 These treatment approaches relate to the long
37 term use of the buildings as described under the
38 GMP. Before the long term uses can be
39 determined, however, issues of building
40 ownership and management must be resolved.
41 In the interim, the treatment *preservation* as
42 described in the 2002 HSR remains appropriate,
43 to protect the historic resources in the short
44 term. Therefore, the technical treatment
45 recommendations presented below are focused
46 on immediate maintenance and stabilization

13. Development of interpretive media for the A.M.E.
Church is proposed under PMIS 143710.

47 measures to protect the buildings. Additional
48 investigation and review of existing conditions
49 of the subject buildings will be needed once the
50 decision is made to implement the long term
51 uses identified in the GMP.

52 Additionally, conceptual recommendations are
53 provided for the restoration of the A.M.E.
54 Church. As the one structure currently owned by
55 NPS, it is likely that it will be possible to
56 proceed with work to address long term
57 treatment goals at this building sooner than for
58 the other buildings of the site. Due to the
59 previous loss of significant portions of the
60 historic fabric at this building, further study will
61 be needed during the design phase to guide the
62 restoration of this building.

63 **REQUIREMENTS FOR TREATMENT**

64 The 2002 HSR defines the logical prioritization
65 of treatment work at the five buildings; provides
66 technical guidance related to the common
67 historic materials of the buildings; and provides
68 general recommendations that apply to all five
69 buildings of the historic site. This information
70 remains relevant and appropriate. Stabilization
71 of the building structures and weatherproofing
72 of the building envelopes should precede
73 rehabilitation of interior finishes. All of the
74 buildings require ongoing inspection and
75 maintenance, continuing after the completion of
76 recommended repair work.

77 As noted in the GMP, at a minimum it is
78 desirable for NPS to obtain facade easements for
79 non-NPS owned structures.¹⁴ The easement
80 process is intended to protect the integrity of the
81 National Historic Site and ensure that future
82 repair and maintenance work is consistent with
83 the *Secretary of the Interior's Standards*.

14. A preservation facade easement is a voluntary legal agreement providing that the property's historic values will be preserved through subsequent ownership. In addition, the owner may obtain tax benefits. Under the terms of an easement, property owners grant a portion of, or interest in, their property rights to a historic preservation organization such as the National Park Service or a not-for-profit group. Once recorded, an easement becomes part of the property's chain of title in perpetuity, thus binding not only the owner who grants the easement but all future owners.

1 **RECOMMENDATIONS FOR FUTURE**
2 **RESEACH**

3 The following areas of study are recommended
4 for further research:

- 5
6 1. **Structural analysis.** All of the buildings
7 continue to have some potential structural
8 deficiencies that may be the primary cause
9 of the distress observed in the building
10 fabric, including problems with foundations
11 and wood floor and roof framing. As
12 outlined in the 2002 HSR recommendations
13 and the specific recommendations listed
14 below, structural analysis of particular
15 construction details is necessary before
16 damage to building finish materials, such as
17 plaster or stucco, is repaired.
18
19 2. **ADA compliance.** Compliance with the
20 Americans with Disabilities Act (ADA) is
21 dependent upon the use of the structure.
22 Until a determination is made regarding the
23 intended use of the buildings, the degree of
24 non-compliance and the need for
25 architectural modifications to achieve
26 compliance cannot be fully assessed. Prior
27 to making architectural modifications to the
28 buildings, consideration should also be
29 given to off-site interpretation of the history
30 and significance of the buildings in lieu of
31 making the buildings themselves fully
32 accessible.
33
34 3. **Code compliance.** Compliance with
35 building codes is also dependent on the use
36 of the structure. Until an ultimate
37 determination is made regarding the
38 intended use of the buildings, the need for
39 code-related modifications cannot be
40 assessed. In working with historic
41 buildings, a creative approach that provides
42 life safety while maintaining significant
43 building fabric is most appropriate. If
44 drastic changes to the historic building
45 fabric would be required to achieve code
46 compliance for a particular use, the
47 appropriateness of that use for that building
48 should be reconsidered.
49

- 50 4. **Termite inspection.** All of the buildings
51 contain substantial amounts of wood
52 structural and finish elements. Although
53 there is no obvious sign of active termite
54 damage at present, ongoing inspection and
55 monitoring to avoid future damage is
56 appropriate.
57
58 5. **Archaeological investigation.** Several of
59 the specific recommendations below involve
60 disruptions to subsoil conditions, including
61 the installation of perimeter drainage or
62 foundation repair. It is important when any
63 excavation is made for any reason on the
64 townsite that a proper archaeological
65 investigation is coordinated with the work.
66 It would not be surprising to find lost or
67 discarded items that would reveal the
68 patterns of past daily life, particularly
69 considering the prevalence of dugout and
70 sod construction in the early history of the
71 townsite.
72
73 6. **Additional Finish Analysis and Research.**
74 It is recommended that during the interim
75 prior to any rehabilitation or restoration,
76 further research be performed on the
77 configuration and material finishes of the
78 building exteriors and interiors at the period
79 of significance. This would include further
80 paint and finish analysis, and plaster and
81 wood analysis. Accompanying this should
82 be an effort to complete a detailed inventory
83 of the materials stored at the interiors of the
84 buildings to determine what is available for
85 reuse for restoration or rehabilitation.

86 **ADDITIONAL GENERAL**
87 **RECOMMENDATIONS**

- 88 1. For the four buildings that are not presently
89 occupied, consideration should be given to
90 providing a minimum level of heat inside
91 the buildings during the winter months. A
92 minimum of 50 degrees Fahrenheit is
93 recommended to help protect building
94 materials. This could be accomplished by
95 the installation of small electric heaters: for
96 the Nicodemus District No. 1 School, one
97 heater would need to be located near the
98 center of the classroom; for the other three

1 buildings, two heaters would be needed at
2 selected locations on the first floor. Repairs
3 to electrical service and wiring would need
4 to be implemented prior to the installation of
5 heaters. Electric heaters are a safer and less
6 expensive alternative than gas-fired heaters;
7 they can safely be used in unoccupied
8 buildings. (See also next item about possible
9 incorporation of smoke and heat detectors.)
10

- 11 2. Consideration should be given to installing
12 smoke detectors in all of the buildings.
13 However, smoke detectors do not function in
14 unheated spaces, so this would require that a
15 minimum level of heat be maintained, as
16 described above. Alternately, heat detectors
17 could be installed. Heat detectors do not
18 require a heated interior to function, but they
19 would need to be connected to a fire alarm
20 panel and monitoring station in a normally
21 occupied building. Therefore, heat detectors
22 require that electrical and telephone service
23 be repaired and reconnected to the buildings.
24

- 25 3. Propane tanks are located at the A.M.E.
26 Church, St. Francis Hotel/Fletcher-Switzer
27 Residence, Old First Baptist Church, and
28 Nicodemus District No. 1 School Building.
29 The propane tanks should be emptied and
30 the propane pipes disconnected at each tank.
31

1 **UPDATED RECOMMENDATIONS**

2 **A.M.E. CHURCH**

3 The proposed long term use of the A.M.E.
4 Church is as a spiritual space for contemplation
5 and reflection by visitors to the National
6 Historic Site. The following discussion includes
7 recommendations for both immediate
8 weatherproofing and protection of the building
9 (short-term treatment recommendation) as well
10 as general work intended to restore the building
11 (long-term treatment recommendation) to its
12 circa 1950 appearance, prior to the
13 discontinuation of its use by the church
14 congregation in the 1950s and the severe
15 physical deterioration of the building that
16 occurred from the 1960s to 1990s.¹⁵ This target
17 restoration date is appropriate in order to
18 maintain a consistent overall interpretation of
19 the town site. Restoration of this building to an
20 earlier appearance would conflict with the
21 intention to retain later additions and alterations
22 to other buildings of the town site.

23 **Stabilization**

- 24 ■ Improve site drainage adjacent to the north
25 wall by adding fill near the building and re-
26 grading to provide positive surface slope.
- 27 ■ Repair spalls deeper than one inch in stone
28 masonry with stone dutchman units.
- 29 ■ Secure cracked stone units, such as the
30 lunette stone over the south elevation
31 window opening, with stainless steel pins.
- 32 ■ Reroof the east vestibule to match the main
33 roof, including appropriate flashing at the
34 intersection of the vestibule roof and the east
35 wall of the sanctuary.
- 36 ■ Repair cracks in the stucco cladding of the
37 vestibule with appropriate cementitious
38 materials.
- 39 ■ Review project documentation and/or
40 perform laboratory materials analysis to
41 determine what mortar mixes were used in

42 recent repointing work at the west and south
43 elevations. The appropriate treatment for the
44 west elevation, where inappropriate
45 repointing mortar was previously installed,
46 needs further study, coordinated with the
47 results of the mortar study performed in
48 2000 for the A.M.E Church (refer to
49 Appendix E in the 2002 HSR). In particular,
50 further assessment is needed to determine
51 whether it will be possible to remove the
52 mortar without significantly damaging the
53 stone units.

- 54 ■ Perform laboratory testing and petrographic
55 study of original stone material to guide
56 future selection of more appropriate mortar
57 mixes and possibly identify a replacement
58 stone type that will be a closer aesthetic
59 match.
- 60 ■ Install backer rod and sealant on both the
61 interior and exterior where the walls of the
62 east vestibule meet the east wall of the
63 sanctuary.
- 64 ■ Maintain the north temporary wall. Close
65 gaps in the north temporary wall using
66 plywood at large openings. At the perimeter
67 of the wood cladding and joints between
68 wood pieces, seal with sealant.
- 69 ■ Maintain the sanctuary roof and painted
70 exterior wood elements.¹⁶

71 **Restoration**

- 72 ■ Reconstruct the north side masonry, the
73 north elevation cross gable, and the north
74 vestibule. The exterior reconstruction will
75 require a new foundation, new masonry wall
76 construction, new wood structural roof and
77 floor framing, and new window and door
78 units. Fragments of some of these original
79 elements exist in the building and may be
80 used to guide the design of the new work.
81 Further research is required to establish the

15. The proposed rehabilitation/restoration scope for the A.M.E. Church is described in PMIS 154163.

16. Proposed cyclical maintenance of the A.M.E. Church is described in PMIS 114171.

- 1 dimensions and details of the cross-gable,
2 arched window, and vestibule.¹⁷
- 3 ■ Once the north wall is reconstructed, the
4 roof structure can be reinforced as needed
5 and adapted to bear on the new north wall,
6 allowing the interior shoring to be removed.
- 7 ■ To address drainage of the site and from the
8 roof, a perimeter French drain system should
9 be installed, aligned to the roof overhang.
- 10 ■ Repair and replace wood floor joists and
11 decking to address rotted and deteriorated
12 wood and restore the interior floor structure.
- 13 ■ Apply a new stucco finish to the exterior
14 masonry walls. A painted stucco coating is
15 appropriate to the restored circa 1950
16 appearance of the building. Aesthetically,
17 the stucco will conceal the color mismatch
18 between the new and original stone units.
19 Further research is needed to determine an
20 appropriate stucco mix design that will be
21 durable and will protect and preserve the
22 original stone masonry wall construction.
- 23 ■ Additional work recommended during the
24 interim period prior to restoration would
25 include the completion of further research to
26 the configuration and material finishes of the
27 exterior and interior at the period of
28 significance. This would include further
29 analysis of plaster, wood, and painted
30 finishes. Accompanying this effort should be
31 a detailed inventory of the materials stored
32 at the building to determine what is
33 available for reuse for restoration.
- 34 ■ Once the research and inventory is
35 completed, final restoration design can
36 proceed.
- 37 ■ The final restoration design will need to
38 respond to a reuse and interpretive
39 program that has not yet been defined.
40 This program will affect the need for,
41 and most likely require, accessible
- 42 routes to and into the building, the
43 installation of a minimal electrical
44 system to provide power for lighting,
45 security and detection systems, and the
46 installation of a minimal mechanical
47 system to provide minimal heating
48 during the winter months to protect
49 restored finishes. Additional systems
50 such as automatic fire protection,
51 lightning protection and telephone/
52 telecommunications may also be
53 required.
- 54 ■ Interior restoration will involve
55 reinstallation and restoration of the wood
56 tongue and groove bead board ceiling;
57 reinstallation and restoration of the wood
58 tongue and groove flooring of the sanctuary
59 and vestibule; reinstallation and restoration
60 of the chancel rail and chancel flooring;
61 repair of the interior masonry walls; and
62 restoration of the plaster finishes and painted
63 finishes to the period of significance.
- 64

17. A proposed geophysical inventory of the A.M.E. Church site is described in PMIS 90474. This project should include identification of the location of the foundation for the north vestibule.

1 OLD FIRST BAPTIST CHURCH

2 Since the exact long term use of the Old First
3 Baptist Church has not been determined, the
4 following repair recommendations are intended
5 to preserve the building in its current, stabilized
6 condition with a weatherproof exterior, pending
7 future determination of an appropriate long term
8 treatment.

- 9 ▪ Maintain the exterior paint coating of the
10 window board-ups and soffit board-ups.
11 Within the next five years, recoating of the
12 exposed exterior wood elements should be
13 performed.
- 14 ▪ Maintain the exterior structural shoring.
15 Treated wood elements should be painted or
16 sealed within the next two years.
- 17 ▪ Coat the newer stucco and weathered
18 original stucco where paint is absent.
19 Potentially, the entire building could be
20 recoated to provide a consistent appearance.
- 21 ▪ Further stucco repairs should be considered
22 to address delaminated and cracked areas of
23 stucco, beyond the localized repairs
24 implemented in 2006.
- 25 ▪ Repoint the concrete masonry walls of the
26 northwest addition. Consideration could be
27 given to applying a stucco coating to these
28 walls, to match the original design of the
29 addition. Since the wall construction of the
30 addition consists of only a single wythe of
31 concrete masonry, the walls are likely to
32 experience ongoing moisture penetration
33 without some type of protective coating.
- 34 ▪ Monitor and maintain the new roof systems.
- 35 ▪ Document and remove all mold and mildew
36 damaged materials at the study and two
37 toilet rooms. Apply biocide and clean all
38 affected areas to prevent the spread of mold
39 and biological growth to other areas of
40 stabilized interior.

1 ST. FRANCIS HOTEL/FLETCHER-
2 SWITZER RESIDENCE

3 The long-term use of the building is to support
4 interpretation of Nicodemus for visitors. Until
5 an interpretive program is established and the
6 future use is identified, the scope of
7 rehabilitation work cannot be defined. In the
8 interim, the following recommendations are
9 intended to stabilize the building and provide a
10 weatherproof envelope.

11 ■ Document, catalogue, and remove all of the
12 furniture, appliances, boxes, household
13 items, window curtains, and other stored
14 objects from the building. Furniture and
15 other salvageable items should be stored off-
16 site and can be considered for possible
17 future use in interpreting daily life in
18 Nicodemus. Properly dispose of potentially
19 hazardous items such as paints and other
20 household chemicals.

21 ■ Following removal of household items,
22 document and remove water-damaged
23 interior finishes such as fabric, carpet,
24 gypsum board, particle board, and wood
25 paneling. Representative samples of each
26 material from each room should be salvaged
27 and retained archivally as part of the historic
28 record of the building. The disconnection
29 and draining of the electrical, gas, and water
30 utilities should also be verified.

31 ■ Document and remove all mold and mildew
32 damaged materials. Apply biocide and
33 clean all affected areas to prevent the spread
34 of mold and biological growth to other areas
35 of stabilized interior.

36 ■ Following the clean-up work, the building
37 can be assessed in more detail for required
38 structural repairs and locations of active
39 water leakage.

40 ■ Perform localized maintenance-type roof
41 repairs. In particular, flashings at transitions
42 between roof areas and at roof/wall
43 intersections should be reviewed.

44 ■ Replace missing trim boards, especially at
45 the roof overhang.

46 ■ Repair, prime, and paint exterior wood trim,
47 windows, doors, the dormer wall siding, and
48 front porch wood frame. The front porch
49 wood frame should not be painted until it is
50 confirmed that it was painted originally.
51 Alternately, the frame could be coated with
52 a clear penetrating wood sealer.

53 ■ Install backer rod and sealant at gaps
54 between wood trim and stucco.

55 ■ Repair the cracked stone lintel at the first
56 floor south facade (at the door location
57 between bedrooms 2 and 3), on the original
58 rear wall of the house, using stainless steel
59 anchor rods.

60 ■ Replace decking and floor joists at localized
61 areas of rotted and deteriorated wood, such
62 as water-damaged floor joists and flooring at
63 location of water heater on first floor near
64 center of house, and sister new studs
65 adjacent to the water-damaged wood studs at
66 the east wall of the rear porch.

67 ■ Repair splits in first floor lapped siding on
68 the north facade. Repair missing and
69 displaced corner trim.

70 ■ The water utilities to the building should be
71 isolated outside the building and all water
72 drained in the piping and in the bathroom
73 water heater tank.

74 ■ Exposed Romex wiring should be removed.

75

1 NICODEMUS SCHOOL DISTRICT NO. 1
2 BUILDING

3 The long-term use of the building is to support
4 interpretation of Nicodemus for visitors. The
5 following discussion includes both
6 recommendations for immediate
7 weatherproofing and protection of the building
8 as well as work intended to rehabilitate the
9 building for use in the interpretation of the site.

10 **Stabilization**

- 11 ■ Secure cracked and displaced portions of the
12 foundation using surface-mounted stainless
13 steel straps.
- 14 ■ Retain the interior shoring at the north wall.
- 15 ■ Complete the restoration of the north wall
16 wood window trim and reinstall original
17 trim pieces.
- 18 ■ Secure the building by boarding up window
19 openings and providing louvers for
20 temporary ventilation. Remove the metal-
21 framed screens from the north windows and
22 store in the building.
- 23 ■ Repoint the brick masonry chimney, and
24 install new flashing at the perimeter of the
25 chimney at its base.
- 26 ■ Repair cracks in the concrete front porch
27 slab with sealant. Repair the concrete block
28 walls at the porch base with grout. Repair
29 cracks in the concrete steps with sealant.
30 Seal the joints at the back of the steps.
- 31 ■ Clean, prime, and paint the steel porch
32 columns and base plates. The existing posts
33 are contributing to distress at the porch roof;
34 therefore, the bearing condition where the
35 posts meet the historic box beam should be
36 modified. Also, seal open joints in the porch
37 fascia.
- 38 ■ The gas piping in the kitchen should be
39 secured to the wall. Currently it is loose and
40 could pull off of its inadequate supports.

- 41 ■ Rehabilitate the exterior wood siding. The
42 paint coating applied in 1998 protected the
43 existing wood siding for a number of years,
44 but deterioration has become more
45 widespread recently. Further maintenance-
46 type repainting is unlikely to extend the life
47 of the siding. A more intensive work
48 program is now required. All exterior wood
49 siding and wood trim should be stripped of
50 paint. It may be desirable to remove all of
51 the siding to allow for inspection of the
52 underlying structure. This work should be
53 coordinated with the recommended
54 structural analysis and reinforcing of the
55 walls (as further discussed below). Also, if
56 the long term reuse of the building includes
57 conditioning of the interior space,
58 consideration should be given to adding
59 insulation and/or an air and water barrier to
60 the walls during this work. Intact pieces of
61 wood siding should be salvaged for
62 reinstallation, but it is anticipated that a
63 significant proportion of the siding is
64 severely deteriorated and will need to be
65 replaced with new material. The new wood
66 siding should match the dimensions, species,
67 and placement of the original siding.
68 Similarly, wood exterior trim elements
69 likely will require repair or replacement.
70 The new or salvaged wood siding and trim
71 should be primed and painted to match the
72 original color.
- 73 ■ Document, catalogue, and remove all of the
74 furniture, appliances, and other stored
75 objects from the building. Furniture and
76 other salvageable items should be stored off-
77 site and can be considered for possible
78 future use in interpreting daily life in
79 Nicodemus during the period of
80 significance. Properly dispose of potentially
81 hazardous items such as paints and other
82 household chemicals.
- 83 ■ Document and remove all mold and mildew
84 damaged materials. Apply biocide and
85 clean all affected areas to prevent the spread
86 of mold and biological growth to other areas
87 of stabilized interior.

1 Rehabilitation

- 2 ■ Design and construct a new cast-in-place
3 concrete foundation for the building. Since
4 the existing concrete foundation is shallow
5 and unreinforced, it cannot be repaired in a
6 manner that will provide for long term
7 preservation of the historic building.
8 Therefore, following detailed documentation
9 of the original foundation, an entirely new
10 foundation should be constructed.
11 Consideration could be given to creating a
12 full basement to house contemporary
13 mechanical equipment or provide space for
14 on-site storage. As part of the foundation
15 work, analyze and reinforce as needed the
16 first floor wood joists and flooring.
- 17 ■ Analyze and reinforce the wood roof and
18 wall structure as needed to properly support
19 dead and live loads. As noted in the 2002
20 HSR, the weight of the plaster ceiling in the
21 main interior space appears to be causing the
22 roof to deflect downward. It likely is not
23 possible to straighten the displaced east wall
24 of the school, but structural reinforcing
25 should be provided to secure it in its existing
26 position. The structural displacement is
27 likely also the cause of the observed plaster
28 cracking at the walls and ceilings of the
29 small east rooms of the school. Following
30 structural analysis and repair, remove the
31 north wall interior shoring.
- 32 ■ Restore the front porch by reconstructing the
33 wood floor structure, porch roof supports,
34 and railing to match the historic appearance
35 of the porch as documented in archival
36 photographs.
- 37 ■ Restore the windows and doors, including
38 repair and repainting of wood components,
39 repair and repainting of metal sash,
40 replacement of corroded screen mesh,
41 replacement of missing muntins and other
42 components, replacement of cracked glass
43 and glazing putty, rehang of previously
44 removed sash, and installation of perimeter
45 sealant.
- 46 ■ The final rehabilitation design will need to
47 respond to a reuse program that has not yet
48 been defined. This program affect the need
49 for, and most likely require, accessible
50 routes to and into the building, the
51 installation of new electrical systems to
52 provide for power, lighting, security, and
53 detection systems, and the installation of an
54 HVAC system to provide for heating and
55 potentially cooling during the periods of use
56 as well as to protect restored finishes.
57 Additional systems such as automatic fire
58 protection, lightning protection and
59 telephone/ telecommunications may also be
60 required.
- 61 ■ Interior rehabilitation should consider the
62 patching and repairing of plaster wall and
63 ceiling finishes, restoration and reuse of the
64 wood tongue and groove flooring, and reuse
65 and restoration of wood trim and millwork
66 elements such as doors, frames, baseboards,
67 and other features.
- 68 ■ The final rehabilitation design will need to
69 balance the retention of historic interior
70 fabric with functional needs.
- 71 ■ Consideration should be given to energy
72 improvements and energy conservation
73 enhancements during the design phases. As
74 the exterior restoration is implemented,
75 additional enhancements as discussed above
76 should be considered.
- 77

1 TOWNSHIP HALL

2 The Township Hall is generally in fair
3 condition. Localized repair and maintenance
4 tasks are recommended to sustain and
5 rehabilitate the building in its current use as the
6 interim visitor center.

7 ■ Undertake immediate measures to improve
8 the drainage of the site at the building
9 perimeter. At the east elevation, remove the
10 concrete paving, except for a narrow stoop
11 aligned to the east side door. Remove soil
12 and regrade the area to provide positive
13 slope away from the building. The top of
14 grade at the building wall should occur just
15 below the lowest course of limestone
16 masonry. Install pea gravel to promote
17 drainage.

18
19 At the west elevation, remove the concrete
20 terrace paving in the zone closest to the
21 building. Cast a new sloped sidewalk to
22 connect the west side door to the remaining
23 terrace. Remove soil and regrade the area to
24 provide positive slope away from the
25 building. The top of grade at the building
26 wall should occur just below the lowest
27 course of limestone masonry. Grade at the
28 southwest corner is already below this level
29 and should be filled to raise the grade
30 several inches. Install pea gravel to promote
31 drainage.¹⁸

32
33 At the north side area well, clean out the
34 drain to provide minimal temporary
35 drainage into the soil.

36 ■ Following or in lieu of the immediate
37 measures outline above, provide a new site
38 and perimeter drainage system. Excavate the
39 site and install subsurface drain tile,
40 connected to a sump pump. Provide a new
41 connection to the north area well drain.
42 Along the east and west elevations, install a
43 French drain aligned to the roof overhang.
44 As part of this work, consideration could be
45 given to installing waterproofing on the

46 subsurface portions of the foundation stone
47 masonry.

- 48 ■ Perform appropriate masonry repairs,
49 including the following:
- 50 ○ Conduct petrographic and laboratory
51 study of the existing stone and mortar
52 materials to guide selection of
53 appropriate masonry repair materials.
 - 54 ○ Repair joints at step cracks at the south
55 elevation. First, install simple crack
56 gauges and monitor the cracks for
57 increasing width. If, as seems likely, the
58 cracks grow and shrink due to
59 temperature variations, a sealant repair
60 will be appropriate. Following the
61 cracked mortar joint locations as closely
62 as possible, rout the mortar joints to a
63 depth three times their width and install
64 backer rod and sealant. If, however, the
65 cracks are progressively growing wider
66 regardless of temperature variations,
67 further structural investigation will be
68 needed to determine the cause of this
69 cracking. If the cracks are determined to
70 be non-moving, they can be repaired by
71 installation of mortar similar to that used
72 for repointing.
 - 73 ○ Perform localized repairs and install
74 dutchman units at isolated locations of
75 severely deteriorated, spalled, cracked,
76 and missing portions of stone units.¹⁹
 - 77 ○ Install backer rod and sealant in the open
78 joint between masonry and the wood
79 roofline trim.
 - 80 ○ Repoint open and cracked joints in the
81 stone masonry walls.
 - 82 ○ Perform a cleaning study to determine
83 appropriate materials and methods, and
84 clean the stone masonry facades to
85 remove organic growth and heavy
86 soiling.

18. Removal of the concrete paving near the building on the east and west elevations is proposed under PMIS 114163.

19. Repair of spalled stone units at grade along the east and west elevations is proposed under PMIS 114163.

1 ■ Investigate the condition of the brick
2 masonry chimney. If indicated by conditions
3 observed, repoint the brick masonry
4 chimney and/or replace the flashing at the
5 chimney/roof intersection.

6 ■ Repair split soffit boards at the roof
7 overhang. Maintain the existing paint
8 coating.

9 ■ Restore the steel windows, including
10 removal of the glazing putty on the interior
11 side, replacing cracked panes of glass,
12 repainting all metal surfaces, reglazing from
13 the interior side, and installation of new
14 perimeter sealant. Consideration should be
15 given to adding new interior storm windows
16 to improve the thermal efficiency of the
17 window system.

18 ■ Clean of corrosion, prime, and paint the
19 steel pipe railing at the north elevation area
20 well.

21 ■ Restore the exterior doors. At the south
22 entrance, consideration could be given to
23 reinstalling the original front doors (now
24 stored in the basement). The stored doors
25 should be examined to confirm that they are
26 original and to determine the extent of
27 modification/repair required to
28 accommodate their reinstallation.

29
30 At the east and west side entrances and the
31 north basement entrance, the existing doors
32 are non-original units. The west entrance
33 door is more heavily deteriorated; as an
34 interim repair measure, this door could be
35 replaced with a contemporary door, similar
36 to the recent work at the east side entrance.
37 The paint coating on all three doors should
38 be maintained. In the long term, all three of
39 these doors should be replaced with new
40 wood doors matching the historic door type
41 of the building.

42 For the building interior, the following
43 maintenance repairs are recommended:

44 ■ Repair cracked and water-damaged plaster.

45 ■ Replace water-damaged ceiling tile in toilet
46 rooms.

47 The following repairs are recommended for the
48 mechanical, electrical, and plumbing systems:

49 ■ Exposed Romex wiring should be replaced
50 with wiring and raceways suitable for an
51 exposed installation.

52

1 **OPINION OF PROBABLE COSTS**

2 The construction cost estimate in Appendix A
3 was developed by an independent cost
4 consultant who provided a detailed cost
5 breakdown for the proposed treatment options
6 and elements. The estimator visited with the
7 project consultants, reviewed the draft HSR
8 documents including the HSR Update, the 2002
9 HSR, and the accompanying drawings and
10 sketches to develop quantity take-offs and
11 component pricing. The estimate reflects the
12 labor rates for the Nicodemus, Kansas, area and
13 a 2010 construction period. The estimate
14 includes labor, overhead, and profit for
15 construction as well as a design and construction
16 contingency. Costs for items including
17 professional fees, furnishings, special technical
18 equipment, exhibits, or artwork are not included.

19 Please refer to the cost estimate in Appendix A
20 of this report.

21

22

BIBLIOGRAPHY

Refer to the Bibliography in the 2002 HSR for a complete list of sources.

Bahr Vermeer Haecker Architects, Ltd., and OCULUS. *Nicodemus National Historic Site, Cultural Landscape Report*. 2003.

Bahr Vermeer Haecker Architects, Ltd.; Wiss, Janney, Elstner Associates, Inc.; and Alvine and Associates, Inc. *Nicodemus National Historic Site, Historic Structures Report*. October 25, 2002.

National Park Service. *Nicodemus National Historic Site: General Management Plan*. April 2004.

———, Nicodemus National Historic Site, Midwest Region, and Harpers Ferry Center. *Long-Range Interpretive Plan: Nicodemus National Historic Site*. September 2009.

APPENDIX


Appendix B: Construction Drawings, Old First Baptist Church Repairs, 2004

APPENDIX B: CONSTRUCTION DRAWINGS, OLD FIRST BAPTIST CHURCH REPAIRS,
2004


OLD FIRST BAPTIST CHURCH STABILIZATION

NICODEMUS NATIONAL HISTORIC SITE

NICODEMUS, KANSAS



J1 AREA MAP
NO SCALE NOTE:



F1 VICINITY PLAN
NO SCALE NOTE:



C1 SITE MAP
NO SCALE NOTE:




OLD FIRST BAPTIST CHURCH, NICODEMUS, KANSAS, LOOKING NORTHEAST.

PHOTO BY BVH, 11/2003

INDEX OF DRAWINGS

SHEET	SUB SHEET	TITLE OF SHEET
1	-	COVER SHEET
ARCHITECTURAL		
2	A1	SITE PLAN
3	A2	FLOOR PLAN
4	A3	ROOF PLAN - DEMOLITION
5	A4	ROOF PLAN - NEW CONSTRUCTION
6	A5	WEST ELEVATION
7	A6	NORTH ELEVATION
8	A7	EAST ELEVATION
9	A8	SOUTH ELEVATION
STRUCTURAL		
10	S1	EAST WALL STABILIZATION
11	S2	ROOF FRAMING PLANS
12	S3	RAFTER REPAIRS
13	S4	TOWER ROOF REPAIRS
14	S5	MASONRY AND STUCCO REPAIRS



ARCHITECT
BAHR VERMEER HAECKER ARCHITECTS
121 SOUTH 13TH STREET, SUITE 200
LINCOLN, NE 68508
(402) 475-4551

STRUCTURAL ENGINEER
WISS, JANNEY, ELSTNER ASSOCIATES, INC.
330 PFINGSTEN ROAD
NORTHBROOK, IL 60062
(847) 272-7400

DATE	BY	REVISION
8 APRIL 2004		REVISED
14 JUNE 2004		
12 AUGUST 2004		
15 SEPTEMBER 2004		


RECOMMENDED	DATE
CHIEF, CULTURAL RESOURCES	
CONCURRED	
SUPERINTENDANT, NICODEMUS NATIONAL HISTORIC SITE	
APPROVED	
REGIONAL DIRECTOR, MIDWEST REGION	
REVIEWED	
REVIEWED	



CONSTRUCTION DOCUMENTS
UNITED STATES
DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE
MIDWEST REGIONAL OFFICE

**OLD FIRST BAPTIST CHURCH
STABILIZATION**
NICODEMUS NATIONAL HISTORIC SITE
NICODEMUS, KANSAS
REGION: MIDWEST COUNTY: GRAHAM STATE: KANSAS

DRAWING NO. 030
80001
SHEET 1
of 14




LEGEND

-  APPROXIMATE LOCATION OF DUGOUT SANCTUARY CA. 1877
-  APPROXIMATE LOCATION OF SOD SANCTUARY CA. 1880
-  APPROXIMATE LOCATION OF STONE SANCTUARY CA. 1885



B1
1" = 20'-0"

SITE PLAN
NOTE:



ARCHITECT
BAHR VERMEER HAECKER ARCHITECTS
121 SOUTH 13TH STREET, SUITE 200
LINCOLN, NE 68508
(402) 475-4551



STRUCTURAL ENGINEER
WISS, JANNNEY, ELSTNER ASSOCIATES, INC.
330 PFINGSTEN ROAD
NORTHBROOK, IL 60062
(847) 272-7400

DESIGNED
J. HANDELAND
DRAWN
M. HANSEN
TECH. REVIEW
DATE: 15 SEPT 2004


SUB SHEET NO.
A1

SITE PLAN
OLD FIRST BAPTIST CHURCH STABILIZATION
NICODEMUS NATIONAL HISTORIC SITE
NICODEMUS, KANSAS


DRAWING NO.
030
80001
SHEET
2
of 14



L13 TYPICAL VENTED WINDOW COVER
1" = 1'-0"
NOTE: SEE B1 ON SHEETS A5, A6, A7, AND A8, FOR LOCATIONS OF THIS DETAIL.



G13 ROUND ATTIC WINDOW COVER DETAIL
1" = 1'-0"
NOTE: SEE B1 ON SHEETS A5 AND A8 FOR LOCATIONS OF THIS DETAIL.



G18 VENTED WINDOW COVER DETAIL
3" = 1'-0"
NOTE:

- B13** DEMOLITION KEYNOTES
NOTE:
- 1 REMOVE AND DISPOSE OF EXISTING ASPHALT SHINGLES, WOOD SHINGLES, AND 1/4" OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL.
 - 2 REMOVE AND DISPOSE OF EXISTING WOOD SHINGLES AND 1/4" OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. VERIFY EXISTING LAP DIMENSION AT SHINGLES.
 - 3 REMOVE AND DISPOSE OF ENTIRE EXISTING TOWER ROOF, INCLUDING ROLL ROOFING, WOOD SHINGLES, 1/4" OPEN SHINGLE LATH, AND STRUCTURAL FRAMING. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEETS S2 AND S4 FOR ADDITIONAL DESCRIPTION OF WORK. VERIFY LAP DIMENSION, SIZE, SHAPE, AND LAYOUT PATTERN OF WOOD SHINGLES BEFORE REMOVAL.
 - 4 REMOVE AND DISPOSE OF ENTIRE LOW SLOPED ROOF, INCLUDING ROOF FRAMING RAFTERS. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEET S2 FOR ADDITIONAL DESCRIPTION OF WORK.
 - 5 REMOVE EXISTING BRICK CHIMNEY TO BELOW ROOF LINE. SALVAGE AND CLEAN BRICK. PLACE A SHEET OF PLYWOOD ON INTERIOR FLOOR OF BUILDING AND CAREFULLY STACK BRICK ON PLYWOOD FOR FUTURE REUSE.
 - 6 REMOVE AND DISPOSE OF EXISTING VENT PIPE OR FLUE PIPE TO BELOW ROOFLINE.
 - 7 REMOVE AND DISPOSE OF EXISTING TREES, SHRUBS, AND VEGETATION EXCEPT FOR GRASS AND ROSES ON WEST SIDE OF STRUCTURE. PROTECT ROSES DURING DEMOLITION AND NEW CONSTRUCTION. COORDINATE WITH NPS (COTR).
 - 8 REMOVE EXISTING WINDOW SASH AND STORE IN PROTECTIVE CONTAINER FOR REUSE AT A LATER DATE IN A SEPARATE FUTURE PROJECT. DELIVER FOR STORAGE WITHIN 1/4 MILE OF THE PROJECT SITE AS DIRECTED BY NPS (COTR).
 - 9 REMOVE EXISTING PLYWOOD COVER AT WINDOW OPENING, EXTERIOR FACE.
 - 10 REMOVE AND DISPOSE OF ENTIRE EXISTING METAL PIPE COLUMN.
 - 11 REMOVE AND DISPOSE OF ENTIRE EXISTING CRICKET, INCLUDING STRUCTURAL FRAMING, OPEN 1x4 WOOD LATH, AND WOOD SHINGLES.
 - 12 REMOVE AND DISPOSE OF EXISTING SCREEN OR PLYWOOD INFILL AT ROUND WINDOW.

B1 FLOOR PLAN
1/4" = 1'-0"
NOTE:

ARCHITECT
BAHR VERMEER HAECKER ARCHITECTS
121 SOUTH 13TH STREET, SUITE 200
LINCOLN, NE 68508
(402) 475-4551



STRUCTURAL ENGINEER
WISS, JANNEY, ELSTNER ASSOCIATES, INC.
330 PFINGSTEN ROAD
NORTHBROOK, IL 60062
(847) 272-7400

DESIGNED
J. HANDELAND
DRAWN
M. HANSEN
TECH. REVIEW
DATE: 15 SEPT 2004

SUB SHEET NO.
A2

FLOOR PLAN
OLD FIRST BAPTIST CHURCH STABILIZATION
NICODEMUS NATIONAL HISTORIC SITE
NICODEMUS, KANSAS

DRAWING NO.
030
80001
SHEET
3
of 14




- 1 THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE AN EXISTING ELEMENT OF THE BUILDING IS TO BE REMOVED. REFER TO KEYNOTE NUMERAL FOR A DESCRIPTION OF THE WORK.
- 2 THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE STUCCO IS MISSING OR DELAMINATED AND SHALL BE REMOVED. REPORT EXPOSED MASONRY. SEE DETAIL, II, SHEET 55.

P13 DEMOLITION GENERAL NOTES
NOTE:

- # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.
- 1 REMOVE AND DISPOSE OF EXISTING ASPHALT SHINGLES, WOOD SHINGLES, AND 1/2" OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL.
- 2 REMOVE AND DISPOSE OF EXISTING WOOD SHINGLES AND 1/2" OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. VERIFY EXISTING LAP DIMENSION AT SHINGLES.
- 3 REMOVE AND DISPOSE OF ENTIRE EXISTING TOWER ROOF, INCLUDING ROLL ROOFING, WOOD SHINGLES, 1/2" OPEN SHINGLE LATH, AND STRUCTURAL FRAMING. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEETS S2 AND S4 FOR ADDITIONAL DESCRIPTION OF WORK. VERIFY LAP DIMENSION, SIZE, SHAPE, AND LAYOUT PATTERN OF WOOD SHINGLES BEFORE REMOVAL.
- 4 REMOVE AND DISPOSE OF ENTIRE LOW SLOPED ROOF, INCLUDING ROOF FRAMING RAFTERS. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEET S2 FOR ADDITIONAL DESCRIPTION OF WORK.
- 5 REMOVE EXISTING BRICK CHIMNEY TO BELOW ROOF LINE. SALVAGE AND CLEAN BRICK. PLACE A SHEET OF PLYWOOD ON INTERIOR FLOOR OF BUILDING AND CAREFULLY STACK BRICK ON PLYWOOD FOR FUTURE REUSE.
- 6 REMOVE AND DISPOSE OF EXISTING VENT PIPE OR FLUE PIPE TO BELOW ROOFLINE.
- 7 REMOVE AND DISPOSE OF EXISTING TREES, SHRUBS, AND VEGETATION EXCEPT FOR GRASS AND ROSES ON WEST SIDE OF STRUCTURE. PROTECT ROSES DURING DEMOLITION AND NEW CONSTRUCTION. COORDINATE WITH NPS (COTR).
- 8 REMOVE EXISTING WINDOW SASH AND STORE IN PROTECTIVE CONTAINER FOR REUSE AT A LATER DATE IN A SEPARATE FUTURE PROJECT. DELIVER FOR STORAGE WITHIN 1/4 MILE OF THE PROJECT SITE AS DIRECTED BY NPS (COTR).
- 9 REMOVE EXISTING PLYWOOD COVER AT WINDOW OPENING, EXTERIOR FACE.
- 10 REMOVE AND DISPOSE OF ENTIRE EXISTING METAL PIPE COLUMN.
- 11 REMOVE AND DISPOSE OF ENTIRE EXISTING CRICKET, INCLUDING STRUCTURAL FRAMING, OPEN 1X WOOD LATH, AND WOOD SHINGLES.
- 12 REMOVE AND DISPOSE OF EXISTING SCREEN OR PLYWOOD INFILL AT ROUND WINDOW.

K13 DEMOLITION KEYNOTES
NOTE:

B1 ROOF PLAN - DEMOLITION
1/4" = 1'-0"
NOTE:



ARCHITECT
BAHR VERMEER HAECKER ARCHITECTS
121 SOUTH 13TH STREET, SUITE 200
LINCOLN, NE 68508
(402) 475-4551


STRUCTURAL ENGINEER
WISS, JANNNEY, ELSTNER ASSOCIATES, INC.
330 PFINGSTEN ROAD
NORTHBROOK, IL 60062
(847) 272-7400

DESIGNED
J. HANDELAND
DRAWN
M. HANSEN
TECH. REVIEW
DATE: 15 SEPT 2004


SUB SHEET NO.
A3

ROOF PLAN DEMOLITION
OLD FIRST BAPTIST CHURCH STABILIZATION
NICODEMUS NATIONAL HISTORIC SITE
NICODEMUS, KANSAS


DRAWING NO.
030
80001
SHEET
4
of 14



B1 ROOF PLAN - NEW CONSTRUCTION
 1/4" = 1'-0"
 NOTE:




M13 WEST ELEVATION AT TOWER ROOF
 3/8" = 1'-0"
 NOTE: NORTH, EAST, AND SOUTH ELEVATIONS SIMILAR.




H13 CEDAR ROOF RIDGE SCHEMATIC DETAIL
 1" = 1'-0"
 NOTE:

- 2 THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.
- 1 INSTALL NEW PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING. SEE H13, SHEET A4.
 - 2 INSTALL NEW STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING WITH DECORATIVE SHINGLE SHAPES. SEE M13, SHEET A4; AND B18, SHEET A4.
 - 3 INSTALL NEW ROLL ROOFING ON TOP OF TOWER. SEE B18, SHEET A5.
 - 4 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AFTER CAREFULLY REMOVING, LABELING, AND TURNING EXISTING WINDOW SASHES OVER TO COIR. SEE L13, SHEET A2; G18, SHEET A2; AND G18, SHEET A2.
 - 5 NEW TEMPORARY WOOD DOORS INSTALLED BY OTHERS.
 - 6 INSTALL PLYWOOD ENCLOSURE AROUND EXISTING EAVE, SOFFIT, FASCIA, AND TRIM. SEE M18, SHEET A4; AND H18, SHEET A4.
 - 7 INSTALL NEW ROLL ROOFING ON LOW SLOPED ROOF.
 - 8 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AT ROUND WINDOW.
 - 9 INSTALL NEW CRICKET, INCLUDING STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING.


B13 NEW CONSTRUCTION KEYNOTES
 NOTE:



M18 SECTION AT ROOF EAVE
 1" = 1'-0"
 NOTE:




H18 ENLARGED SECTION AT ROOF EAVE
 1 1/2" = 1'-0"
 NOTE: THESE SHINGLE SHAPES OCCUR ONLY AT THE TOWER PORTION OF THE ROOF




B18 CEDAR ROOF SHINGLE TYPES AT TOWER
 3" = 1'-0"
 NOTE: THESE SHINGLE SHAPES OCCUR ONLY AT THE TOWER PORTION OF THE ROOF

ARCHITECT BAHR VERMEER HAECKER ARCHITECTS 121 SOUTH 13TH STREET, SUITE 200 LINCOLN, NE 68508 (402) 475-4551	STRUCTURAL ENGINEER WISS, JANNEY, ELSTNER ASSOCIATES, INC. 330 PFINGSTEN ROAD NORTHBROOK, IL 60062 (847) 272-7400	DESIGNED J. HANDELAND	SUB SHEET NO. A4	ROOF PLAN NEW CONSTRUCTION OLD FIRST BAPTIST CHURCH STABILIZATION NICODEMUS NATIONAL HISTORIC SITE NICODEMUS, KANSAS	DRAWING NO. 030 80001 SHEET 5 OF 14
		DRAWN M. HANSEN TECH. REVIEW			



J1 WEST ELEVATION - DEMOLITION
1/4" = 1'-0"



B1 WEST ELEVATION - NEW CONSTRUCTION
1/4" = 1'-0"

- 1 [Symbol] THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE AN EXISTING ELEMENT OF THE BUILDING IS TO BE REMOVED. REFER TO KEYNOTE NUMERAL FOR A DESCRIPTION OF THE WORK.
- 2 [Symbol] THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE STUCCO IS MISSING OR DELAMINATED AND SHALL BE REMOVED. REPOINT EXPOSED MASONRY. SEE DETAIL, H1, SHEET 55.

P13 DEMOLITION GENERAL NOTES

- NOTE:
- # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.
 - 1 REMOVE AND DISPOSE OF EXISTING ASPHALT SHINGLES, WOOD SHINGLES, AND 1/2" OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL.
 - 2 REMOVE AND DISPOSE OF EXISTING WOOD SHINGLES AND 1/2" OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. VERIFY EXISTING LAP DIMENSION AT SHINGLES.
 - 3 REMOVE AND DISPOSE OF ENTIRE EXISTING TOWER ROOF, INCLUDING ROLL ROOFING, WOOD SHINGLES, 1/2" OPEN SHINGLE LATH, AND STRUCTURAL FRAMING. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEETS S2 AND S4 FOR ADDITIONAL DESCRIPTION OF WORK. VERIFY LAP DIMENSION, SIZE, SHAPE, AND LAYOUT PATTERN OF WOOD SHINGLES BEFORE REMOVAL.
 - 4 REMOVE AND DISPOSE OF ENTIRE LOW SLOPED ROOF, INCLUDING ROOF FRAMING RAFTERS. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEET S2 FOR ADDITIONAL DESCRIPTION OF WORK.
 - 5 REMOVE EXISTING BRICK CHIMNEY TO BELOW ROOF LINE. SALVAGE AND CLEAN BRICK. PLACE A SHEET OF PLYWOOD ON INTERIOR FLOOR OF BUILDING AND CAREFULLY STACK BRICK ON PLYWOOD FOR FUTURE REUSE.
 - 6 REMOVE AND DISPOSE OF EXISTING VENT PIPE OR FLUE PIPE TO BELOW ROOF LINE.
 - 7 REMOVE AND DISPOSE OF EXISTING TREES, SHRUBS, AND VEGETATION EXCEPT FOR GRASS AND ROSES ON WEST SIDE OF STRUCTURE. PROTECT ROSES DURING DEMOLITION AND NEW CONSTRUCTION. COORDINATE WITH NPS (COTR).
 - 8 REMOVE EXISTING WINDOW SASH AND STORE IN PROTECTIVE CONTAINER FOR REUSE AT A LATER DATE IN A SEPARATE FUTURE PROJECT. DELIVER FOR STORAGE WITHIN 1/4 MILE OF THE PROJECT SITE AS DIRECTED BY NPS (COTR).
 - 9 REMOVE EXISTING PLYWOOD COVER AT WINDOW OPENING, EXTERIOR FACE.
 - 10 REMOVE AND DISPOSE OF ENTIRE EXISTING METAL PIPE COLUMN.
 - 11 REMOVE AND DISPOSE OF ENTIRE EXISTING CRICKET, INCLUDING STRUCTURAL FRAMING, OPEN 1x WOOD LATH, AND WOOD SHINGLES.
 - 12 REMOVE AND DISPOSE OF EXISTING SCREEN OR PLYWOOD INFILL AT ROUND WINDOW.

K13 DEMOLITION KEYNOTES


- NOTE:
- # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.
 - 1 INSTALL NEW PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING. SEE H13, SHEET A4.
 - 2 INSTALL NEW STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING WITH DECORATIVE SHINGLE SHAPES. SEE M18, SHEET A4; AND B18, SHEET A4.
 - 3 INSTALL NEW ROLL ROOFING ON TOP OF TOWER. SEE B18, SHEET A5.
 - 4 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AFTER CAREFULLY REMOVING LABELING AND TURNING EXISTING WINDOW SASHES OVER TO COTR. SEE L13, SHEET A2; G18, SHEET A2; AND G13, SHEET A2.
 - 5 NEW TEMPORARY WOOD DOORS INSTALLED BY OTHERS.
 - 6 INSTALL PLYWOOD ENCLOSURE AROUND EXISTING EAVE, SOFFIT, FASCIA, AND TRIM. SEE M18, SHEET A4; AND H18, SHEET A4.
 - 7 INSTALL NEW ROLL ROOFING ON LOW SLOPED ROOF.
 - 8 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AT ROUND WINDOW.
 - 9 INSTALL NEW CRICKET, INCLUDING STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING.

B13 NEW CONSTRUCTION KEYNOTES

NOTE:

STRUCTURAL ENGINEER
WISS, JANNEY, ELSTNER ASSOCIATES, INC.
330 PFINGSTEN ROAD
NORTHBROOK, IL 60062
(847) 272-7400

DESIGNED
J. HANDELAND
DRAWN
M. HANSEN
TECH. REVIEW
DATE: 15 SEPT 2004




B18 CURB DETAIL AT NEW TOWER ROOF
3" = 1'-0"

NOTE: THIS CURB CONDITION OCCURS ONLY AT WEST, NORTH, AND SOUTH SIDES OF TOWER

SUB SHEET NO.
A5

WEST ELEVATION
OLD FIRST BAPTIST CHURCH STABILIZATION
NICODEMUS NATIONAL HISTORIC SITE
NICODEMUS, KANSAS


DRAWING NO.
030
80001
SHEET
6
of 14



J1 NORTH ELEVATION - DEMOLITION

1/4" = 1'-0"

NOTE:



B1 NORTH ELEVATION - NEW CONSTRUCTION

1/4" = 1'-0"

NOTE:

- 1 THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE AN EXISTING ELEMENT OF THE BUILDING IS TO BE REMOVED. REFER TO KEYNOTE NUMERAL FOR A DESCRIPTION OF THE WORK.
- 2 THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE STUCCO IS MISSING OR DELAMINATED AND SHALL BE REMOVED. REPORT EXPOSED MASONRY. SEE DETAIL, II, SHEET 55.

P13 DEMOLITION GENERAL NOTES


- NOTE:
- # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.
 - 1 REMOVE AND DISPOSE OF EXISTING ASPHALT SHINGLES, WOOD SHINGLES, AND 1/2" OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL.
 - 2 REMOVE AND DISPOSE OF EXISTING WOOD SHINGLES AND 1/2" OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. VERIFY EXISTING LAP DIMENSION AT SHINGLES.
 - 3 REMOVE AND DISPOSE OF ENTIRE EXISTING TOWER ROOF, INCLUDING ROLL ROOFING, WOOD SHINGLES, 1/2" OPEN SHINGLE LATH, AND STRUCTURAL FRAMING. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEETS S2 AND S4 FOR ADDITIONAL DESCRIPTION OF WORK. VERIFY LAP DIMENSION, SIZE, SHAPE, AND LAYOUT PATTERN OF WOOD SHINGLES BEFORE REMOVAL.
 - 4 REMOVE AND DISPOSE OF ENTIRE LOW SLOPED ROOF, INCLUDING ROOF FRAMING RAFTERS. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEET S2 FOR ADDITIONAL DESCRIPTION OF WORK.
 - 5 REMOVE EXISTING BRICK CHIMNEY TO BELOW ROOF LINE. SALVAGE AND CLEAN BRICK. PLACE A SHEET OF PLYWOOD ON INTERIOR FLOOR OF BUILDING AND CAREFULLY STACK BRICK ON PLYWOOD FOR FUTURE REUSE.
 - 6 REMOVE AND DISPOSE OF EXISTING VENT PIPE OR FLUE PIPE TO BELOW ROOFLINE.
 - 7 REMOVE AND DISPOSE OF EXISTING TREES, SHRUBS, AND VEGETATION EXCEPT FOR GRASS AND ROSES ON WEST SIDE OF STRUCTURE. PROTECT ROSES DURING DEMOLITION AND NEW CONSTRUCTION. COORDINATE WITH NPS (COTR).
 - 8 REMOVE EXISTING WINDOW SASH AND STORE IN PROTECTIVE CONTAINER FOR REUSE AT A LATER DATE IN A SEPARATE FUTURE PROJECT. DELIVER FOR STORAGE WITHIN 1/4 MILE OF THE PROJECT SITE AS DIRECTED BY NPS (COTR).
 - 9 REMOVE EXISTING PLYWOOD COVER AT WINDOW OPENING, EXTERIOR FACE.
 - 10 REMOVE AND DISPOSE OF ENTIRE EXISTING METAL PIPE COLUMN.
 - 11 REMOVE AND DISPOSE OF ENTIRE EXISTING CRICKET, INCLUDING STRUCTURAL FRAMING, OPEN 1X WOOD LATH, AND WOOD SHINGLES.
 - 12 REMOVE AND DISPOSE OF EXISTING SCREEN OR PLYWOOD INFILL AT ROUND WINDOW.

K13 DEMOLITION KEYNOTES

- NOTE:
- # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.
 - 1 INSTALL NEW PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING. SEE H13, SHEET A4.
 - 2 INSTALL NEW STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING WITH DECORATIVE SHINGLE SHAPES. SEE M18, SHEET A4; AND B18, SHEET A4.
 - 3 INSTALL NEW ROLL ROOFING ON TOP OF TOWER. SEE B18, SHEET A5.
 - 4 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AFTER CAREFULLY REMOVING LABELING AND TURNING EXISTING WINDOW SASHES OVER TO COTR. SEE L13, SHEET A2; G18, SHEET A2; AND G18, SHEET A2.
 - 5 NEW TEMPORARY WOOD DOORS INSTALLED BY OTHERS.
 - 6 INSTALL PLYWOOD ENCLOSURE AROUND EXISTING EAVE, SOFFIT, FASCIA, AND TRIM. SEE M18, SHEET A4; AND H18, SHEET A4.
 - 7 INSTALL NEW ROLL ROOFING ON LOW SLOPED ROOF.
 - 8 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AT ROUND WINDOW.
 - 9 INSTALL NEW CRICKET, INCLUDING STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING.

B13 NEW CONSTRUCTION KEYNOTES

- NOTE:
- DESIGNED: J. HANDELAND
 - DRAWN: M. HANSEN
 - TECH. REVIEW:
 - DATE: 15 SEPT 2004




B18 SECTION AT LOW SLOPED ROOF

3" = 1'-0"

NOTE:

<p>ARCHITECT BAHR VERMEER HAECKER ARCHITECTS 121 SOUTH 13TH STREET, SUITE 200 LINCOLN, NE 68508 (402) 475-4551</p>	<p>STRUCTURAL ENGINEER WISS, JANNEY, ELSTNER ASSOCIATES, INC. 330 PFINGSTEN ROAD NORTHBROOK, IL 60062 (847) 272-7400</p>	<p>DESIGNED J. HANDELAND DRAWN M. HANSEN TECH. REVIEW DATE: 15 SEPT 2004</p>	<p>SUB SHEET NO. A6</p>	<p>NORTH ELEVATION OLD FIRST BAPTIST CHURCH STABILIZATION NICODEMUS NATIONAL HISTORIC SITE NICODEMUS, KANSAS 17</p>	<p>DRAWING NO. 030 80001</p>
					<p>SHEET 7 of 14</p>



J1 EAST ELEVATION - DEMOLITION
1/4" = 1'-0"

NOTE:

- 1 THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE AN EXISTING ELEMENT OF THE BUILDING IS TO BE REMOVED. REFER TO KEYNOTE NUMERAL FOR A DESCRIPTION OF THE WORK.
- 2 THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE STUCCO IS MISSING OR DELAMINATED AND SHALL BE REMOVED. REPORT EXPOSED MASONRY. SEE DETAIL, II, SHEET 55.

P13 DEMOLITION GENERAL NOTES


- NOTE:
- # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.
 - 1 REMOVE AND DISPOSE OF EXISTING ASPHALT SHINGLES, WOOD SHINGLES, AND 1x OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL.
 - 2 REMOVE AND DISPOSE OF EXISTING WOOD SHINGLES AND 1x OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. VERIFY EXISTING LAP DIMENSION AT SHINGLES.
 - 3 REMOVE AND DISPOSE OF ENTIRE EXISTING TOWER ROOF, INCLUDING ROLL ROOFING, WOOD SHINGLES, 1x OPEN SHINGLE LATH, AND STRUCTURAL FRAMING. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEETS S2 AND S4 FOR ADDITIONAL DESCRIPTION OF WORK. VERIFY LAP DIMENSION, SIZE, SHAPE, AND LAYOUT PATTERN OF WOOD SHINGLES BEFORE REMOVAL.
 - 4 REMOVE AND DISPOSE OF ENTIRE LOW SLOPED ROOF, INCLUDING ROOF FRAMING RAFTERS. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEET S2 FOR ADDITIONAL DESCRIPTION OF WORK.
 - 5 REMOVE EXISTING BRICK CHIMNEY TO BELOW ROOF LINE. SALVAGE AND CLEAN BRICK. PLACE A SHEET OF PLYWOOD ON INTERIOR FLOOR OF BUILDING AND CAREFULLY STACK BRICK ON PLYWOOD FOR FUTURE REUSE.
 - 6 REMOVE AND DISPOSE OF EXISTING VENT PIPE OR FLUE PIPE TO BELOW ROOFLINE.
 - 7 REMOVE AND DISPOSE OF EXISTING TREES, SHRUBS, AND VEGETATION EXCEPT FOR GRASS AND ROSES ON WEST SIDE OF STRUCTURE. PROTECT ROSES DURING DEMOLITION AND NEW CONSTRUCTION. COORDINATE WITH NPS (COTR).
 - 8 REMOVE EXISTING WINDOW SASH AND STORE IN PROTECTIVE CONTAINER FOR REUSE AT A LATER DATE IN A SEPARATE FUTURE PROJECT. DELIVER FOR STORAGE WITHIN 1/4 MILE OF THE PROJECT SITE AS DIRECTED BY NPS (COTR).
 - 9 REMOVE EXISTING PLYWOOD COVER AT WINDOW OPENING, EXTERIOR FACE.
 - 10 REMOVE AND DISPOSE OF ENTIRE EXISTING METAL PIPE COLUMN.
 - 11 REMOVE AND DISPOSE OF ENTIRE EXISTING CRICKET, INCLUDING STRUCTURAL FRAMING, OPEN 1x WOOD LATH AND WOOD SHINGLES.
 - 12 REMOVE AND DISPOSE OF EXISTING SCREEN OR PLYWOOD INFILL AT ROUND WINDOW.

K13 DEMOLITION KEYNOTES

- NOTE:
- # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.
 - 1 INSTALL NEW PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING. SEE H13, SHEET A4.
 - 2 INSTALL NEW STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING WITH DECORATIVE SHINGLE SHAPES. SEE M13, SHEET A4; AND B13, SHEET A4.
 - 3 INSTALL NEW ROLL ROOFING ON TOP OF TOWER. SEE B13, SHEET A5.
 - 4 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AFTER CAREFULLY REMOVING, LABELING, AND TURNING EXISTING WINDOW SASHES OVER TO COTR. SEE L13, SHEET A2; G13, SHEET A2; AND G13, SHEET A2.
 - 5 NEW TEMPORARY WOOD DOORS INSTALLED BY OTHERS.
 - 6 INSTALL PLYWOOD ENCLOSURE AROUND EXISTING EAVE, SOFFIT, FASCIA, AND TRIM. SEE M13, SHEET A4; AND H13, SHEET A4.
 - 7 INSTALL NEW ROLL ROOFING ON LOW SLOPED ROOF.
 - 8 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AT ROUND WINDOW.
 - 9 INSTALL NEW CRICKET, INCLUDING STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING.


B13 NEW CONSTRUCTION KEYNOTES

- NOTE:
- ARCHITECT
BAHR VERMEER HAECKER ARCHITECTS
121 SOUTH 13TH STREET, SUITE 200
LINCOLN, NE 68508
(402) 475-4551
 - STRUCTURAL ENGINEER
WISS, JANNEY, ELSTNER ASSOCIATES, INC.
330 PFINGSTEN ROAD
NORTHBROOK, IL 60062
(847) 272-7400
 - DESIGNED
J. HANDELAND
 - DRAWN
M. HANSEN
 - TECH. REVIEW
 - DATE: 15 SEPT 2004




B1 EAST ELEVATION - NEW CONSTRUCTION
1/4" = 1'-0"

NOTE:



A7	SUB SHEET NO.	DRAWING NO.
	8	030
	8	80001
	of 14	SHEET
EAST ELEVATION OLD FIRST BAPTIST CHURCH STABILIZATION NICODEMUS NATIONAL HISTORIC SITE NICODEMUS, KANSAS		



J1 SOUTH ELEVATION - DEMOLITION

1/8" = 1'-0"

NOTE:

- 1 THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE AN EXISTING ELEMENT OF THE BUILDING IS TO BE REMOVED. REFER TO KEYNOTE MATERIAL FOR A DESCRIPTION OF THE WORK.
- 2 THIS SYMBOL SHOWN ON THE DRAWING INDICATES WHERE STUCCO IS MISSING OR DELAMINATED AND SHALL BE REMOVED. REPORT EXPOSED MASONRY. SEE DETAIL, I1, SHEET S5.

P13 DEMOLITION GENERAL NOTES


NOTE:
 # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.

- 1 REMOVE AND DISPOSE OF EXISTING ASPHALT SHINGLES, WOOD SHINGLES, AND 1x OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL.
- 2 REMOVE AND DISPOSE OF EXISTING WOOD SHINGLES AND 1x OPEN SHINGLE LATH. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. VERIFY EXISTING LAP DIMENSION AT SHINGLES.
- 3 REMOVE AND DISPOSE OF ENTIRE EXISTING TOWER ROOF, INCLUDING ROLL ROOFING, WOOD SHINGLES, 1x OPEN SHINGLE LATH, AND STRUCTURAL FRAMING. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEETS S2 AND S4 FOR ADDITIONAL DESCRIPTION OF WORK. VERIFY LAP DIMENSION, SIZE, SHAPE, AND LAYOUT PATTERN OF WOOD SHINGLES BEFORE REMOVAL.
- 4 REMOVE AND DISPOSE OF ENTIRE LOW SLOPED ROOF, INCLUDING ROOF FRAMING RAFTERS. COORDINATE WITH NPS (COTR) FOR POSSIBLE SALVAGE OF MATERIAL. SEE STRUCTURAL SHEET S2 FOR ADDITIONAL DESCRIPTION OF WORK.
- 5 REMOVE EXISTING BRICK CHIMNEY TO BELOW ROOF LINE. SALVAGE AND CLEAN BRICK. PLACE A SHEET OF PLYWOOD ON INTERIOR FLOOR OF BUILDING AND CAREFULLY STACK BRICK ON PLYWOOD FOR FUTURE REUSE.
- 6 REMOVE AND DISPOSE OF EXISTING VENT PIPE OR FLUE PIPE TO BELOW ROOFLINE.
- 7 REMOVE AND DISPOSE OF EXISTING TREES, SHRUBS, AND VEGETATION EXCEPT FOR GRASS AND ROSES ON WEST SIDE OF STRUCTURE. PROTECT ROSES DURING DEMOLITION AND NEW CONSTRUCTION. COORDINATE WITH NPS (COTR).
- 8 REMOVE EXISTING WINDOW SASH AND STORE IN PROTECTIVE CONTAINER FOR REUSE AT A LATER DATE IN A SEPARATE FUTURE PROJECT. DELIVER FOR STORAGE WITHIN 1/4 MILE OF THE PROJECT SITE AS DIRECTED BY NPS (COTR).
- 9 REMOVE EXISTING PLYWOOD COVER AT WINDOW OPENING, EXTERIOR FACE.
- 10 REMOVE AND DISPOSE OF ENTIRE EXISTING METAL PIPE COLUMN.
- 11 REMOVE AND DISPOSE OF ENTIRE EXISTING CRICKET, INCLUDING STRUCTURAL FRAMING, OPEN 1x WOOD LATH, AND WOOD SHINGLES.
- 12 REMOVE AND DISPOSE OF EXISTING SCREEN OR PLYWOOD INFILL AT ROUND WINDOW.

K13 DEMOLITION KEYNOTES

NOTE:
 # THIS SYMBOL AND NUMERAL SHOWN ON THE DRAWING REFER TO KEYNOTES BELOW.


- 1 INSTALL NEW PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING. SEE H13, SHEET A4.
- 2 INSTALL NEW STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING WITH DECORATIVE SHINGLE SHAPES. SEE M18, SHEET A4; AND B18, SHEET A4.
- 3 INSTALL NEW ROLL ROOFING ON TOP OF TOWER. SEE B18, SHEET A5.
- 4 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AFTER CAREFULLY REMOVING LABELING, AND TURNING EXISTING WINDOW SASHES OVER TO COTR. SEE L13, SHEET A2; G18, SHEET A2; AND G18, SHEET A2.
- 5 NEW TEMPORARY WOOD DOORS INSTALLED BY OTHERS.
- 6 INSTALL PLYWOOD ENCLOSURE AROUND EXISTING EAVE, SOFFIT, FASCIA, AND TRIM. SEE M18, SHEET A4; AND H18, SHEET A4.
- 7 INSTALL NEW ROLL ROOFING ON LOW SLOPED ROOF.
- 8 INSTALL NEW VENTED PLYWOOD WINDOW COVERS AT ROUND WINDOW.
- 9 INSTALL NEW CRICKET, INCLUDING STRUCTURAL FRAMING, PLYWOOD SHEATHING, 15" ROOFING FELT, VENTILATION UNDERLAYMENT, AND CEDAR SHINGLE ROOFING.



E18 DETAIL AT ROOF PITCH TRANSITION

3" = 1'-0"

NOTE:



B1 SOUTH ELEVATION - NEW CONSTRUCTION

1/8" = 1'-0"

NOTE:



B13 NEW CONSTRUCTION KEYNOTES

- NOTE:
- | | | |
|--|--|---|
| <p>ARCHITECT
 BAHR VERMEER HAECKER ARCHITECTS
 121 SOUTH 13TH STREET, SUITE 200
 LINCOLN, NE 68508
 (402) 475-4551</p> | <p>STRUCTURAL ENGINEER
 WISS, JANNEY, ELSTNER ASSOCIATES, INC.
 330 PFINGSTEN ROAD
 NORTHBROOK, IL 60062
 (847) 272-7400</p> | <p>DESIGNED
 J. HANDELAND
 DRAWN
 M. HANSEN
 TECH. REVIEW
 DATE: 15 SEPT 2004</p> |
|--|--|---|

SUB SHEET NO.
A8



SOUTH ELEVATION
 OLD FIRST BAPTIST CHURCH STABILIZATION
 NICODEMUS NATIONAL HISTORIC SITE
 NICODEMUS, KANSAS

DRAWING NO.
030
80001
 SHEET
9
 OF 14



G1 EAST ELEVATION
1/4" = 1'-0"
NOTE:



G14 WALL SECTION AT TYPICAL NEW WOOD BRACE
1/2" = 1'-0"
NOTE:




B1 PLAN DETAIL OF NEW WOOD BRACE AT BOTTOM CHORD
3" = 1'-0"
NOTE:

B14 PLAN DETAIL OF UPPER CLIP ANGLES
3" = 1'-0"
NOTE:

ARCHITECT BAHR VERMEER HAECKER ARCHITECTS 121 SOUTH 13TH STREET, SUITE 200 LINCOLN, NE 68508 (402) 475-4551	STRUCTURAL ENGINEER WISS, JANNEY, ELSTNER ASSOCIATES, INC. 330 PFINGSTEN ROAD NORTHBROOK, IL 60062 (847) 272-7400	DESIGNED MLW	SUB SHEET NO. S1	DRAWING NO. 030 80001 SHEET 10 OF 14
		DRAWN JKL/KMI		
		TECH. REVIEW TBB	EAST WALL STABILIZATION OLD FIRST BAPTIST CHURCH STABILIZATION NICODEMUS NATIONAL HISTORIC SITE NICODEMUS, KANSAS	



H14 NORTHWEST LOW SLOPE ROOF - PLAN DETAIL
3/8" = 1'-0" NOTE:



B14 PLYWOOD ROOF SHEATHING NAILING PATTERN
NOT TO SCALE NOTE: TYPICAL FOR ALL NEW PLYWOOD ROOF SHEATHING, 5/8" AND 3/4" THICKNESSES

B1 ROOF FRAMING PLAN
1/4" = 1'-0" NOTE:

ARCHITECT
BAHR VERMEER HAECKER ARCHITECTS
121 SOUTH 13TH STREET, SUITE 200
LINCOLN, NE 68508
(402) 475-4551

STRUCTURAL ENGINEER
WISS, JANNEY, ELSTNER ASSOCIATES, INC.
330 PFINGSTEN ROAD
NORTHBROOK, IL 60062
(847) 272-7400 2003.0016

DESIGNED
MLW

DRAWN
JKL / KMI

TECH. REVIEW
TBB

DATE: 15 SEPT. 2004
REVISED: 1 FEB. 2005

ARCHITECT

STRUCTURAL ENGINEER

DESIGNED
MLW

DRAWN
JKL / KMI











TECH. REVIEW
TBB

DATE: 15 SEPT. 2004
REVISED: 1 FEB. 2005


SUB SHEET NO.
S2

ROOF FRAMING PLANS
OLD FIRST BAPTIST CHURCH STABILIZATION
NICODEMUS NATIONAL HISTORIC SITE
NICODEMUS, KANSAS

DRAWING NO.
030
80001
SHEET
11
OF 14




ARCHITECT BAHR VERMEER HAECKER ARCHITECTS 121 SOUTH 13TH STREET, SUITE 200 LINCOLN, NE 68508 (402) 475-4551	STRUCTURAL ENGINEER WISS, JANNEY, ELSTNER ASSOCIATES, INC. 330 PFINGSTEN ROAD NORTHBROOK, IL 60062 (847) 272-7400	DESIGNED MLW DRAWN JKL/KMI TECH. REVIEW TBB DATE: 15 SEPT. 2004 REVISED: 1 FEB. 2005	SUB SHEET NO. S3	DRAWING NO. 030 80001 SHEET 12 OF 14
RAFTER REPAIRS OLD FIRST BAPTIST CHURCH STABILIZATION NICODEMUS NATIONAL HISTORIC SITE NICODEMUS, KANSAS				



H1 VESTIBULE ROOF - SECTION LOOKING NORTH

1/2" = 1'-0"


NOTE:



J13 VESTIBULE ROOF - CORNER COLUMN DETAILS

1-1/2" = 1'-0"


NOTE:



B1 VESTIBULE ROOF - PLAN AT TOP OF MASONRY

1/2" = 1'-0"

NOTE:




B11 VESTIBULE ROOF - PLAN AT TOP OF MANSARD ROOF


1/2" = 1'-0"

NOTE:


ARCHITECT BAHR VERMEER HAECKER ARCHITECTS 121 SOUTH 13TH STREET, SUITE 200 LINCOLN, NE 68508 (402) 475-4551	STRUCTURAL ENGINEER WISS, JANNEY, ELSTNER ASSOCIATES, INC. 330 PFINGSTEN ROAD NORTHBROOK, IL 60062 (847) 272-7400	DESIGNED MLW	SUB SHEET NO. S4	TOWER ROOF REPAIRS OLD FIRST BAPTIST CHURCH STABILIZATION NICODEMUS NATIONAL HISTORIC SITE NICODEMUS, KANSAS	DRAWING NO. 030 80001 SHEET 13 OF 14
		DRAWN JKL/KMI			




11 TYPICAL REPOINTING DETAILS AT EXPOSED STONE MASONRY
NOTE: TO BE IMPLEMENTED AT ALL EXISTING STONE MASONRY EXPOSED BY STUCCO REMOVAL.



B1 ELEVATION OF INTERIOR SHORING WALL AT EAST WALL OF SANCTUARY
NOTE:



L11 STUCCO CRACK REPAIR
NOTE: TO BE IMPLEMENTED ONLY AT LOCATIONS DESIGNATED BY A/E IN FIELD.



F11 SEALANT DETAIL AT EDGE OF REMOVED STUCCO
NOTE: TO BE IMPLEMENTED WHERE EXISTING STUCCO IS REMOVED.

ARCHITECT BAHR VERMEER HAECKER ARCHITECTS 121 SOUTH 13TH STREET, SUITE 200 LINCOLN, NE 68508 (402) 475-4551	STRUCTURAL ENGINEER WISS, JANNEY, ELSTNER ASSOCIATES, INC. 330 PFINGSTEN ROAD NORTHBROOK, IL 60062 (847) 272-7400 2003.0016	DESIGNED MLW DRAWN JKL / KMI TECH. REVIEW TBB DATE: 15 SEPT. 2004 REVISED: 1 FEB. 2005	SUB SHEET NO. S5	MASONRY AND STUCCO REPAIR OLD FIRST BAPTIST CHURCH STABILIZATION NICODEMUS NATIONAL HISTORIC SITE NICODEMUS, KANSAS	DRAWING NO. 030 80001 SHEET 14 OF 14
---	--	---	----------------------------	--	---