
VII. Appendix

Information Sources

- 2000 "Ventilation Systems Evaluation for Laboratory Facility," ARH Engineering, Inc., Estimate for National Seashore, 1/7/2000.
- 1999 Draft Building Condition Assessment, BH+A Title 1 Facilities Planning Study for the NPS.
- 1995 Building Evaluation and Construction Cost Estimates, NPS Boston Office.
- 1999 Site Plan and Environmental Assessment for the Former North Truro Air Force Station, NPS Cape Cod National Seashore.
- 1995 Historical and Architectural Documentation Reports of North Truro Air Force Station", Tri-Services Cultural Resources Research Center, USACERL, Champlain, Illinois.
- 1995, "Cultural Landscape Inventory", Summary Report, North Truro Air Force Station, Hillary Quarles.
- 1994 Environmental Baseline Survey at NTAFS, Radian Corporation for the US Air Force and Army Corps.

Photographs



Photo 1: View of exterior LBP trim, Building #203.




Photo 2: View of LBP bowling gutters, Building #15.

Photographs



Photo 3: View of suspect creosote utility poles, LBP exterior eave and window casings, Building #22.

Photographs



Photo 4: View of LBP-coated interior wall, ticket office, Building #22.

Photographs



Photo 5: View of LBP-coated exterior eve, Building #14.




Photo 6: View of LBP-coated exterior eve (asbestos material), Building #36.

Photographs




Photo 7: View of liquid mercury thermostat ampule, Building #203.



Photo 8: View of miscellaneous OHM, Building #37.

Photographs



Photo 9: View of miscellaneous OHM, Flammables closet, Building #36.

Photographs




Photo 10: View of miscellaneous OHM, Supplies closet, Building #36.

Photographs




Photo 11: View of CFC-containing refrigerators, Building #17.




Photo 12: View of cases of scouring powder, Building #17.

Photographs




Photo 13: View of LBP-coated ASTs, handrails and floor debris, Building #31.




Photo 14: View of LBP-coated diesel fuel ASTs, ladder support and yellow crane beams, Building #31.

Photographs




Photo 15: View of emergency diesel generator, Building #31.




Photo 16: View of electric turbine engine, Building #31.

Photographs



Photo 17: View of multiple layers of asbestos floor tile, Building #22.




Photo 18: View of multiple layers of asbestos floor tile, Building #16.

Photographs




Photo 19: View of LBP-coated sheet rock walls, Building #14.




Photo 20: View of asbestos sheet rock/joint compound walls, Building #203.

Photographs




Photo 21: View of asbestos linoleum and sheet rock/joint compound walls, Building #203.




Photo 22: View of LBP-coated sheet rock walls, Dining Room, Building #18.