


Update on the Independence Hall Tower Restoration Project



Carpenter installing wood shake roof



Woodcrafter restoring a Level wood bracket



Many repairs have been over the years to the Level 3 south window. It has been disassembled and incompatible repairs will be removed and the window restored.



Most of Level 5 cladding has been removed. This has revealed the wood framing of the clock face.



The Level 2 round windows have been disassembled and each member is being reviewed to see what work is required to conserve the window.



A close inspection of the carved pilaster capitals after paint removal has revealed that they will need to be



Construction team is checking the match of handmade bricks to the existing masonry.



The mason submitted mortar samples in the tubes that were rejected. They were grayer than the original mortar used to construct the tower.