RESTORATION OF UNDESIGNATED VEHICLE ROUTES (UVRs)

Department of Interior Lands in Western Pima County, Arizona Bureau of Land Management Ajo Block (BLM) Cabeza Prieta National Wildlife Refuge (CPNWR) Organ Pipe Cactus National Monument (OPCNM)

FINAL PROGRESS REPORT

REPORTING PERIOD: June 8 – June 26, 2015


	NIOD. Julie 8 – Julie 20, 2013	Lond			No. of Miles
Week starting	Crew(s)	Land Manager	Zone	No. of UVRs	restored
			Totals as of May 15	226	183.1
06/08/2015	NAC Construction	OPCNM	F, G	32	6.4
06/15/2015	NAC Construction	OPCNM	G, A	20	3.9
06/22/2015	NAC Construction	OPCNM	Α	1	3.8
Reporting period totals				53	14.1
Totals to Date				279	197.2

Accomplishments

- NAC Construction returned a week ahead of schedule arriving the week of June 8 to complete the restoration of the remaining routes.
- NAC completed the remaining routes in Zone F, all of the routes in Zone G and the newly mapped routes in Zone A.
- The additional routes in Zone A were mapped and culturally surveyed during the time NAC was not working on the project. NPS coordinated with Border Patrol to identify additional UVRs to be restored.
- NAC completed their last UVR restoration on Wednesday, June 24, 2015. With the completion of this
 route, the field portion of their contract is now complete. NAC did not continue on to restore routes in
 Zone H because they completed the number of miles to be restored as specified in their contract.
- NAC Construction began restoration on February 4 and concluded June 24, 2015. The completion of this
 segment of the restoration effort is the culmination of a five year effort. All parties involved are to be
 congratulated on their contribution towards the successful completion of this project.

Upcoming

- Restoration will continue as the OPCNM restoration crew works on the vertical mulching of routes in Zones F, G and A and the restoration of the remaining routes along the northwest boundary of the park in Zone H.
- OPCNM will coordinate with the Saguaro Trail Crew and the Lake Mead Exotic Plant Management Team to schedule their assistance with continuing restoration work.



Restored UVR in Zone F



SOVA-2014-0002AE_010_20150512 - Post mechanical treatment



SOVA-2014-0002AE_010_20150512 - Post vertical and horizontal mulching