Figure 6 - 18. Repair the Perimeter Sentry Walk and all extant features from the Wharf to Stores/QM Warehouse. Remove non-contributing (GSA and newer) fencing. (c 1960) (source: Parks Conservancy); (Sally Port GOGA 18352.100.tif, P1030446.JPG)

Figure 6 - 19. Repair historic features of Sentry Perimeter Walk from Wharf to Stores/QM Warehouse and GSA fencing. Remove non-historic gate and fencing. Allow year round access to Post Exchange. Allow seasonal access from Post Exchange to Stores/QM Warehouse (c 2010) (source: MBD); (DSC_0068.JPG, DSC_0072.JPG, DSC_0098.JPG)

Figure 6 - 20. Repair the extant historic features of the Perimeter Sentry Walk; top, (c 1960s) (source: J Martini); (photo006.jpg); bottom, (c 2009) (source: MBD); (IMG_2801.JPG)

Figure 6 - 21. Repair the extant historic features of the Perimeter Sentry Walk. Allow year round visitor access from the Dock Tower to Post Exchange and seasonal access from Post Exchange to Stores/QM Warehouse; top, (c 1960s) (source: J Martini); (photo007.jpg); bottom, (c 2009) (source: MBD); (P1010016.JPG)



Figure 6 - 22. Maintain extant historic features of the Perimeter Sentry Walk along northeast shoreline. Allow only operations access north of Stores/QM Warehouse. Restore 'Alcatraz' sign on Stores/QM Warehouse (c 1930) (source: GOGA); (1930_1 (GOGA).jpg)



Figure 6 - 23. Maintain extant historic features of the Perimeter Sentry Walk on shoreline including fencing (MBSF15) and entanglements. (c Federal Penitentiary period 1934 - 1963) (source: GOGA); (AZ industrial buildings(GOGA).jpg)



Figure 6 - 24. Maintain extant historic features, including topography, trails and steps, of the Perimeter Sentry Walk. Allow only operations access north of Stores/QM Warehouse to Model Industries. (c 1930) (source: Parks Conservancy); (1930_1)

Figure 6 - 25. Maintain topography, entanglements, and path northeast of Model Industries. (c2010) (source: MBD); (P1030543.JPG , DSC_0200.JPG)

Figure 6 - 26. Maintain wall, seawall, path, and slope. Allow plantings that provide dual value habitat and retain the historic character of low mounding shrubs and perennials (c 2010) (MBD); (DSC_0113.JPG)

Figure 6 - 27. Maintain recesses of wooden boardwalk from the Perimeter Sentry Walk. (c 2009) (source: MBD); (DSC02947.JPG)

Figure 6 - 28. Remove *Eucalyptus* trees, stabilize slope and plant with new *Eucalyptus* species. Manage trees to produce straight vigorous trees and consider tree topping as was done historically by the U.S. Army. (source: MBD); (P1040237.JPG)

Figure 6 - 29. top. Sun bathers on south Shoreline, top (c 1957) (source: GOGA); (GOGA 18237-006 Sunbathing on Alcatraz ca-1957-61.tif); Existing south shoreline: bottom (c 2009) (source: MBD); (P1040237.JPG)