

Staten Island



MILLER FIELD


Relocation of Hurricane Sandy Damaged Maintenance Facilities to More Sustainable Locations within the Staten Island Unit



Miller Field Options Considered

Option	Description	Status
1	Constructing new maintenance facility at a location of recently developed Temporary maintenance facility while also incorporating recently renovated garage structure along northern boundary.	Being evaluated by NPS and A/E Team
2	Constructing new maintenance facility at a location in very close proximity to and incorporating the recently renovated garage structure along northern boundary.	Being evaluated by NPS and A/E Team
3	Constructing new maintenance facility at a location in very close proximity to and incorporating the recently renovated garage structure along northern boundary.	Dismissed due to impact of natural resources and proximity to 100 year flood elevation
4a	Constructing new maintenance facility at a location near parking lot #2 (NPS-owned).	Being evaluated by NPS and A/E Team
4b	Constructing new maintenance facility at a location near New Dorp Lane and with access to parking lot #1 (NPS-owned).	Being evaluated by NPS and A/E Team
5	Constructing new maintenance facility at a location at or near Hanger 38.	Dismissed due to site being below 100 year flood elevation
6	Constructing new maintenance facility at a location near parking lot #2 (NPS-owned).	Dismissed due to impact to Natural and Cultural Resources - community garden.


Lower Bay





MILLER FIELD – DESIGN CONCEPT LAYOUTS

New Site Options – Design Concept #4a



View from NPS parking lot #2 to the NE




View towards SW from existing NPS parking lot #2

NOTE: Approximately **1-acre** would be needed to construct a facility to store equipment, perform small equipment repairs, and provide office space and parking for staff at Miller Field.



MILLER FIELD – DESIGN CONCEPT LAYOUTS

New Site Options – Design Concept #4b



View towards SE from existing NPS parking lot #1



View of site option #4 from the southern edge looking north

NOTE: The yellow dashed line represents the 4.4 acre project area. It does not represent the footprint of the approximately 1 acre maintenance facility or the entire area that will be disturbed. The exact location of the maintenance facility, within this overall larger project area, will require further analysis.

NOTE: Approximately **1-acre** would be needed to construct a facility to store equipment, perform small equipment repairs, and provide office space and parking for staff at Miller Field.