





# Parade Ground and Summit South Terrace Treatment Recommendations

Figure 6-2













# Main Road - East Treatment Recommendations


Figure 6-4









**Figure 6 - 5.** Concept sketch of Main Road and Perimeter Sentry Walk. Stabilize building walls and veranda of the Post Exchange, and add interior floor decking for visitor access. Allow year round access on Perimeter Sentry Walk from Wharf to Post Exchange.




**Figure 6 - 6.** Concept sketch of Parade Ground, view towards Apartment C. Re-configure rubble mounds to reveal extant building walls and foundations. Stabilize building walls, rubble mounds and plantings. Maintain interior rubble as habitat for Black-crowned Night Heron and secure rubble to eliminate any access for visitor safety. Repair all extant contributing features: lights, curbs, sidewalks, Seawall Planter, building and site walls, and plantings to reflect historic character of the Federal Penitentiary period.



**Figure 6 - 7.** Concept sketch of the Parade Ground, view towards Officers' Quarters – Duplex remnants (Building 83). Restore historic plantings in top of Seawall Planter and add plantings in area in front of Seawall Planter to reflect historic character and to deter visitor access to wall.



**Figure 6 - 8.** Concept sketch of Parade Ground. Allow year round visitor access. Repair Officers' Quarters 72 – 75 building foundations and foundation walls. Add decking and railings at first floor of Quarters 72 and 73 for visitor access. Repair escarpment slope.



**Figure 6 - 9.** Concept sketch of Main Road - West showing the restoration of the Road Tower and Catwalk to the Stockade/Recreation Yard. Restore the guard station fencing; and catwalks of the Stockade/Recreation Yard. Repair the West Lawn - North, historic hillside plantings on upper slopes, and pedestrian lights. Maintain the perennial borders of the West Lawn. Maintain existing vegetation for Snowy Egret habitat.



**Figure 6 - 10.** Concept sketch of Main Road - West. Maintain existing vegetation for Snowy Egret habitat at the West Lawn - South and allow for a new tipi structure to be built so it is visible. No visitor access to the Tipi site is allowed.




**Figure 6 - 11.** Concept sketch of Utility Chase and Walk from Powerhouse to Main Prison. Stabilize walk and railing and repair sections that are fully deteriorated. Restore the vertical structure of the guard tower and stabilize extant footings. Allow seasonal visitor access. Stabilize slope and add low understory planting as dual habitat areas that do not obscure views.




**Figure 6 - 12.** Concept sketch of Main Prison Plaza looking towards San Francisco. Remove pedestrian light on east side of staircase. Remove non-contributing railings at edge and restore historic concrete decorative railing, and repair extant wall at Summit edge.




**Figure 6 - 13.** Concept sketch of Warden's House interior. Add decking on main level and stabilize building foundations and walls to allow for visitor access.



**Figure 6 - 14.** Concept sketch of Wharf. Remove amphitheater and restore Federal Penitentiary period security fencing and wall. Repair garden terraces, staircase, and railings and stabilize buttresses. Allow year-round visitor access to Parade Ground via extant staircase.



**Figure 6 - 15.** Concept sketch of Main Road through the Guardhouse Complex, looking north. Remove Wooden Boathouse Addition and restore Guardhouse Complex to Early Military Prison period.



**Figure 6 - 16.** Concept sketch of Parade Ground. Encourage archeological excavations. Clean up rubble mounds to reveal extant building foundations and walls. Maintain rubble mounds for Black-crowned Night Heron habitat. Restore residential character including lights, curbs, sidewalks, Seawall Planter, walls, and landscape to Federal Penitentiary period.



**Figure 6 - 17.** Concept sketch of Windy Gulch Trail. Restore staircase decorative concrete railings and walk to Federal Penitentiary period. Allow year round visitor access and add railings to walkway below staircase to deter visitor access into protected areas. Maintain vegetation for Black-crowned Night Heron habitat.