



**FP2: REMOVE GATE**

**FP4: REPLACE TREES IN PARKING AREA**

**BSS5: REINSTATE TRAIL TO WEST SULPHUR**

**BSS4: PROVIDE ADA ACCESS TO WALKWAY**

**DMG: DARKEN WHITE CONCRETE PATH**

**BSS1a: PRESERVE PAVILION**

**BSS1b: REHABILITATE PAVILION PLANTINGS**

**FP3: IMPROVE DAVIS AVE FRONTAGE**

**FP1: RESTORE 1940 POOL EDGES**

**FP1: RESTORE DAMS, STREAM EDGES TO 1940 (TYP.)**

**FP8: DEVELOP LIGHTING PLAN FOR FLOWER PARK**

**BSS2: REHABILITATE FOUNTAIN**

**BSS3b: REGULARLY CLEAR SAND TO IMPROVE BEACH**

**BSS3a: STABILIZE/REPAIR CAUSEWAY**

**FP10: REHABILITATE MAIN GATE**

**FP5: REHABILITATE VEGETATION AROUND PATHS & STAIRS (REMOVE DENSE CEDARS)**

**DMG: STABILIZE TREAD SURFACES**

**FP4: REPLACE SHADE TREES THROUGHOUT FLOWER PARK**

**FP1: RESTORE 1940 POOL EDGES**

**FP6: REPLACE CONCRETE SIPHON/MANHOLE COVERS (TYP.) (LONG TERM)**

**FP7: REMOVE 2 NON-HISTORIC REUNION POSTS**

**PLATT DISTRICT**  
 Chickasaw National Recreation Area  
 Cultural Landscape Report  
 Iowa State University, Landscape Architecture Department  
 8/31/02

