





622 $1\frac{1}{2}$ P. Doz.



595 $2\frac{1}{2}$ P. Doz.



565 $7\frac{1}{2}$ Ea

All Union Joints of various sizes
may be had at the small end
if required at proportionate
prices

This end may
be screw'd various
sizes

for $\frac{1}{2}$ in. iron pipe

This Pattern may be had a
Size less, say for $\frac{1}{2}$ in. $\$ 66$


$\$ 6$ Ea



This Cock
may be screw'd
with a rough
himal For small iron
Pipe if required

694

$\frac{1}{2}$ in at both ends 432 $1\frac{1}{2}$ P. Doz
 $\frac{3}{4}$ " " " 833 " "
 $\frac{1}{2}$ " " " 834 " "



577 $2\frac{1}{2}$ P. Doz.

$\frac{1}{2}$ in to $\frac{3}{4}$ in $7\frac{1}{2}$ P. Doz
 $\frac{1}{2}$ in to $\frac{3}{4}$ in 1329

A Connecting Joint may be had to any of the Gas Cocks