
METERS
4000
3000
2000
1000
0
FEET
10,000
5000
0
UTAH
WYOMING
Restored gradient of Gilbert Peak erosion surface projected from Little Mountain (before faulting)
1590 m
Little Hole
1280 m
Goslin Mountain
60°
790 m
Surface eroded from this area
Present Gilbert Peak surface
300 m
Heave or extension
500 m
Heave or extension
DUTCH JOHN FAULT
175 m
UINTA FAULT
Precambrian rocks
Mesozoic and Tertiary rocks
0
2
4 KILOMETERS
0
1
2 MILES