



B16: REPLACE LETTERING ON ENTRY PIERS

B18: REPLACE NON HISTORIC DOORS & WINDOWS

B17: REMOVE NON HISTORIC FEATURES

B3: STABILIZE BANK AT CAUSEWAY STEPS

B4: REPLACE ANCIENT RIVERS SIGN

B2: REMOVE CONCRETE BLOCK PUMPHOUSE

B7: ENSURE ADA ACCESS AT TERRACE

B11: REPLACE COTTONWOOD

B10: REHABILITATE LILY POND

B9: RESTORE MINERAL WATER AT PAVILION

B8: RESTORE SEMICIRCULAR BENCH

B19: INSTALL GRATES ON TRAIL DRAINS

B20: PROVIDE ADA ACCESS AT BROMIDE OVERLOOK

B22: MAINTAIN PRAIRIE AREA

B9: RESTORE MINERAL WATER AT PAVILION

B1: CONSTRUCT NEW PICNIC SHELTER

B20: GRADE ACCESS RAMP FROM PARKING AREA

B15: MAINTAIN FLAGSTONE

B12: REHABILITATE 12TH ST. FOUNTAIN

B14: REPLACE COPING

B13: RESTORE DRINKING FOUNTAINS

B5: REMOVE CULVERT

B21: REPLANT TREES

PLATT DISTRICT
 Chickasaw National Recreation Area
 Cultural Landscape Report
 Iowa State University, Landscape Architecture Department
 Date 10/7/2002

