



United States Department of the Interior

NATIONAL PARK SERVICE

Yosemite National Park

P.O. Box 577

Yosemite, California 95389

Safety Closure- Hazardous Rockfall Area

On December 12, 2009, a rock fall occurred on the Wapama -Rancheria Falls Trail, damaging the trail and covering an approximately 150 yard section with trees and debris. In order to maintain the safety of park visitors and allow the repairs of the trail to be completed, the Superintendent of Yosemite National Park is designating the area as closed. The area will be closed until repairs are completed or further notice is given.

By order of the Superintendent of Yosemite National Park and under authority of Title 36, Code of Federal Regulations, Section 1.5(a) and Section (a)(1):

The portion of the trail between the drainage west of Teeulala Falls and the east side of the bridges at Wapama Falls is closed for public safety until repairs are completed or further notice given.

Notice of closure will be posted and area will be monitored to ensure compliance. Your cooperation in complying with this temporary restriction is greatly appreciated.

The designation will remain in place until rescinded.


David V. Oberuaga
Acting Superintendent


Date



Rockfall near Wapama Falls
119°46'6.7"W
37°57'46.4"N

Trail closure (until further notice)

RESERVOIR

HETCHY
Elevation 3797

Kiliana
Rock



PJD
December 19, 2009
1534 Hours

1:15,000