

Grant-Kohrs Ranch National Historic Site

Deer Lodge, Montana

CULTURAL LANDSCAPE REPORT

Part One

*Landscape History, Existing Conditions,
and Analysis and Evaluation*

July 2004



GRANT-KOHR'S RANCH
NATIONAL HISTORIC SITE
DEER LODGE, MONTANA

Cultural Landscape Report

Part One

*Landscape History, Existing Conditions,
and Analysis and Evaluation*

Contract No. C2000981500
Task Order 2000981569

Prepared for
National Park Service
Grant-Kohrs Ranch NHS
Deer Lodge, Montana

Prepared by

John Milner Associates, Inc.
Charlottesville, Virginia

Rivanna Archaeological Consulting
Charlottesville, Virginia

In association with
Susan Maxman & Partners Architects
Philadelphia, Pennsylvania

July 2004

Superintendent of Grant-Kohrs Ranch
National Historic Site

Date

Director, Intermountain Region

Date

Cover image: "View of ranch and cattle from northwest," circa 1940. Grant-Kohrs Ranch National Historic Site archives. Catalog no. GRKO 6833. Color rendering by JMA, 2003.

CREDITS

National Park Service

Intermountain Region, Denver Support Office

Ed Tafoya, Contracting Officer
Tom Keohan, Cultural Landscape Architect

Intermountain Regional Office, Santa Fe, New Mexico

Jill Cowley, Project COTR

Grant-Kohrs Ranch National Historic Site

Darlene Koontz, Superintendent

Ben Bobowski, Natural Resource Specialist

Chris Ford, Curator

Peggy Gow, Museum Technician

Jesse Harris, Rancher

Mike McWright, Facility Manager

Lynel Meikle, Interpretive Ranger

John Milner Associates, Inc.

Rob McGinnis, ASLA, Project Director

Krista Schneider, ASLA, Project Manager/ Landscape Architect

Matthew Whitaker, Project Designer

Julie Basic, Project Designer

Alisa Hefner, Project Designer

Amy Wells, Graphic Designer

Corkey Goldsmith, Editor

Rivanna Archaeological Consulting

Dr. Benjamin Ford, Historian

Susan Maxman & Partners Architects

Jane Rath, Contract Administrator

TABLE OF CONTENTS

Chapter One: Introduction

Management Summary.....	1-1
Historical Summary.....	1-1
Administrative Context	1-2
Scope of Work/Methodology Overview.....	1-5
Project Scope	1-5
Project Methodology	1-7
Study Boundaries.....	1-11
Summary of Findings.....	1-11
Description of Component Landscapes.....	1-13

Chapter Two: Landscape Physical History

Introduction.....	2-1
Narrative and Chronology	
Period I: PaleoIndian Period ca. 11,000 – 8,000 before present (BP)...	2-2
Period II: Archaic Period, ca. 8,000 to 1,500 BP.....	2-5
Period III: Late Prehistoric Period, ca. 1,500 BP to 1700.....	2-10
Period IV: Pend d'Oreille, Flathead, and the early European occupation of Western Montana, ca. 1700 – 1860.....	2-14
Period V: The Establishment of the Johnny Grant Ranch, the Settlement of Cottonwood, and incipient stock raising, 1860-1866.....	2-21
Period VI: The Conrad Kohrs Home Ranch and the Growth and Development of the Ranching Industry on the Northern Plains, 1866-1887.....	2-31
Period VII: The Decline of the Open Range and Dissolution of the Kohrs-Bielenberg Ranch, 1877-1922.....	2-45
Period VIII: The Conrad K. Warren Era: Rebuilding the Ranch and the application of scientific advances in veterinary medicine, breeding, feed, crops and mechanical systems, 1922-1940.....	2-57
Period IX: The Warren Hereford Ranch, 1940-1958.....	2-72
Period X: Post-Dispersal and efforts to establish a National Park, 1958-1972.....	2-82
Period XI: The National Park Service and early conservation efforts, 1972-1988	2-87
Period XII: Acquisition of the Con Warren Ranch, 1988-2002.....	2-99
Animal/Breed Table.....	2-107
Crop/Produce Table.....	2-111
Field/Pasture Table.....	2-114
Water System Table	2-116

Chapter Three: Existing Conditions Documentation

Grant-Kohrs Ranch National Historic Site

Introduction.....	3-1
Overview of Existing Conditions.....	3-2
Natural Systems and Features.....	3-4
Vegetation	3-5
Spatial Organization.....	3-6
Land Uses	3-6
Constructed Water Features.....	3-10
Circulation.....	3-11
Views and Vistas.....	3-12
Buildings and Structures.....	3-13
Objects and Small-scale Features.....	3-13
Archeological & Missing Resources.....	3-14

Component Landscapes

Home Ranch Complex

Introduction.....	3-1-1
Natural Systems and Features.....	3-1-1
Vegetation	3-1-1
Spatial Organization.....	3-1-2
Land Uses	3-1-4
Constructed Water Features.....	3-1-4
Circulation.....	3-1-5
Views and Vistas.....	3-1-5
Buildings and Structures.....	3-1-6
Objects and Small-scale Features.....	3-1-13
Missing & Archeological Resources.....	3-1-14

East Feed Lot/Warren Hereford Ranch

Introduction.....	3-2-1
Natural Systems and Features.....	3-2-1
Vegetation	3-2-1
Spatial Organization.....	3-2-1
Land Uses	3-2-2
Constructed Water Features.....	3-2-3
Circulation.....	3-2-3
Views and Vistas.....	3-2-3
Buildings and Structures.....	3-2-4
Objects and Small-scale Features.....	3-2-6
Missing & Archeological Resources.....	3-2-8

Grant-Kohrs Residence

Introduction.....	3-3-1
Natural Systems and Features.....	3-3-1
Vegetation	3-3-1
Spatial Organization.....	3-3-2
Land Uses	3-3-3

Constructed Water Features.....	3-3-3
Circulation.....	3-3-3
Views and Vistas.....	3-3-4
Buildings and Structures.....	3-3-5
Objects and Small-scale Features.....	3-3-6
Missing & Archeological Resources.....	3-3-7
<i>Warren Residence</i>	
Introduction.....	3-4-1
Natural Systems and Features.....	3-4-1
Vegetation.....	3-4-1
Spatial Organization.....	3-4-2
Land Uses.....	3-4-2
Constructed Water Features.....	3-4-3
Circulation.....	3-4-3
Views and Vistas.....	3-4-3
Buildings and Structures.....	3-4-3
Objects and Small-scale Features.....	3-4-5
Missing & Archeological Resources.....	3-4-6
<i>Pasture/Hay Field</i>	
Introduction.....	3-5-1
Natural Systems and Features.....	3-5-1
Vegetation.....	3-5-1
Spatial Organization.....	3-5-2
Land Uses.....	3-5-4
Constructed Water Features.....	3-5-4
Circulation.....	3-5-6
Views and Vistas.....	3-5-6
Buildings and Structures.....	3-5-7
Objects and Small-scale Features.....	3-5-7
Missing & Archeological Resources.....	3-5-8
<i>Upland Pasture</i>	
Introduction.....	3-6-1
Natural Systems and Features.....	3-6-1
Vegetation.....	3-6-1
Spatial Organization.....	3-6-2
Land Uses.....	3-6-3
Constructed Water Features.....	3-6-3
Circulation.....	3-6-3
Views and Vistas.....	3-6-4
Buildings and Structures.....	3-6-4
Objects and Small-scale Features.....	3-6-4
Missing & Archeological Resources.....	3-6-5
<i>Riparian Woodland</i>	
Introduction.....	3-7-1
Natural Systems and Features.....	3-7-1
Vegetation.....	3-7-1
Spatial Organization.....	3-7-2

Land Uses	3-7-3
Constructed Water Features.....	3-7-5
Circulation.....	3-7-5
Views and Vistas.....	3-7-5
Buildings and Structures.....	3-7-6
Objects and Small-scale Features.....	3-7-6
Missing & Archeological Resources.....	3-7-8
 <i>Railroad Corridor & Barrow Pit/Wetland</i>	
Introduction.....	3-8-1
Natural Systems and Features.....	3-8-1
Vegetation	3-8-2
Spatial Organization.....	3-8-3
Land Uses	3-8-3
Constructed Water Features.....	3-8-4
Circulation.....	3-8-4
Views and Vistas.....	3-8-4
Buildings and Structures.....	3-8-4
Objects and Small-scale Features.....	3-8-5
Missing & Archeological Resources.....	3-8-6
 <i>Development Zone</i>	
Introduction.....	3-9-1
Natural Systems and Features.....	3-9-1
Vegetation	3-9-1
Spatial Organization.....	3-9-1
Land Uses	3-9-2
Constructed Water Features.....	3-9-2
Circulation.....	3-9-2
Views and Vistas.....	3-9-2
Buildings and Structures.....	3-9-2
Objects and Small-scale Features.....	3-9-3
Missing & Archeological Resources	3-9-5

Chapter 4: Landscape Analysis and Evaluation

Introduction.....	4-1
Summary of Previous Evaluations of Significance.....	4-1
Evaluation of Significance by Criteria	
Significance by National Historic Landmark Criteria.....	4-3
Significance by National Register Criteria.....	4-5
Period of Significance.....	4-15

Comparative Analysis of Historic and Existing Conditions by Landscape Characteristics

Introduction..... 4-17
 Natural Systems and Features..... 4-18
 Vegetation 4-19
 Spatial Organization..... 4-22
 Land Uses 4-24
 Constructed Water Features..... 4-26
 Circulation..... 4-28
 Views and Vistas..... 4-30
 Buildings and Structures..... 4-32
 Objects and Small-scale Features..... 4-36
 Missing Features..... 4-37

Inventory Table of Existing Conditions and Contributing Resources

Home Ranch 4-40
 East Feed Lot/Warren Hereford Ranch 4-44
 Grant-Kohrs Residence..... 4-47
 Warren Residence 4-51
 Pasture/Hay Fields 4-54
 Upland Pasture..... 4-58
 Riparian Woodland..... 4-61
 Railroad Corridor & Barrow Pit/Wetland..... 4-63
 Development Zone..... 4-66

Integrity Assessment

Introduction..... 4-69
 Grant-Kohrs Ranch National Historic Site 4-72
 Home Ranch..... 4-73
 East Feed Lot/Warren Hereford Ranch..... 4-74
 Grant-Kohrs Residence..... 4-75
 Warren Residence..... 4-75
 Pasture/Hay Fields..... 4-76
 Upland Pasture..... 4-77
 Riparian Woodland..... 4-77
 Railroad Corridor & Barrow Pit/Wetland..... 4-78
 Development Zone..... 4-78

References..... R-1

List of Figures

Chapter 1

Figure 1-1: Extent of lands owned, leased, or available, 1866-1982.....	1-14
Figure 1-2: Study Area	1-15
Figure 1-3: Land Ownership.....	1-16

Chapter 2

Figure 2-1 : Hot Spring Mound in “Deer Lodge” 1855-1860	2-117
Figure 2-2 : Residence of John Grant 1865.....	2-118
Figure 2-3 : Residence of John Grant, purchased by Hon. Conrad Kohrs 1866...	2-119
Figure 2-4 : Detail of 1869 Survey T8N, R9W.....	2-120
Figure 2-5 : Detail, Deer Lodge City, Montana 1881	2-121
Figure 2-6 : Bird’s Eye View of Deer Lodge 1883	2-122
Figure 2-7 : Grant-Kohrs ranch house 1884	2-123
Figure 2-8 : Detail of Deer Lodge Valley vicinity, Montana 1891	2-124
Figure 2-9 : Front yard of Grant Kohrs Ranch House circa 1900	2-125
Figure 2-10 : Area in front of Grant Kohrs Ranch House circa 1900	2-126
Figure 2-11 : William Kohrs Memorial Library Dedication 1903	2-127
Figure 2-12 : Front yard of Grant Kohrs Ranch House 1904	2-128
Figure 2-13 : John Bielenberg and Gehrman boys 1904	2-129
Figure 2-14 : Robert and Anna Warren among whitewashed tree trunks 1908 ...	2-130
Figure 2-15 : Sweet Peas on trellis, circa 1910’s	2-131
Figure 2-16 : Lower Ranch Yard circa 1900.....	2-132
Figure 2-17 : General view of ranch circa.....	2-133
Figure 2-18 : Rear yard of Grant Kohrs Ranch House circa 1890	2-134
Figure 2-19 : Putting up hay with a beaver slide circa 1910	2-135
Figure 2-20 : Partial Map of Deer Lodge Townsite 1907	2-136
Figure 2-21 : Kohrs Ranch 1904. Drawn from Memory in 1974	2-137
Figure 2-22 : Threshing hay, Ben Goldie’s thresher, 1938	2-138
Figure 2-23 : Ben Goldie’s thresher, Conrad Warren watching, 1938	2-139
Figure 2-24 : Threshing grain, Conrad Warren watching, 1938	2-140
Figure 2-25 : Threshing grain, Ben Goldie’s thresher, 1938	2-141
Figure 2-26 : Threshing hay, Ben Goldie’s thresher, 1938	2-142
Figure 2-27 : Front view of Grant Kohrs Ranch House circa 1910	2-143
Figure 2-28 : Side of Grant Kohrs Ranch House, conservatory circa 1915	2-144
Figure 2-29 : Auntie in drive, Anna Kohrs Boardman, no date, possibly 1925 ..	2-145
Figure 2-30 : Augusta Kohrs in the garden watering plants, circa 1930	2-146
Figure 2-31 : Feed Bunker (HS-52), circa 1940	2-147
Figure 2-32 : Feed Bunker (HS-52), circa 1940	2-148
Figure 2-33 : Three horse team and moldboard plow, circa 1935	2-149
Figure 2-34 : Feeding Belgians and Herefords south of HS-58, possibly 1935 ...	2-150
Figure 2-35 : Unknown Structure in Lower House Yard, 1937.....	2-151
Figure 2-36 : CK Show wagon, probably at Great Falls, circa 1938	2-152
Figure 2-37 : CK Show wagon, probably at Great Falls, circa 1938	2-153
Figure 2-38 : Cattle at feeding bunker, circa 1937	2-154
Figure 2-39 : Conrad Warren branding cattle, 1937	2-155
Figure 2-40 : Conrad Warren and cattle feeding, 1937	2-156
Figure 2-41 : Conrad Warren with calves in corral, circa 1937	2-157
Figure 2-42 : Nellie Warren in front of Warren House foundation 1934	2-158

Figure 2-43 : Construction of new Warren residence with Nell Warren, 1934 ...	2-159
Figure 2-44 : Warren residence, 1934	2-160
Figure 2-45 : Warren residence, 1934	2-161
Figure 2-46 : Warren residence, 1934	2-162
Figure 2-47 : Pat Warren in yard (HS-58), ca. 1937	2-163
Figure 2-48 : Pat Warren in yard (HS-58) with trellis in background, ca. 1937 ..	2-164
Figure 2-49 : Pat Warren in yard (HS-58) showing landscaped area, ca. 1938 ..	2-165
Figure 2-50 : Pat Warren in yard with sweet pea trellis in background, 1938	2-166
Figure 2-51 : Pat Warren in yard with dog house in background, 1939	2-167
Figure 2-52 : Pat and Bud Warren in yard, ca. 1942	2-168
Figure 2-53 : Pat Warren in yard behind house (HS-58) with swing, ca. 1942....	2-169
Figure 2-54 : Garden south side of Grant Kohrs Ranch House, possibly 1935...	2-170
Figure 2-55 : Grant Kohrs Ranch House with fence and trees, possibly 1936 ...	2-171
Figure 2-56 : Grant Kohrs Ranch, circa 1937	2-172
Figure 2-57 : Lower House Yard, 1937.....	2-173
Figure 2-58 : General view of ranch from the east, circa 1938	2-174
Figure 2-59 : Jack Peters with Grant Kohrs Ranch House in background, 1938 .	2-175
Figure 2-60 : Conrad Warren in lower yard with horse team, 1938	2-176
Figure 2-61 : Haying on the west side, circa 1937	2-177
Figure 2-62 : Haying on the west side, circa 1937	2-178
Figure 2-63 : Grain stacks North West Little Meadow, circa 1937	2-179
Figure 2-64 : Jayhawk Overshot Hay Stacker, 1938	2-180
Figure 2-65 : Conrad Warren on Sin, circa 1940	2-181
Figure 2-66 : Stallion Barn, circa 1940	2-182
Figure 2-67 : Herefords in pasture, north of Warren Ranch, circa 1945	2-183
Figure 2-68 : High place looking west, circa 1950	2-184
Figure 2-69 : View of ranch and cattle from northwest, circa 1940	2-185
Figure 2-70 : Warren Ranch House, 1947	2-186
Figure 2-71 : Warren House, 1947.....	2-187
Figure 2-72 : Grant Kohrs Ranch House and Bunkhouse Row, circa 1945	2-188
Figure 2-73 : Southwest view of Grant Kohrs Ranch House, possibly 1952	2-189
Figure 2-74 : Entry lane south of Bull Barns, no date	2-190
Figure 2-75 : Warren Hereford Ranch sign and barn, 1952	2-191
Figure 2-76 : Picket fence behind Warren House (HS-58), ca. 1953	2-192
Figure 2-77 : Birdbath and clothesline in Warren yard, 1964	2-193
Figure 2-78 : Mt. Powell, Deer Lodge Valley, possibly 1955	2-194
Figure 2-79 : Historical Base Map 1958-1971	2-195
Figure 2-80 : Driveway approaching Grant Kohrs Ranch House, 1972	2-196
Figure 2-81 : Grant Kohrs Ranch House, no date	2-197
Figure 2-82 : Front yard of Grant Kohrs Ranch House, no date.....	2-198
Figure 2-83 : Aerial view of Grant Kohrs Ranch, October 1974	2-199
Figure 2-84 : Aerial view of Deer Lodge Valley, October 1974	2-200
Figure 2-85 : Aerial view of Grant Kohrs Ranch, October 1974	2-201
Figure 2-86 : Aerial view of Grant Kohrs Ranch, October 1974	2-202
Figure 2-87 : Aerial view of Grant Kohrs Ranch, October 1974	2-203
Figure 2-88 : Aerial view of Grant Kohrs Ranch, October 1974	2-204
Figure 2-89 : Aerial view of Grant Kohrs Ranch, October 1974	2-205
Figure 2-90 : Aerial view of Grant Kohrs Ranch, October 1974	2-206
Figure 2-91 : Aerial view of Grant Kohrs Ranch, October 1974	2-207
Figure 2-92 : Aerial view of Grant Kohrs Ranch, October 1974	2-208
Figure 2-93 : Aerial view of Grant Kohrs Ranch, October 1974	2-209

Figure 2-94 : Perspective view of Grant Kohrs Ranch, October 1974	2-210
Figure 2-95 : Perspective view of the west corrals, October 1974	2-211
Figure 2-96 : Perspective view of west yard and outbuildings, October 1974	2-212
Figure 2-97 : Grant Kohrs Ranch House looking east, 1985	2-213
Figure 2-98 : Grant Kohrs Ranch looking toward rear of ice house, 1985	2-214
Figure 2-99 : Farm equipment, 1985	2-215
Figure 2-100 : Cattle in corral near sales barn, circa 1972-1988	2-216
Figure 2-101 : Aerial of Grant Kohrs Ranch, circa 1947	2-217
Figure 2-102 : Detail of aerial view of Grant Kohrs Ranch, circa 1947	2-218
Figure 2-103 : Aerial view of Grant Kohrs Ranch, 1960	2-219
Figure 2-104 : Detail of aerial view of Grant Kohrs Ranch, 1960	2-220
Figure 2-105 : Aerial view of Grant Kohrs Ranch, 1972	2-221
Figure 2-106 : Detail of aerial view of Grant Kohrs Ranch, 1972	2-222
Figure 2-107: Aerial view of Grant Kohrs Ranch, 1979	2-223
Figure 2-108 : Detail of aerial view of Grant Kohrs Ranch, 1979	2-224
Figure 2-109 : Aerial view of Grant Kohrs Ranch, 1983	2-225
Figure 2-110 : Detail of aerial view of Grant Kohrs Ranch, 1983	2-226
Figure 2-111 : Aerial view of Grant Kohrs Ranch, 1986	2-227
Figure 2-112 : Detail of aerial view of Grant Kohrs Ranch, 1986	2-228
Figure 2-113 : Aerial view of Grant Kohrs Ranch, 1994	2-229
Figure 2-114 : Detail of aerial view of Grant Kohrs Ranch, 1994	2-230
Figure 2-115 : Aerial view of Grant Kohrs Ranch, 1994	2-231
Figure 2-116 : Aerial view of Grant Kohrs Ranch, circa 1994	2-232

Chapter 4

Figure 4-1: Rear yard of Grant Kohrs Ranch House, circa 1890	4-79
Figure 4-1: Rear yard of Grant Kohrs Ranch House, 2002	4-79
Figure 4-3: Lower Ranch Yard circa 1900.....	4-80
Figure 4-4: View of Lower Ranch Yard, 2002.....	4-80
Figure 4-5: General view of ranch, circa 1900.....	4-81
Figure 4-6: View of Ranch from similar vantage point, 2002.....	4-81
Figure 4-7: Area in front of Grant Kohrs Ranch House, circa 1900.....	4-82
Figure 4-8: Front of Grant Kohrs Ranch House, 2002.....	4-82
Figure 4-9: Anna Kohrs Boardman in drive, possibly 1925.....	4-83
Figure 4-10: View of Bunkhouse Row from similar vantage point, 2002.....	4-83
Figure 4-11: Warren House, 1934.....	4-84
Figure 4-12: Warren Residence from similar vantage point, 2002.....	4-84
Figure 4-13: Garden south side of Grant Kohrs Ranch House, possibly 1935....	4-85
Figure 4-14: View of house from similar vantage point, 2002.....	4-85
Figure 4-15: General view of ranch from the east, circa 1938.....	4-86
Figure 4-16: View of ranch from the east from similar vantage point, 2002.....	4-86
Figure 4-17: Conrad Warren on Sin, circa 1940.....	4-87
Figure 4-18: View of Lower Yards from similar vantage point, 2002.....	4-87
Figure 4-19: Stallion Barn, circa 1940.....	4-88
Figure 4-20: Stallion Barn from similar vantage point, 2002.....	4-88
Figure 4-21: Conrad Warren with calves in corral, circa 1940.....	4-89
Figure 4-22: View of corral from similar vantage point, 2002.....	4-89
Figure 4-23: Warren Ranch House, circa 1945.....	4-90
Figure 4-24: Warren Residence from similar vantage point, 2002.....	4-90
Figure 4-25: Herefords in pasture, north of Warren Ranch, circa 1945.....	4-91
Figure 4-26: View of Pasture, from similar vantage point, 2002.....	4-91

Figure 4-27: Grant Kohrs Ranch House and Bunkhouse Row, circa 1945.....	4-92
Figure 4-28: Front of Grant-Kohrs Ranch House, 2002.....	4-92
Figure 4-29: Cattle in corral near sales barn, possibly 1952.....	4-93
Figure 4-30: View of corral near sales barn, 2002.....	4-93
Figure 4-31: Warren Hereford Ranch sign and barn, 1952.....	4-94
Figure 4-32: View of pasture and barn, 2002.....	4-94

List of Maps

Chapter 2

Period Plans

Circa 1865.....	H-1
Circa 1895.....	H-2
Circa 1920.....	H-3
Circa 1955.....	H-4
Circa 1982.....	H-5
Circa 2003	H-6

Chapter 3

Map 3-1: Component Landscapes.....	3-15
Map 3-2: Vicinity Map.....	3-16
Map 3-3: Location Map.....	3-17
Map 3-4: Regional Geology.....	3-18
Map 3-5: Soils.....	3-19
Map 3-6: Topography and Water Features.....	3-20
Map 3-7: Vegetation	3-21
Map 3-8: Land Use	3-22
Map 3-9: Constructed Water Features	3-23
Map 3-10: Circulation	3-24

Home Ranch

Photo Station Point Map, 1 of 3.....	P-1
Photo Station Point Map, 2 of 3.....	P-2
Photo Station Point Map, 3 of 3	P-3
Existing Conditions.....	EC-1
Existing Conditions.....	EC-2
Existing Conditions.....	EC-3
Existing Conditions.....	EC-4
Existing Conditions.....	EC-5
Existing Conditions.....	EC-6
Existing Conditions.....	EC-7

East Feed Lot/Warren Hereford Ranch

Photo Station Point Map.....	P-4
Existing Conditions.....	EC-8
Existing Conditions.....	EC-9
Existing Conditions.....	EC-10

Grant-Kohrs Residence

Photo Station Point Map.....	P-5
Existing Conditions.....	EC-11
Existing Conditions.....	EC-12
Existing Conditions.....	EC-13
Existing Conditions.....	EC-14

Warren Residence

Photo Station Point Map.....	P-6
Existing Conditions.....	EC-15
Existing Conditions.....	EC-16
Existing Conditions.....	EC-17
Existing Conditions.....	EC-18

Pasture/Hay Fields

Map P-7: Photo Station Point Map.....	P-7
Existing Conditions.....	EC-19
Existing Conditions.....	EC-20
Existing Conditions.....	EC-21
Existing Conditions.....	EC-22
Existing Conditions.....	EC-23
Existing Conditions.....	EC-24
Existing Conditions.....	EC-25
Existing Conditions.....	EC-26
Existing Conditions.....	EC-27
Existing Conditions.....	EC-28

Upland Pasture

Photo Station Point Map.....	P-8
Existing Conditions.....	EC-29
Existing Conditions.....	EC-30
Existing Conditions.....	EC-31
Existing Conditions.....	EC-32

Riparian Woodland

Photo Station Point Map.....	P-9
Existing Conditions.....	EC-33
Existing Conditions.....	EC-34
Existing Conditions.....	EC-35
Existing Conditions.....	EC-36
Existing Conditions.....	EC-37

Railroad Corridor & Barrow Pit/Wetland

Photo Station Point Map.....	P-10
Existing Conditions.....	EC-38
Existing Conditions.....	EC-39
Existing Conditions.....	EC-40

Visitor Center Complex

Photo Station Point Map.....	P-11
Existing Conditions.....	EC-41
Existing Conditions.....	EC-42
Existing Conditions.....	EC-43

Chapter 4

Home Ranch Comparative Photo Station Points.....	P-12
Warren Hereford Ranch Comparative Photo Station Points.....	P-13

List of Photos

Chapter 3

Photo 3-1: Flint Creek Range and the peaks of Mt. Powell	3-25
Photo 3-2: Views to the east of the Ranch	3-25
Photo 3-3: Cattle and horses at the Ranch	3-26

Home Ranch

Photo 3-1-1: Johnson Creek within the Grant-Kohrs Ranch.....	3-1-18
Photo 3-1-2: Willows and cottonwoods along the Johnson Creek.....	3-1-18
Photo 3-1-3: The Home Ranch landscape.....	3-1-19
Photo 3-1-4: Structures within the home ranch complex.....	3-1-19
Photo 3-1-5: The Lower House Yard currently used for education.....	3-1-20
Photo 3-1-6: A trailer located to the west of the thoroughbred barn	3-1-20
Photo 3-1-7: The Kohrs-Manning Ditch	3-1-21
Photo 3-1-8: The Kohrs-Manning Ditch crosses Johnson Creek.....	3-1-21
Photo 3-1-9: Dairy Loop Road.....	3-1-22
Photo 3-1-10: Bunkhouse Road.....	3-1-22
Photo 3-1-11: Johnson Creek Road.....	3-1-23
Photo 3-1-12: Clark Fork River Bridge Road.....	3-1-23
Photo 3-1-13: Kohrs-Manning Ditch Road	3-1-24
Photo 3-1-14: Warren Pumphouse Road.....	3-1-24
Photo 3-1-15: Buildings and fences within the Home Ranch	3-1-25
Photo 3-1-16: Western foothills and the Flint Creek Mountain Range.....	3-1-25
Photo 3-1-17: Ice House (HS-5).....	3-1-26
Photo 3-1-18: Coal shed (HS-4).....	3-1-26
Photo 3-1-19: Blacksmith Shop/Garage (HS-3).....	3-1-27
Photo 3-1-20: Granary/Roller Mill (HS-6).....	3-1-27
Photo 3-1-21: Draft Horse Barn (HS-7)	3-1-28
Photo 3-1-22: Privy (HS-8)	3-1-28
Photo 3-1-23: Dairy (HS-9).....	3-1-29
Photo 3-1-24: Oxen Barn (HS-10).....	3-1-29
Photo 3-1-25: Bielenberg Barn (HS-11).....	3-1-30
Photo 3-1-26: Cattle Scale (HS-35).....	3-1-30
Photo 3-1-27: Feed Rack (HS-37).....	3-1-31
Photo 3-1-28: Manure Pit (HS-39).....	3-1-31
Photo 3-1-29: Beef Hoist (HS-40) and Simple Rail and Post Fence.....	3-1-32
Photo 3-1-30: Machine Shed (HS-12).....	3-1-32
Photo 3-1-31: Cow Shed in distance (HS-13).....	3-1-33

Photo 3-1-32: Squeeze Chute (HS-41).....	3-1-33
Photo 3-1-33: Thoroughbred Barn (HS-15).....	3-1-34
Photo 3-1-34: Stallion Barn (HS-14).....	3-1-34
Photo 3-1-35: Stallion Barn (HS-16).....	3-1-35
Photo 3-1-36: Stallion Barn (HS-19).....	3-1-35
Photo 3-1-37: Stallion Barn (HS-30).....	3-1-36
Photo 3-1-38: Feed Rack (HS-43).....	3-1-36
Photo 3-1-39: Feed Bunk (HS-46).....	3-1-37
Photo 3-1-40: Feed Storage House (HS-31).....	3-1-37
Photo 3-1-41: Squeeze Chute (HS-47).....	3-1-38
Photo 3-1-42: Buggy Shed (HS-17).....	3-1-38
Photo 3-1-43: Privy (HS-20).....	3-1-39
Photo 3-1-44: Granary (HS-18).....	3-1-39
Photo 3-1-45: Brooding House (HS-21).....	3-1-40
Photo 3-1-46: Chicken Coop (HS-22).....	3-1-40
Photo 3-1-47: Metal Granary (HS-23).....	3-1-41
Photo 3-1-48: Stock Shelter (HS-29).....	3-1-41
Photo 3-1-49: West Corrals Stock Shelter (HS-25).....	3-1-42
Photo 3-1-50: West Corrals Storage Structure (HS-26).....	3-1-42
Photo 3-1-51: Feed Storage House (HS-28).....	3-1-43
Photo 3-1-52: Feed bunk (HS-48).....	3-1-43
Photo 3-1-53: Kohrs-Manning Ditch Bridge (HS-55)	3-1-44
Photo 3-1-54: West Feedlot Stock Shelter (HS-32).....	3-1-44
Photo 3-1-55: West Feedlot Storage Shed (HS-34).....	3-1-45
Photo 3-1-56: West Feedlot Squeeze Chute (HS-53).....	3-1-45
Photo 3-1-57: West Feedlot Feed Bunk (HS-52).....	3-1-46
Photo 3-1-58: Jack-leg fence	3-1-46
Photo 3-1-59: Vertical Board Fence behind feed bunk.....	3-1-47
Photo 3-1-60: 5-rail stacked end fence.....	3-1-47
Photo 3-1-61: Chicken wire fence.....	3-1-48
Photo 3-1-62: Chicken wire gates.....	3-1-48
Photo 3-1-63: Stacked Log Fence.....	3-1-49
Photo 3-1-64: Typical Overhead Gate	3-1-49
Photo 3-1-65: Typical Red Wood Gate.....	3-1-50
Photo 3-1-66: Typical 5-Rail Braced Gate.....	3-1-50
Photo 3-1-67: Vertical Board Gate with Jack-Leg Fence.....	3-1-51

East Feed Lot/Warren Hereford Ranch

Photo 3-2-1: Warren-Hereford Ranch topography	3-2-9
Photo 3-2-2: Pasture grasses vegetation	3-2-9
Photo 3-2-3: The feed lot corral complex	3-2-10
Photo 3-2-4: One corral contains a squeeze chute and feed rack.....	3-2-10
Photo 3-2-5: Northwest corral in feed lot complex.....	3-2-11
Photo 3-2-6: Four smaller corrals	3-2-11
Photo 3-2-7: The "Whiskey" pasture, now used for NPS parking.....	3-2-12
Photo 3-2-8: Area immediately surrounding the garage/shop.....	3-2-12
Photo 3-2-9: The "boneyard," currently serves as a storage area.....	3-2-13
Photo 3-2-10: "Ritchie Fountains," heated water troughs.....	3-2-13
Photo 3-2-11: Main Entry Road.....	3-2-14
Photo 3-2-12: Kohrs-Warren Lane.....	3-2-14
Photo 3-2-13: Gravel parking area.....	3-2-15

Photo 3-2-14: Warren Barn (HS-64).....	3-2-15
Photo 3-2-15: Squeeze chute behind double gates.....	3-2-16
Photo 3-2-16: Feed Rack (HS-68).....	3-2-16
Photo 3-2-17: Metal squeeze chute.....	3-2-17
Photo 3-2-18: Sales Barn (HS-65).....	3-2-17
Photo 3-2-19: Resource Building/Office (HS-003).....	3-2-18
Photo 3-2-20: Scale House (HS-66).....	3-2-18
Photo 3-2-21: Loading Chute (HS-69).....	3-2-19
Photo 3-2-22: Typical Cow Shed (HS-76).....	3-2-19
Photo 3-2-23: Typical Feed House (HS-83).....	3-2-20
Photo 3-2-24: 5-Rail Locked-End Fence.....	3-2-20
Photo 3-2-25: Plank and Post Fence.....	3-2-21
Photo 3-2-26: Flat Rail and Post Fence.....	3-2-21
Photo 3-2-27: Woven Wire Fence (hog-wire).....	3-2-22
Photo 3-2-28: Metal Pipe Fence and Gates.....	3-2-22
Photo 3-2-29: Complex system of fences and gates	3-2-23
Photo 3-2-30: Complex system of fences and gates	3-2-23
Photo 3-2-31: Typical Overhead Bar Gate with Red Wood Gate.....	3-2-24
Photo 3-2-32: Overhead Bar Gate with 5-Rail Braced Gate.....	3-2-24
Photo 3-2-33: Hitching Post.....	3-2-25
Photo 3-2-34: Wooden Trough.....	3-2-25

Grant-Kohrs Residence

Photo 3-3-1: The Grant-Kohrs residence is located along the “bench”.....	3-3-9
Photo 3-3-2: The front lawn is dominated by newly planted cottonwoods	3-3-9
Photo 3-3-3: A large black willow occupies the north lawn of the house.....	3-3-10
Photo 3-3-4: A diverse cluster of trees and shrubs in the lower garden.....	3-3-10
Photo 3-3-5: Vegetation along the slope	3-3-11
Photo 3-3-6: An asphalt sidewalk to the Visitor Center.....	3-3-11
Photo 3-3-7: A wood plank walk leads to the front porch of the residence.....	3-3-12
Photo 3-3-8: A brick walk from the northeast corner of the Grant house.....	3-3-12
Photo 3-3-9: Flagstone walkway in the lower garden.....	3-3-13
Photo 3-3-10: Wide stone staircase on north side of house.....	3-3-13
Photo 3-3-11: A narrow stone staircase with a wooden handrail.....	3-3-14
Photo 3-3-12: Wooden stairs located on the west side of the porch.....	3-3-14
Photo 3-3-13: Bunkhouse Road.....	3-3-15
Photo 3-3-14: The Main Residence has a T-shaped footprint.....	3-3-15
Photo 3-3-15: The 1890 brick Kohrs addition forms the perpendicular post.....	3-3-16
Photo 3-3-16: A large porch is located on the south elevation.....	3-3-16
Photo 3-3-17: White picket fence under construction.....	3-3-17
Photo 3-3-18: White picket fence along south edge of the lower garden.....	3-3-17
Photo 3-3-19: Wire mesh gate.....	3-3-18
Photo 3-3-20: Wooden benches.....	3-3-18
Photo 3-3-21: Fire hydrant, fire box, pipe, and utility cover and trash barrel.....	3-3-19
Photo 3-3-22: Wooden raised bed frames and trellises in lower garden.....	3-3-19
Photo 3-3-23: Antique wheelbarrow.....	3-3-20
Photo 3-3-24: Utility meters on the western side of the residence.....	3-3-20
Photo 3-3-25: Wood cellar covers.....	3-3-21

Warren Residence

Photo 3-4-1: Native cottonwoods dominate the narrow riparian zone.....	3-4-8
Photo 3-4-2: The Warren domestic landscape.....	3-4-8
Photo 3-4-3: East Field.....	3-4-9
Photo 3-4-4: Chicken Coop Field.....	3-4-9
Photo 3-4-5: West Field.....	3-4-10
Photo 3-4-6: Stuart Pasture.....	3-4-10
Photo 3-4-7: Metal culvert, Stuart Pasture Road, and Magpie Trap.....	3-4-11
Photo 3-4-8: Kohrs-Warren Lane, looking east.....	3-4-11
Photo 3-4-9: Warren Residence (HS-58).....	3-4-12
Photo 3-4-10: Warren Garage (HS-61).....	3-4-12
Photo 3-4-11: Warren Residence Pump House (HS-88).....	3-4-13
Photo 3-4-12: Chicken Coop (HS-59).....	3-4-13
Photo 3-4-13: Boat House (HS-60).....	3-4-14
Photo 3-4-14: Picket Fence and Picket Single Gate.....	3-4-14
Photo 3-4-15: Electrical fence along outside of picket fence.....	3-4-15
Photo 3-4-16: Picket fence and Picket Double Gate.....	3-4-15
Photo 3-4-17: Wire Mesh Gate.....	3-4-16
Photo 3-4-18: Red Wood Gate.....	3-4-16
Photo 3-4-19: Jack-Leg Fence.....	3-4-17
Photo 3-4-20: Fire hydrant.....	3-4-17
Photo 3-4-21: Concrete foundation and metal burn barrel.....	3-4-18
Photo 3-4-22: Clothes line and concrete bird bath.....	3-4-18
Photo 3-4-23: Stepping stones along front of house.....	3-4-19
Photo 3-4-24: Concrete Trough.....	3-4-19
Photo 3-4-25: Remnant concrete granary foundations.....	3-4-20

Pasture/Hay Fields

Photo 3-5-1: An unnamed gulch feeds into the Kohrs-Manning Ditch.....	3-5-9
Photo 3-5-2: Non-native vegetation in fields and riparian zone.....	3-5-9
Photo 3-5-3: Stuart Field in the distance.....	3-5-10
Photo 3-5-4: North Meadows.....	3-5-10
Photo 3-5-5: The Kohrs "Big" Ditch.....	3-5-11
Photo 3-5-6: Typical Wooden Headgate with Wooden Distribution Gate.....	3-5-11
Photo 3-5-7: Typical Concrete Headgate.....	3-5-12
Photo 3-5-8: Distribution Gate.....	3-5-12
Photo 3-5-9: Exposed Culvert.....	3-5-13
Photo 3-5-10: Kohrs Ditch Road.....	3-5-13
Photo 3-5-11: Erosion at end of unnamed gulch ranch.....	3-5-14
Photo 3-5-12: Erosion at end of unnamed gulch.....	3-5-14
Photo 3-5-13: Sewage Treatment Service Road.....	3-5-15
Photo 3-5-14: Jensen Hay Stacker and Wood Post and Wire Fence.....	3-5-15
Photo 3-5-15: Jack-Leg Fence with Overhead Gates.....	3-5-16
Photo 3-5-16: Metal Post and Wire Fence and Metal Pipe Gate.....	3-5-16
Photo 3-5-17: Metal Pipe and Mesh Gate.....	3-5-17
Photo 3-5-18: Ruins of frame structure.....	3-5-17

Upland Pasture

Photo 3-6-1: Much of the dry upland pasture has been used for grazing.....	3-6-6
Photo 3-6-2: A cluster of mature apple trees at the old Kading homestead.....	3-6-6

Photo 3-6-3: Row of cottonwoods along Taylor Creek.....	3-6-7
Photo 3-6-4: Big Gulch.....	3-6-7
Photo 3-6-5: Little Gulch with views toward ranch.....	3-6-8
Photo 3-6-6: Taylor Fields.....	3-6-8
Photo 3-6-7: Westside Ditch.....	3-6-9
Photo 3-6-8: The Upland Pasture dirt/grass roads.....	3-6-9
Photo 3-6-9: Kohrs “Big” Ditch Road.....	3-6-10
Photo 3-6-10: Views of Hillcrest Cemetery.....	3-6-10
Photo 3-6-11: Electric Fence.....	3-6-11
Photo 3-6-12: 5-Rail Locked-End Fence.....	3-6-11
Photo 3-6-13: Wire Gate.....	3-6-12
Photo 3-6-14: Mining excavations.....	3-6-12
Photo 3-6-15: Pig Farm Foundations.....	3-6-13
Photo 3-6-16: Dump site.....	3-6-13

Riparian Woodland

Photo 3-7-1: Clark Fork River with views of ranch in background.....	3-7-9
Photo 3-7-2: Three natural springs source a 300 foot long slough.....	3-7-9
Photo 3-7-3: Cottonwood Creek.....	3-7-10
Photo 3-7-4: Vegetation and remnant fencing along Clark Fork River.....	3-7-10
Photo 3-7-5: Cattails in the abandoned sewage lagoon.....	3-7-11
Photo 3-7-6: Riparian vegetation variation.....	3-7-11
Photo 3-7-7: Slickens.....	3-7-12
Photo 3-7-8: Cottonwood trail.....	3-7-12
Photo 3-7-9: Clark Fork River Bridge Road with Jack-Leg Fencing	3-7-13
Photo 3-7-10: Slough Bridge (HS-90).....	3-7-13
Photo 3-7-11: Clark Fork Bridge (HS-89).....	3-7-14
Photo 3-7-12: Pumphouse (HS-87).....	3-7-14
Photo 3-7-13: Metal post and barbed wire fence along Clark Fork River.....	3-7-15
Photo 3-7-14: Wood Post and Woven Wire Fence.....	3-7-15
Photo 3-7-15: Double Rail and Post Fence.....	3-7-16
Photo 3-7-16: Metal Post and Woven Wire Fence.....	3-7-16
Photo 3-7-17: 5-Rail Braced Gate.....	3-7-17
Photo 3-7-18: Drum.....	3-7-17
Photo 3-7-19: Health Warning Signs.....	3-7-18
Photo 3-7-20: Wooden signs.....	3-7-18
Photo 3-7-21: Wood post along interpretive trail.....	3-7-19
Photo 3-7-22: Wooden bench along Johnson Creek.....	3-7-19

Railroad Corridor & Barrow Pit/Wetland

Photo 3-8-1: The railroad beds are elevated above grade	3-8-7
Photo 3-8-2: The Northern Pacific Railroad bed.....	3-8-7
Photo 3-8-3: The barrow pits are deep pits lower in elevation.....	3-8-8
Photo 3-8-4: Wetland conditions are found within the barrow pits.....	3-8-8
Photo 3-8-5: A concentration of native grasses.....	3-8-9
Photo 3-8-6: Vegetation found within the barrow pits.....	3-8-9
Photo 3-8-7: Vegetation along the rail corridors create “tunnel” views.....	3-8-10
Photo 3-8-8: The Milwaukee Railroad bed was constructed in 1908.....	3-8-10
Photo 3-8-9: Crossing along the Sewage Treatment Service Road.....	3-8-11
Photo 3-8-10: Siphon (HS-57).....	3-8-11
Photo 3-8-11: Pumphouse (HS-86).....	3-8-12

Photo 3-8-12: Cattle Cars.....	3-8-12
Photo 3-8-13: Railroad trestle above pedestrian underpass.....	3-8-13
Photo 3-8-14: 4-Rail Stacked End Fence with Metal Pipe Gate.....	3-8-13
Photo 3-8-15: 4-1/2 Rail Braced Gate.....	3-8-14
Photo 3-8-16: 4-Rail Locked End Gate with Galvanized Gate	3-8-14
Photo 3-8-17: Overhead utility lines.....	3-8-15
Photo 3-8-18: Utility boxes with wheel flange detector.....	3-8-15

Development Zone

Photo 3-9-1: Johnson Creek riparian zone within Visitor Center area.....	3-9-6
Photo 3-9-2: Visitor Entry Drive off Business Loop 90.....	3-9-6
Photo 3-9-3: Visitor Parking Area.....	3-9-7
Photo 3-9-4: Grass traffic islands with flagpole and grain wagon.....	3-9-7
Photo 3-9-5: Curation Storage Facility, access drive, and parking area.....	3-9-8
Photo 3-9-6: Asphalt sidewalk and fire hydrant.....	3-9-8
Photo 3-9-7: Pedestrian walk continues under railroad trestle.....	3-9-9
Photo 3-9-8: Visitor Center (002) and trash barrels.....	3-9-9
Photo 3-9-9: Rest rooms (001) and trash cans.....	3-9-10
Photo 3-9-10: Overhead Gate with 5-Rail Braced Gate.....	3-9-10
Photo 3-9-11: Square Wood Post and Beam sign.....	3-9-11
Photo 3-9-12: Mounted Information Kiosk.....	3-9-11
Photo 3-9-13: Large Interpretive Sign.....	3-9-12
Photo 3-9-14: Small informational signs.....	3-9-12
Photo 3-9-15: Wayfinding Signs.....	3-9-13
Photo 3-9-16: Metal plaque and wood bench.....	3-9-13
Photo 3-9-17: Fire box and dumpster.....	3-9-14
Photo 3-9-18: Antenna pole, utility structure and picnic table.....	3-9-14