


A black and white photograph of a river scene. In the foreground, a boat is docked at a wooden pier. The river flows from the left towards the right. In the background, there are several buildings. One large building has "CUSHWADE" written on its roof. Another building has "BUILDERS COAL SUPPLIES" written on its side. There are trees on the left bank and a hillside in the distance.

**Captain
Myers
Bad Day**




Conococheague Aqueduct watered with boat and mules before 1920 breach



Conococheague Aqueduct 1920 breach water pouring over side



Conococheague Aqueduct Breach 1920 with Captain Myers boat in creek



Captain Myers boat in Conococheague Creek water pouring over side



Boats in dry canal after breach 1920 (note Railroad Lift Bridge in background)



Conococheague Aqueduct empty after breach – Rebuilding the wall with timber