



Source: PWA 2004

Figure 2-1
Alternative 1 - No Project Alternative
Year 0




Source: PWA 2004


Note: Location of cross section is shown in Figure 2-1



Source: PWA 2006




Source: PWA 2006



NOTE: The channel shown is over-simplified for purposes of this illustration. The channel bed would be expected to be irregular after installation of large woody debris to create channel features, such as deep pools.

Source: PWA 2006



Source: PWA 2005