

Figure 2-13 **Public Access Alternative B2**






Figure 2-14 Public Access Alternative B3




Note: Shown with older version of Restoration Alternative 2

Figure 2-15 **Public Access Alternative B4** Shown with Alternative 2 – Creek Restoration



Note: Shown with older version of Alternative 3

Figure 2-16 **Public Access Alternative B5**



 THIS FIGURE DEPICTS POST-CONSTRUCTION TOPOGRAPHY (YEAR 1) AND NEAR-TERM (YEAR 5) HABITAT CONDITIONS. 2. THIS TURN-AROUND AND HANDICAPPED PARTKING WOULD BE BUILT AS PART OF THIS PROJECT.

Note: Shown with older version of Alternative 4

Figure 2-17 Public Access Alternative C




Figure 2-18 Bridge Alternatives