

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
CONTINUATION SHEET**

Section _____ Page _____

=====

SUPPLEMENTARY LISTING RECORD

NRIS Reference Number: 88003438

Date Accepted: 8/23/2013


Weber Stake Relief Society Building
Property Name

Weber
County

UT
State

Mormon Church Buildings in Utah MPS
Multiple Name

This property is listed in the National Register of Historic Places in accordance with the attached nomination documentation subject to the following exceptions, exclusions, or amendments, notwithstanding the National Park Service certification included in the nomination documentation.



Signature of the Keeper

8/23/2013

Date of Action

Amended Items in Nomination:

Property Name:

The box for Related Multiple Property Listing should read *Mormon Church Buildings in Utah MPS*, as the original 1989 listing was submitted under the MPS cover.

Significance:


Criteria Consideration A (Religious Property) should also be checked as in the original nomination.

Criterion C is incorrectly marked on page 7 and should be removed. While the building may be eligible under this Criterion, the additional documentation does not provide a corresponding area of significance for Criterion C, nor does it provide any justification or historic context for architectural significance.

These clarifications were confirmed with the UT SHPO office.

DISTRIBUTION:

- National Register property file
- Nominating Authority (without nomination attachment)



Weber Stake Relief Society Hall
Name of Property
United States Department of the Interior
National Park Service

Weber Co., UT
County and State

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations for individual properties and districts. See instructions in National Register Bulletin, *How to Complete the National Register of Historic Places Registration Form*. If any item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions.

1. Name of Property

Historic name: Weber Stake Relief Society Building (amendment, additional documentation)

Other names/site number: Weber County Daughters of the Utah Pioneers Relic Hall Museum

Name of related multiple property listing:

(Enter "N/A" if property is not part of a multiple property listing)

2. Location

Street & number: 2104 Lincoln Avenue

City or town: Ogden State: UT County: Weber

Not For Publication: Vicinity:

3. State/Federal Agency Certification

As the designated authority under the National Historic Preservation Act, as amended,

I hereby certify that this X nomination ___ request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set forth in 36 CFR Part 60.

In my opinion, the property X meets ___ does not meet the National Register Criteria. I recommend that this property be considered significant at the following level(s) of significance:

___ national ___ statewide X local

Applicable National Register Criteria:

X A ___ B ___ C ___ D

	<u>07/01/13</u>
Signature of certifying official/Title:	Date
<u>Utah Division of State History/Office of Historic Preservation</u>	
State or Federal agency/bureau or Tribal Government	

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

In my opinion, the property ___ meets ___ does not meet the National Register criteria.


Signature of commenting official: **Date**

Title : **State or Federal agency/bureau
or Tribal Government**

4. National Park Service Certification

I hereby certify that this property is:

- entered in the National Register
 determined eligible for the National Register
 determined not eligible for the National Register
 removed from the National Register
 other (explain:) _____


Signature of the Keeper

5/23/2013
Date of Action

5. Classification

Ownership of Property

(Check as many boxes as apply.)

- Private:
- Public – Local
- Public – State
- Public – Federal

Category of Property

(Check only one box.)

- Building(s)
- District
- Site

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

Structure

Object

Number of Resources within Property

(Do not include previously listed resources in the count)

Contributing	Noncontributing	
<u>1</u>	<u> </u>	buildings
<u> </u>	<u> </u>	sites
<u> </u>	<u> </u>	structures
<u> </u>	<u> </u>	objects
<u>1</u>	<u>0</u>	Total

Number of contributing resources previously listed in the National Register N/A

6. Function or Use

Historic Functions

(Enter categories from instructions.)

RELIGION: religious facility

Current Functions

(Enter categories from instructions.)

RECREATION AND CULTURE: museum

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

7. Description

Architectural Classification

(Enter categories from instructions.)

LATE VICTORIAN: Gothic

Materials: (enter categories from instructions.)

Principal exterior materials of the property: BRICK, STONE, CONCRETE

Narrative Description

(Describe the historic and current physical appearance and condition of the property. Describe contributing and noncontributing resources if applicable. Begin with a **summary paragraph** that briefly describes the general characteristics of the property, such as its location, type, style, method of construction, setting, size, and significant features. Indicate whether the property has historic integrity.)

Summary Paragraph

The previously listed Weber Stake Relief Society Building (NRIS # 88003438), located in Ogden, Weber County, was moved to a new location at 2104 Lincoln Avenue, a block west of the former location (2148 Grant Avenue). The building was reestablished at the new site and ready for use in December 2012. Also, the Miles Goodyear Cabin (NRIS #71000866), which was located adjacent to the building at the former site was also moved to the current site, still adjacent to the Relief Society Building. The former site was undergoing new construction that would have resulted in the demolition of both buildings. Below is a description of the new site and rehabilitation of the building that was part of the move.

Narrative Description

Setting

The new location is slightly larger than the parcel that the building occupied on Grant Avenue, providing a more protected open space—similar to its historic setting. The current landscape area is very similar to the original. It is flat with landscaping of lawn and various shrubs and deciduous trees. The site has some mature trees and has been landscaped appropriately. The primary façade continues to face west, as it did at the former site, and the distance from the street

Weber Stake Relief Society Hall

Weber Co., UT

Name of Property

County and State

to the building has been maintained exactly, as has the ground-level elevation. Since the building is no longer encumbered as it was by an encroaching parking structure at the former site, the entire building is now much more visible to the public, as it would have been historically.

Curved concrete and brick-paved walkways provide access (including ADA accessibility) to the various entrances. A below-grade stairwell provides access to the basement entryway on the north elevation. As it is an urban setting, there is a small asphalt surfaced parking lot behind the building. A decorative metal fence surrounds a portion of the property as well. There is a small, brick-paved plaza and walkway from the museum to the Miles Goodyear Cabin (NRIS #71000866), which was also moved to the site, and from the parking lot at the rear of the museum to Lincoln street at the front (west).

New Foundation

The building was placed on a new full basement of poured concrete, on top of which is a concrete block foundation. Stone from the original foundation was reused to face the new foundation, from the brick walls down to grade level, retaining the historical appearance. The new basement is divided up into a number of storage and exhibit spaces along with restrooms and mechanical rooms in order to leave the main floor open for exhibits.

Building Exterior

The exterior has undergone minor rehabilitation to return it to a more historic appearance. Minor brick repair was completed and mortar repointed with like soft mix to match color and softness of the historic mortar. The brick was then carefully cleaned with a light detergent—no harsh methods or power spraying—and still retains its weathered patina.

The original exterior doors were sanded, filled, painted and re-hung with good weather stripping. All historic windows, including basement windows were retained and restored with sanding and painting. On the main floor interior, and entire exterior, the moldings and woodwork were all retained, filled and repainted. The roof has received new asphalt shingles in the past five years to replace the older asphalt roofing.

Historic architectural detail had been lost more recently beneath a monochrome paint job in the faux half-timbered gables. In historic photographs it is apparent the decorative half-timbering in the south- and east-facing gables was a darker color that contrasted with the lighter color plaster beneath. This paint scheme in both rear gables has been restored, and the timbers now contrast with the stucco walls.

Building Interior

The existing attic trusses were repaired with like sister members where they had failed over time. All other existing flooring, wood molding and windows were retained and restored.

New furnaces and air conditioning were installed in the basement with the existing chimney being repaired and used for venting the new HVAC system. A handicap lift and walkout stair were added as required by code for the new basement. Around the new lift the stairway to the basement had to be reworked for safety reasons and to accommodate the lift but this space had

Weber Stake Relief Society Hall

Name of Property

Weber Co., UT

County and State

been altered many times over the history of the building. Handrails, newel posts and balusters were made to match the historic handrails.

Existing floor vents were used for the new mechanical and no changes were made on the main floor for this new system. Electrical was carefully updated without any damage to the historic fabric. The minor plumbing that existed was completely replaced and only exists in the new basement.

Although the building has been moved to a new site, the setting is very near the appearance of the original before more modern structures had altered the landscape. Through careful rehabilitation of the exterior and public interior spaces, and low-impact modern upgrades in the basement, the Weber Stake Relief Society Building retains its historical integrity and will be a better utilized building in the community.

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

8. Statement of Significance

Applicable National Register Criteria

(Mark "x" in one or more boxes for the criteria qualifying the property for National Register listing.)

- A. Property is associated with events that have made a significant contribution to the broad patterns of our history.
- B. Property is associated with the lives of persons significant in our past.
- C. Property embodies the distinctive characteristics of a type, period, or method of construction or represents the work of a master, or possesses high artistic values, or represents a significant and distinguishable entity whose components lack individual distinction.
- D. Property has yielded, or is likely to yield, information important in prehistory or history.

Criteria Considerations

(Mark "x" in all the boxes that apply.)

- A. Owned by a religious institution or used for religious purposes
- B. Removed from its original location
- C. A birthplace or grave
- D. A cemetery
- E. A reconstructed building, object, or structure
- F. A commemorative property
- G. Less than 50 years old or achieving significance within the past 50 years

Areas of Significance

(Enter categories from instructions.)

RELIGION
SOCIAL HISTORY

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

Period of Significance

1902-1926

Significant Dates

1902

Significant Person

(Complete only if Criterion B is marked above.)

N/A

Cultural Affiliation

N/A

Architect/Builder

Unknown

Statement of Significance Summary Paragraph (Provide a summary paragraph that includes level of significance, applicable criteria, justification for the period of significance, and any applicable criteria considerations.)

Narrative Statement of Significance (Provide at least **one** paragraph for each area of significance.)

9. Major Bibliographical References

Bibliography (Cite the books, articles, and other sources used in preparing this form.)

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

Previous documentation on file (NPS):

- preliminary determination of individual listing (36 CFR 67) has been requested
- previously listed in the National Register
- previously determined eligible by the National Register
- designated a National Historic Landmark
- recorded by Historic American Buildings Survey # _____
- recorded by Historic American Engineering Record # _____
- recorded by Historic American Landscape Survey # _____

Primary location of additional data:

- State Historic Preservation Office
- Other State agency
- Federal agency
- Local government
- University
- Other
- Name of repository: _____

Historic Resources Survey Number (if assigned): _____

10. Geographical Data

Acreeage of Property 0.525 acres

Use either the UTM system or latitude/longitude coordinates

Latitude/Longitude Coordinates

Datum if other than WGS84: _____

(enter coordinates to 6 decimal places)

1. Latitude: 41.228897° Longitude: -111.975487°

Or

UTM References

Datum (indicated on USGS map):

NAD 1927 or NAD 1983

1. Zone: Easting: Northing:

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

Verbal Boundary Description (Describe the boundaries of the property.)

BEGINNING AT THE NORTHWEST CORNER LOT 6, BLOCK 47, PLAT 'A', OGDEN CITY SURVEY, AND RUNNING THENCE SOUTH 89°03'41" EAST ALONG THE NORTH LINE OF SAID LOT 6 A DISTANCE OF 173.12 FEET TO A POINT ON A LINE THAT IS 0.50 FEET PERPENDICULARLY EAST OF A CONCRETE CURB LINE; THENCE SOUTH 01°06'37" WEST ALONG SAID LINE PERPENDICULAR TO AND PARALLEL WITH SAID CURB LINE 135.92 FEET TO A POINT ON A WROUGHT IRON FENCE LINE; THENCE WESTERLY ALONG SAID FENCE LINE THE FOLLOWING (3) COURSES: (1) NORTH 89°16'10" WEST 43.25 FEET, (2) NORTH 84°17'33" WEST 80.61 FEET, (3) NORTH 85°27'54" WEST 49.35 FEET TO A POINT ON THE WESTERLY LINE OF SAID LOT 6; THENCE NORTH 00°57'00" EAST ALONG SAID WESTERLY LINE 126.28 FEET TO THE POINT OF BEGINNING.

Boundary Justification (Explain why the boundaries were selected.)

The boundary is the current tax parcel for the property where the building was recently moved.

11. Form Prepared By

name/title: Rod Mortensen and Cory Jensen (Utah SHPO Staff)
organization: Utah Division of State History
street & number: 300 S. Rio Grande Street
city or town: Salt Lake City state: Utah zip code: 84101
e-mail: coryjensen@utah.gov
telephone: 801/245-7242
date: June 13, 2013

Additional Documentation

Submit the following items with the completed form:

- **Maps:** A USGS map or equivalent (7.5 or 15 minute series) indicating the property's location.

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

- **Sketch map** for historic districts and properties having large acreage or numerous resources. Key all photographs to this map.
- **Additional items:** (Check with the SHPO, TPO, or FPO for any additional items.)

Photographs

Submit clear and descriptive photographs. The size of each image must be 1600x1200 pixels (minimum), 3000x2000 preferred, at 300 ppi (pixels per inch) or larger. Key all photographs to the sketch map. Each photograph must be numbered and that number must correspond to the photograph number on the photo log. For simplicity, the name of the photographer, photo date, etc. may be listed once on the photograph log and doesn't need to be labeled on every photograph.

Photo Log

Name of Property: Weber Stake Relief Society Building

City or Vicinity: Ogden

County: Weber State: Utah

Photographer: Christopher Hansen and Rod Mortensen

Date Photographed: Winter 2012, March/April 2013

Description of Photograph(s) and number, include description of view indicating direction of camera:

- 1 of 8. South and west elevations of building, showing site. Camera facing northeast.
- 2 of 8. South and west elevations of building. Camera facing northeast.
- 3 of 8. North and west elevations of building. Camera facing southeast.
- 4 of 8. North and east elevations of building. Camera facing southwest.
- 5 of 8. South and east elevations of building. Camera facing northwest.
- 6 of 8. Building in transport to new site. Camera facing west.
- 7 of 8. Building interior, main floor. Camera facing southwest.
- 8 of 8. Building interior, basement. Camera facing southwest.

Weber Stake Relief Society Hall
Name of Property

Weber Co., UT
County and State

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listings. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C.460 et seq.).

Estimated Burden Statement: Public reporting burden for this form is estimated to average 100 hours per response including time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Office of Planning and Performance Management, U.S. Dept. of the Interior, 1849 C. Street, NW, Washington, DC.

United States Department of the Interior
National Park Service

National Register of Historic Places Continuation Sheet

..... Name of Property
..... County and State
..... Name of multiple listing (if applicable)

Section number Maps Page 13



Weber Stake Relief Society Building
2104 Lincoln Ave
Ogden, Weber County, Utah
 Latitude 41.228897° Longitude -111.975487°



United States Department of the Interior
National Park Service

National Register of Historic Places Continuation Sheet

..... Name of Property
..... County and State
..... Name of multiple listing (if applicable)

Section number Maps Page 14

PROPOSED SITE FOR THE WEBER COUNTY DAUGHTERS OF THE UTAH PIONEERS MUSEUM - OPTION C





Weber Stake Relief Society Building, Lat 41.228897° Long -111.975487°




Weber Stake Relief Society Building

2104 Lincoln Ave

Ogden, Weber County, Utah

Latitude 41.228897° Longitude -111.975487°



PROPOSED SITE FOR THE WEBER COUNTY DAUGHTERS OF THE UTAH PIONEERS MUSEUM - OPTION C



DAUGHTERS OF UTAH
PIONEERS MUSEUM



DAUGHTERS OF UTA
PIONEERS MUSEUM

S. J. HARRIS SOCIETY



PIONEER
MUSEUM











EXIT

LT 10