



Saguaro National Park News Release

For Immediate Release

February 16, 2010

Contact: Brian Bergsma at (520) 733-5140

Repair Work Slated for Picture Rocks Road Patching and Chip Seal to Occur Next Week

From Monday, February 22nd through Tuesday, February 23rd, contract crews will be patching and crack sealing portions of Picture Rocks Road within Saguaro National Park's West District. The work will occur between 9:00 am and 3:30 pm each day. No closures are anticipated, but motorists may experience brief delays.

The work is being done in advance of a chip seal project scheduled for late May or early June, 2010. Both projects are being coordinated by the Federal Highways Administration. For additional information please contact Brian Bergsma, acting Chief of Facility Management, at 733-5140.