



NPS Photo

Delaware and Hudson Railroad, Snow Flanger #36037.

Flanger, #36037. Shop-built, probably before 1910. Used for snow removal. Wood with a steel flange notched to fit over the rails. Pushed by a locomotive with a crew inside to raise and lower the flange, as needed, to avoid grade crossings and other obstructions. Received by Steamtown Foundation, 1985-1987.