

EXHIBIT D

ASSIGNED LAND AND REAL PROPERTY IMPROVEMENTS (CONCESSION FACILITIES)

Land Assigned


Land is assigned in accordance with the boundaries shown on the following maps.


Page D-2: Land Assignment—Folk Art Center


Page D-3: Folk Art Center Floor Plan—First Floor

Page D-4: Folk Art Center Floor Plan—Second Floor

Land Assignment—Folk Art Center



Folk Art Center Floor Plan—First Floor

Folk Art Center Floor Plan—Second Floor

Real Property Improvements Assigned

The following real property improvements are assigned to the concessioner for use in conducting its operations under this Contract:

Asset Code	Asset Description	Asset Type	Unit of Measure	Quantity	Date Built or Installed	Historic (Y or N)	Insurance Replacement Value
4856	Folk Art Center	4100	SF	34,017	1978	N	\$6,921,858
4896	Folk Art Center Maintained Landscape	3100	acres	18	1978	N	*
48715	Folk Art Center & Loops (Road)	1100	miles	0.41	1978	N	*
87307	Folk Art Center Parking	1300	SF	39,832	1978	N	*
226404	Folk Art Center Employee Parking	1300	SF	34,250	1978	N	*

* Please note: The lack of value for an asset in the Insurance Replacement Value column does not relieve the Concessioner of its obligation to insure the asset according to the terms of this Contract.

Approved, effective _____, 20__.

By: _____
Regional Director, Southeast Region